

				WOR		ctivity Date:		November 19, 2024				
			Process Name/Title:		APING ASSEMBLY PRO		dity Date:		n/a			
		7	Model code/Part number:	ES1 / 7N0165-7020	Customer: TRJ	Car Model: SUBARU-FOREST	ER Docu	ument No.:		WI-ENG-PDE-11	64A	
			Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revi	ision No.:	1	Page No.:	1 of 6	
PARTS:  1. All parts: Connector 7C83-5524-70 (Y); MRSW CP AVSSf 0.3 wires W-B/W L=765±3mm with inserted Black SV tube (Vinyl) ø5 L=38±3mm; Black Corrugated tube ø7 L=644±6mm; Black tape									1. Locking 2. Termina	Locking jig 3.Insertion jig     Terminal cover jig 4. Measuring jig		
N	Ο.	F	PROCESS NAME	Wo		TOOLS/PPE	(	QUALITY POIN	TERS			
( ),								: 017 for Wire ce				
				Revision Hi	istory			Prepared by	Reviewed by	Approved by	Noted by	
11/19/24		Change Initial iss	pre-launch to mass pro.			A.Hernandez C. Villanueva A. Arañes	n/a	Other Conduction	South House			
Eff. Date		milial ISS	uc.	Details of Change		A.Hernandez C. Villanueva A. Arañes  Revised Reviewed Approved	n/a Noted		C. Villanueva lovember 18, 2024	A. Arañes	n/a	







			WORK	Effectivity Date:	November 19, 2024						
		Process Name/Title:	Validity Date:	n/a							
		Model code/Part number:	ES1 / 7N0165-70200	ES1 / 7N0165-7020C Customer: TRJ Car Model: SUBARU-FORESTER		Document No.:	WI-ENG-PDE-1164A				
		Purpose:	PROTOTYPE	☐ PRE-LAUNCH		ASSPRO	Revision No.:	1	Page No.:	4 of 6	
PARTS:	1. Assy 2. Blac				JIG:	1. Measuring jig					
NO.	F	PROCESS NAME	WO	RK PROCEDURE/ II	TOOLS/PPE	QUALITY POINTERS					
6	P1	Taping 1 Black SV tube (Vinyl) to	1. Conduct measuremen jig by placing the assy padimension. (See illustration)	t on measuring	25±3mm	2. Hold the tube using left hand, get the Black tape using right hand then start taping process using both hands.  MEASURING TAPE  6 7 8 9 10 1 2 3 4 5 6 7			1. No flip-out tape 2. No peel-off tape 3. No loose tape 4. No missing tape 5. No wrong use of tape 6. No wrong dimension  Important reminders/Note/s: 1. Used WHITE TAPE to easy visualization of shifting lines, but in actual should be BLACK TAPE 2. Please use calibrated/verified measuring tape when getting the measurement. 3. First dimension will be conducted using measuring jig		
		wire near PCB	3. Attach tape then con winding while folding tube (Vinyl)	nduct 1 he SV	going to wires	ng must be within	TOLICO MARKET	Posi	tion the finger		


			WORK INS	Effectivity Date:	November 19, 2024					
		Process Name/Title:	TAPIN	Validity Date:	n/a					
		Model code/Part number:	ES1 / 7N0165-7020C	Customer: <b>T</b>	RJ Car Model:	SUBARU-FORESTER	Document No.:	WI-ENG-PDE-1164A		
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSP	RO	Revision No.:	1	Page No.:	5 of 6
PARTS:	1. Assy 2. Blac			JIG:	1.Measuring jig					
NO.	F	PROCESS NAME WORK PROCEDURE/ ILLUSTRATION					TOOLS/PPE	(	QUALITY POIN	TERS
7	P1	Taping 1 Black SV tube (Vinyl) to wire near PCB (Continuation)	5. Conduct 1 wind  25 ± 3mm  25 ± 3mm  25 ± 3mm	26 ± 3mm	6. Conduct 2x  7. Conduct 3x pre			1. Used 1 visualiza actual sh 2. Please measurin measure 3. First of using me 1. No flip-ou 2. No peel-ou 3. No loose 4. No missin 5. No wrong visualization of the short of t	limension will be deasuring jig  ut tape off tape tape	asy nes, but in <u>FAPE</u> erified ting the

	C	WORK INSTRUCTION							Effectivity Date:	November 19, 2024		
		Process Name/Title:	Validity Date:	n/a								
			Model code/Part number:	ES1 / 7N0165-7020C	Cus	tomer:	TRJ	Car Mode	SUBARU-FORESTER	Document No.:		WI-ENG-PDE-11
		Purpose:	PROTOTYPE	☐ PRE-	-LAUNCH		MAS	SPRO	Revision No.:	1	Page No.:	6 of 6
PARTS:	1 Δς	sy parts							JIG:	n/a		
	1.710	o, pare					oic.	11/4				

## **VISUAL INSPECTION/ QUALITY CHECKPOINTS**

## **TAPING - P1**

## 7N0165-7020C



- 1 No Wrong Insert
- No Terminal backing out
- 3 No Deformed terminal
- 4 No Missing tape (Black tape)
- **5** No Missing tape parts

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.