WORK INSTRUCTION Effectivity Date: August 20, 2024										24	
			Process Name/Title:		NG ASSEMBLY PROC	FSS	Validity Date:		August 20, 2024 n/a		
			Model code/Part number:	920B / 7R0117-7025	Customer: TRMX	Car Model: TOYOTA-TACOMA	Document No.:		WI-ENG-PDE-982C		
					<u> </u>				l I		
			Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	1 of 5	
PARTS:		Assy parts: Black tape					JIG:	n/a			
NO.		PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	(QUALITY POIN	TERS	
TABLE LAYOUT ASSY PART TAPE HOLDER BLACK TAPE		Safety Instruction Be sure to wear required personal protective equipment during operation (gloves, finger cots, etc.) Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker. Alert level		ssing parts/tools ess parts/tools							
				Revision History			Prepared by	Reviewed by	Approved by	Noted by	
8/20/24	1 0	Change Initial iss	purpose from Pre-launch to Mas	spro.			n/a hlmly	of of form		7-1-	
Eff. Date	Rev No	No Details of Change Revised Reviewed Approved						C.Villanueva / 19, 2024	A. NALGABORS	n/a	
2 410	IVGN. INO			Details of Criatige		Izevised Keviewed Applioved I	NOIGU JESI. DAIG. JUI)	1 13, 2024			




			Effectivity Date:	August 20, 20	August 20, 2024					
		Process Name/Title:	Validity Date:	n/a						
		Model code/Part number:	920B / 7R0117-7025	Document No.:	WI-ENG-PDE-982C					
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	2 of 5	
1. Assy parts										
	2. Black	tape					n/a			
NO.	F	ROCESS NAME	WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	(QUALITY POINTERS		
2	P3	Taping 3 COT to Black VM tube (Sunprene) near PCB	Start of taping	2. Hold the COT Black tape usin taping using bot	1. Measure from end of COT up to PCB 176±3mm then start the taping process using both hands. Tusing left hand, get the gright hand then start pre-	MEASURING TAPE 6 7 8 9 10 1 2 3 4 5 6 7 8 9 1	Imports 1. Plea measu measu Docum 1. Refe taping 1. No flip-c 2. No peel- 3. No loose 4. No miss 5. No wron	ant reminders anse use calibrated ring tape when grement. The sent reference/s: row WI-PRO-ASY procedure. The sent tape off tape at tape at tape are tape as the sent reminders and tape at tape at tape at tape are tape.	nd Note/s: d/verified vetting the	



			WORK INS	Effectivity Date:		August 20, 20	24			
		Process Name/Title:	Validity Date:	n/a						
		Model code/Part number:	920B / 7R0117-7025	Customer: TRMX		Document No.:		WI-ENG-PDE-98	32C	
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	3 of 5	
PARTS:	Assy parts Black tape				JIG:	n/a	- √a			
NO.	PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	(QUALITY POINTERS		
3	P3	Y-Taping	No gap in	Note: Do not exert excessive force during winding of tape to left side, 2 5. Wind the corrugated	1. Fix the corrugated tube . taping direction ape shifting 1/3 20±3mm Wind the tape 1/3 shifting until it each the other side of corrugated tibe (must be 20±3mm) Tape shifting 9mm below 20±3mm 20±3mm 20±3mm	n/a	Importa 1. Use Y visualiza actual sl 1. No flip-ou 2. No peel-ou 3. No loose 4. No missiu 5. No wrong	ant reminders/l ELLOW TAPE for tion of shifting li nould be <u>BLACK</u> at tape toff tape tape tg tape	Note/s: easy nes, but	





NBC (Philippines)

MASTER COPY

			Effectivity Date:	August 20, 2024		24			
		Process Name/Title:	Validity Date:		n/a				
	J	Model code/Part number:	920B / 7R0117-7025	Customer: TRMX	Car Model: TOYOTA-TACOMA	Document No.:		WI-ENG-PDE-98	82C
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	5 of 5
PARTS:	1. Ass	y parts	JIG:	n/a					
VISUAL INSPECTION/ QUALITY CHECKPOINTS									

P3 7R0117-7025



1 3 No MISSING TAPE

2 Correct Facing of Y-taping

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY