					WORK INSTRUCTION	N			Effectivity Date:		February 6, 20	24			
			Process Name/Title:		OFFLINE ASSE	MBLY PROC	ESS		Validity Date:		n/a				
			Model code/Part number:	930B /	7N0204-7020A Custon	mer: TRJ	Car Model: TO	YOTA-4 RUNNER	Document No.:		WI-ENG-PDE-8	328			
Ш			Purpose:	PROTOTYPE	PRE-LA	UNCH	MASSPRO		Revision No.:	0	Page No.:	1 of 8			
PARTS:		1. All p L=266:	arts: Connector 6188-0066 ±4mm (No slit); Connector 6	(GR); AVSSf Y-OR L= 6189-1161 (B)	364±2mm; Black corrugated t	ube ø7 L=45±3mr	m (No slit); Black	k corrugated tube ø5	JIG:	 Insertion Insertion Locking j 		r			
NC).	F	PROCESS NAME		WORK PROCEDU	JRE/ ILLUSTR/	ATION		TOOLS/PPE	(QUALITY POIN	TERS			
1		n/a	Table Lay-out		orrugated tube ø7 ±3mm (No slit)	E LAY-OUT F OR L=364±2mm AVSS Locking	Black c L=26 Connec	corrugated tube ø5 86±4mm (No slit) ector 6189-1161 (B)/connector tray	Safety Instruction Be sure to wear prescribed personal protective equipmen during operation (gloves, finger cots, etc. Housekeeping 1. Maintain and alway practice 5's. 2. Personal things or the workplace is prohibited. Keep it in your locker. Alert level For any trouble, infort the Assembly Assista Supervisor or Line Leader for immediate corrective action.	Docume 1. Refer to Strip leng 1. No mis 2. No excent	ent references: o WI-PRO-CNC-0 th tolerance. ssing parts/tools cess parts/tools	17 for Wire and			
					Revision History				Prepared by	Reviewed by	Approved by	Noted by			
02/06/24	0	Initial iss	iue				D.Castillo C. Vil	illanueva A. Arañes n)/a D. Castillo	C. Villanueva		2/0			
				Details of Cha	nge				D. Castillo		/ ALAIBINES	n/a			
0.0				2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	•	te Rev. No Details of Change Revised Revised Approved Noted Est. Date: February 06, 2024									



			WORK INSTRUCTION	Effectivity Date:	February 6, 2024				
		Process Name/Title:	OFFLINE ASSEMBLY PROCESS	Validity Date:		n/a			
		Model code/Part number:	930B / 7N0204-7020A Customer: TRJ Car Model: TOYOTA-4 RUNNER	Document No.:		WI-ENG-PDE-828			
		Purpose:	□ PROTOTYPE □ PRE-LAUNCH ■ MASSPRO	Revision No.:	0	Page No.: 2 of 8			
PARTS:	1. Coni	nector 6188-0066 (GR)		JIG:	Insertion jig with switch cover				
NO.	F	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS				
2	n/a	Connector setting to insertion jig 6188-0066 (GR)	Insertion jig with switch cover Insertion Inserti	n/a	I-mark not ali	NNECTOR ORIENTATION ILLUSTRATION 1 hole is open GOOD 2 holes are open			



				WORK INSTRUCTION		Effectivity Date:	February 6, 202	24				
		Process Name/Title:		OFFLINE ASSEM	3LY PROC	CESS		Validity Date:	n/a			
		Model code/Part number:	930B /	7N0204-7020A Customer	TRJ	Car Model:	TOYOTA-4 RUNNER	Document No.:		WI-ENG-PDE-8	28	
		Purpose:	PROTOTYPE	PRE-LAUNG	н	MASSP	PRO	Revision No.:	0	Page No.:	3 of 8	
PARTS:	1. AVS	Sf Y-OR L=364±2mm						JIG:	1. Insertior	n jig with switch cov	/er	
NO.	F	PROCESS NAME		WORK PROCEDUR	DURE/ ILLUSTRATION TOOLS/PPE				(QUALITY POIN	TERS	
3	n/a	Wire Insertion to connector 6188-0066 (GR)	1. Hold the insertice the Yellow wire the using right hand. 3. Get the Orange terminal slot 2 using the terminal slot 2 u	wire then insert to	2. Press the slot for Order	Press ion, push the the wires and	Ing right thumb. The II be opened.		2. No wron 3. One by 4. No defo 5. No wron Importa 1. Please 2. Make 3: inserted. Conduct insertion Do not e. Docume 1. Refer Push pro 2. Refer of	ant reminders/N e hold the wire necesure wires are pro- pull-Push-Pull-Push- ent references: to GL-PRO-ASY-0	ar terminal. operly ush after 029 for Pull- 17 for Wire	

				WORK INSTRUCTION			Effectivity Date:		February 6, 20	24
		Process Name/Title:		OFFLINE ASSEMBI	Y PROC	ESS	Validity Date:		n/a	
		Model code/Part number:	930B /	7N0204-7020A Customer:	TRJ	Car Model: TOYOTA-4 RUNNER	Document No.:		WI-ENG-PDE-8	28
		Purpose:	PROTOTYPE	☐ PRE-LAUNCH		MASSPRO	Revision No.:	0	Page No.:	4 of 8
PARTS:	1. Assy 2. Blac	parts c corrugated tube ø7 L=45:	±3mm (No slit)	3. Black cor	rugated tub	e ø5 L=266±4mm (No slit)	JIG:	n/a		
NO.	F	ROCESS NAME		WORK PROCEDURE/	ILLUSTR	ATION	TOOLS/PPE	(QUALITY POIN	TERS
4		Wire insertion to Black corrugated tube ø7 L=45±3mm (No slit)	L		F	1. Get the Black corrugated tube ø7 L=45±3mm (No slit) using right hand and insert Yellow wire and Orange wire by using left hand.	n/a		g use of parts rmed terminal	
5	n/a	Wire insertion to Black corrugated tube ø5 L=266±4mm (No slit)	L	Ø7 L= 45±3mm Ø	5 L= 266±4		n/a		ig use of parts rmed terminal	



			WORK INSTE		Effectivity Date: February 6, 2024					
		Process Name/Title:		ASSEMBLY PROC		Validity Date:		n/a		
		Model code/Part number:	930B / 7N0204-7020A	Customer: TRJ	Car Model: TOYOTA-4 RUNNER	Document No.:		WI-ENG-PDE-82	28	
		Purpose:	☐ PROTOTYPE [PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	5 of 8	
PARTS:	1. Conr	nector 6189-1161 (B)				JIG:	1. Insertior	n jig		
NO.	F	ROCESS NAME	WORK PR	OCEDURE/ ILLUSTR	ATION	TOOLS/PPE	(QUALITY POINT	ΓERS	
6	n/a	Connector setting to insertion jig 6189-1161 (B)	INSERTION JIG Visual Butto Guide Press 1. Press the lock using left thumb.	Press 2. Get the connector 618 insert to insertion jig. Re	CONNECTOR ORIENTATION Release 89-1161 (B) using right hand and elease the lock after insertion.		I-mark alig	GOOD is not	le is open le is open odel nnector	



				WORK INSTRUCTIO	N		Effectivity Date:	1	February 6, 20)24
		Process Name/Title:		OFFLINE ASSE		CESS	Validity Date:		n/a	
		Model code/Part number:	930B /	7N0204-7020A Custon		Car Model: TOYOTA-4 RUNNE	R Document No.:		WI-ENG-PDE-8	328
		Purpose:	PROTOTYPE	l l	UNCH	MASSPRO	Revision No.:	0	Page No.:	6 of 8
PARTS:	1. Assy	parts					JIG:	1. Insertion jig		
NO.	F	PROCESS NAME		WORK PROCEDU	JRE/ ILLUSTR/	ATION	TOOLS/PPE	(QUALITY POINTERS	
7	n/a	Connector setting to insertion jig 6189-1161 (B)	Yellow wire then in right hand.	1 Yellow wire on jig using left hand. Get the nsert to terminal slot 1 using 2 Orange wire R wire then insert to terminal and.	2. Press th slot for Ora 4. After insertior and then hold then hold then hold then hold then hold the hold the hold the hold then hold the hold th	Press R In, push the lock using left thumb the wires and gently pull out the jig using right hand.	n/a	4. No defo 5. No wron Importa 1. Please 2. Make s inserted. Conduct insertion Do not ex Docume 1. Refer t Push pro 2. Refer t	ng insertion one insertion rmed terminal ng wire facing ant reminders/N e hold the wire ne sure wires are pr Pull-Push-Pull-P oxert extra force. ent references: to GL-PRO-ASY-(ear terminal. roperly Push after : : : : : : : : : : : : : : : : : : :

				WORK INSTRUCTI		Effectivity Date:	24						
		Process Name/Title:		OFFLINE ASS	EMBLY PRO	CESS		Validity Date:		n/a			
		Model code/Part number:	930B /		omer: TRJ		OYOTA-4 RUNNER	Document No.:		WI-ENG-PDE-8	28		
		Purpose:	PROTOTYPE	☐ PRE-	LAUNCH	MASSPRO)	Revision No.:	0	Page No.:	7 of 8		
PARTS:									1. Locking	WI-ENG-PDE-828 0 Page No.: 7 of 8 Cocking jig QUALITY POINTERS Page 10 of			
NO.	F	ROCESS NAME		WORK PROCED	URE/ ILLUSTF	₹ATION		TOOLS/PPE	(QUALITY POIN	TERS		
8	n/a	Connector lock		NG	lock appears NG Half Lock Condition	press 2x. Check	D	LOCKING JIG	1. Use the connector. 2. No unlo	JAL LOCKING MA ED CONNECTOR provided jig tool to	o lock the		

			WORK INSTRUCTION			Effectivity Date:		February 6, 20	24		
MAA	Process Name/Title:		OFFLINE ASSEMBL	Y PROCES	SS	Validity Date:		n/a			
	Model code/Part number:	930B /	7N0204-7020A Customer:	1	ar Model: TOYOTA-4 RUNNER	Document No.:		WI-ENG-PDE-8			
	Purpose:	PROTOTYP			MASSPRO	Revision No.:	0	Page No.:	8 of 8		
							I I	<u> </u>			
PARTS: n/a						JIG:	n/a				
			QUALI	TY CHECKP	POINTS						
OFFL	INE INSE	RTION			7N0204-7	7020A	·				
					7110201	U					
	5	1 2		5				GO(
1 1	1 No Wrong insert 3 No Terminal Backing 5 No Missing COT Out										
(/)	lo Unlock/ Connector	Half Lo	ck 4 No D	eform	n terminal (6 Check	the	Alignm	ent		