

			WORK INSTRUCTION						Effectivity Date: March 15, 2025			25
			Process Name/Title:	OFFLINE ASSEMBLY PROCESS					Validity Date: n/a			
			Model code/Part number:	311D/ 7L0156-7022	Customer: TRQSS	Car Model:	TOYO	TA-RAV 4	Document No.:		WI-ENG-PDE-1	197
			Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPI	RO		Revision No.:	1	Page No.:	1 of 6
PARTS: 1. Connector 6098-3802 (W) 2. AVSSf 0.3 B wires L=167±2mm									JIG: 1. Insertion jig 2. Locking jig			
N	Ο.	PROCESS NAME WORK PROCEDURE/ ILLUSTRATION							TOOLS/PPE		QUALITY POIN	ITERS
TABLE LAY-OUT Table Lay-out Table Lay-out Insertion jig						or 6098- (W) AVSSF 0.3 L=167±2m	ım		Safety Instruct Be sure to wea required person protective equipm during operatio (gloves, finger cots, finder	ion r al ient n etc.) Docui 1. Refe Strip Le g vays 1. No mi 2. No ex t in form stant ne iate	Document reference/s: 1. Refer to WI-PRO-CNC-017 for Wire a Strip Length Tolerance 1. No missing parts/tools 2. No excess parts/tools	
				Revision History					Prepared by	Checked by	Reviewed by	Approved by
									. 1050.00 by	C.i.co.i.cd by	sy	
03/15/25		Change Purpose from Pre-launch to Masspro. Initial issue.							rañes M. Ariola	Sin	C. Villanueva	
Eff. Date				Details of Change		M. Ariola Revised	Checked		proved Est. Date:	J. Loverte 'February 12, 202		✓ A. Watables






		WORK INSTRUCTION						Effectivity Date: March 15, 2025			
		Process Name/Title: OFFLINE ASSEMBLY PROCESS					Validity Date:	n/a			
		Model code/Part number:	311D/ 7L0156-7022	Customer:	TRQSS	Car Model:	TOYOTA-RAV 4	Document No.:		WI-ENG-PDE-1	197
		Purpose:	PROTOTYPE	PRE-LAUNCH		MASSPI	30	Revision No.:	1	Page No.:	3 of 6
PARTS:	1. AVS	Sf 0.3 B wires L=167±2mm	[2pcs]				JIG:	1. Insertion Jig			
NO.	F	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION				TOOLS/PPE	QUALITY POINTERS			
3	Offline	Wire Insertion to Connector 6098-3802 (W)	1. Get the 1st B wire then insert to conneusing right hand.	3. After inse	2. Get the 2 using right I	hand.	en insert to connector on using left thumb then connector from jig	n/a	1. Refer to Strip Leng Importar 1. Make su Conduct P Do not exe 1. No loose 2. No wrong 3. One by 0 4. No defor		ote/s: erly inserted.

			Effectivity Date:	March 15, 2025						
		Process Name/Title: OFFLINE ASSEMBLY PROCESS					Validity Date:	n/a		
		Model code/Part number: 311D/ 7L0156-7022 Customer: TRQSS Car Model: TOYOTA-RA				TOYOTA-RAV 4	Document No.:	WI-ENG-PDE-1197		
		Purpose:	PROTOTYPE [PRE-LAUNCH	MASSPE	RO	Revision No.:	1	Page No.:	4 of 6
PARTS: 1. As		sy parts				JIG:	1. Locking jig			
NO.	F	OCESS NAME WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	QUALITY POINTERS				
4	Offline	Connector lock	1. Load the connector into the jig hol both side of the connector, tip first. Right thumb-Lower Left thumb-middle 3. Press the lower parts of connector wright hand while left hand holding the middle Left thumb-middle 5. Lift then press the connector in the midusing left and right hand.	using niddle. 6. En slide seque	2. Press the lower part insert into the locking ji Right thumb 4. Press the upper part of hand while left hand hold the touching the connector lowerce illustrated.	b-upper-middle of connector using right ding the middle.	LOCKING JIG	2. Use prodamaged I Importante Information	rtant reminder. IUAL LOCKING M GED LOCK provided jig tool p damaged lock. Imment reference er to GL-PRO-ASS tion of Coupler loc re pressing After	rs/note/s: MAY CAUSED per model to e/s: S-017 for the








OFFLINE INSERTION

7L0156-7022



- 1 No Unlocked/Half-locked connector
- **2** No Wrong Insert
- **3 No Terminal Backing Out**
- **4** No Deformed Terminal

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.