				WORK INS	TRUCTION	Effectivity Date:	May 18	May 18, 2021			
		Process Name/Title:		TAPING	ASSEMBLY PR	OCESS	Validity Date:	n/a			
		Product Name/Code:	291B /	7L0036-7020	Customer:	TRQSS	Document No.:	WI-ENG-I	WI-ENG-PDE-198A		
		Purpose:	☐ PROTOT	YPE	PRE-LAUNCH	MASSPRO	Revision No.:	2 Page No	.: 1 of 4		
							ı				
PARTS:		nector 6188-0294 (GR) Sf 0.3 B/W-GR wires L=549	9±3mm			JIG:	1. Insertion jig with switch	h cover			
NO.	Р	ROCESS NAME		TOOLS/PPE	QUALITY	QUALITY POINTERS					
1		Connector setting to P1 insertion jig 6188-0294 (GR)	B/W wire	Switch GR w	cover	Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves finger cots, etc.)	Connector Illustr				
	P1		Lock I-MARK Button	Vist reference Guide			Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.	I-mark is not			
			Press 1. Press the lock of insertion jig using left thumb.	hand and releas	nector 6188-0294 (GR) into jig using ri	ght Alert level	align	1 hole is open			
			L	Guide	Hole	3. Check the holes/terminal slot for B/W wires.		Use the provided jig per model No wrong orientation of connector No wrong use of connector No damaged connector			
			Prepared by	Reviewed by Approved	by Noted by						
05/18/21 2 11/17/20 1		of validity date. Apply some in process owner from Production		B) to Engineering (WI-ENG-PD	E-198A). Apply some	M. Catapang C. Villanueva A. Shima	amura A. Arañes	triff (0-1			
07/10/17 0	improvements/pictures. Removal of marker on taping jig.								ura A. Arañes		
Eff. Date Rev. No		siy established as Production w	,	of Change		Revised Checked Appro	,	C. Villanueva A. Shimam v 10, 2017	ura		
			- /	<u> </u>			, , , , , , , , , , , , , , , , , , , ,				

		WORK INSTRUCTION							Effectivity Date:		May 18, 2021			
		Process Name/Title: TAPING ASSEMBLY PROCESS Va						Validity Date:		n/a				
		Product Name/Code:	291B /	7L0036	-7020	Customer:	TRQSS		Document No.:			WI-ENG-PDF	E-198A	
		Purpose:	PROTO	TYPE		PRE-LAUNCH	MASSPR	0	Revision No.:		2	Page No.:	2 of 4	
												<u> </u>		
PARTS: n/a										JIG			tch cover	
NO.	PI	ROCESS NAME		WORI	K PROCEI	DURE/ ILLUS	TRATION		TOOLS/	PPE	QI	n/a WI-ENG-PDE-198A		
2	P1	Wire insertion to connector 6188-0294 (GR)	L 3. Get the GR	1) B/W wire R V wire then insert to using right hand. 2) GR wire R wire then insert to using right hand.	to	butt	fter insertion of B/W wire, con using right thumb. The se will be opened. 4. After insertion lock using left the then hold the wingently pull out the from jig using right.	, push the umb and res and le connector	n/a		2. No wr 3. One b 4. No de 5. No wr Note: inserte Conductinsertic	ong insertion by one insertion formed termin rong wire facing Make sure wire d. ct Pull-Push-Pul on.	al g es are properly I <u>l-Push</u> after	
3		Connector Lock	1. Put the connec jig using right han Check the connec properly locked.	d then press 2x.	Before Pressing	After Pressing	Coupler Cross Sect NG Double lock Double lock Unlock Condition Half Lock Condition	GOOD Double lock Full Lock Condition	LOCKING	i JIG	1. Use the	he provided jig	per model	

		WORK INSTRUCTION Effe							Effectivity Date:			May 18, 2021			
NB		Process Name/Title: TAPING ASSEMBLY PROCESS Validity Date:								ite: n/a			1		
		Product Name/Code:	291B / 7L0036-7020 Customer: TRQSS				Docu	Document No.:			WI-ENG-PDE-198A				
		Purpose:	□ F	PROTOTYPE		PRE-LAUNCH	MASSPRO	Revis	sion No.:		2	Page No.:	3 of 4		
PARTS:	1. Assy parts 2. Black corrugated tube (no slit) Ø7 L=50±3mm 3. Black vinyl tube Ø10 L=435±3mm									JIG	1. Termir	nal cover jig			
NO.	PF	ROCESS NAME			WORK PROC	EDURE/ ILLUS	TRATION		TOOLS/	PPE	QL	JALITY P	OINTERS		
4	P1	Wire insertion to Black corugated tube (no slit) Ø7 L=50±3mm using right hand and then insert the B/W-GR wires using left hand. 1. Get the terminal cover jig using right hand and then insert the B/W-GR wires using left using right hand and then insert the B/W-GR wires using left hand. TERMINAL CO 3. After insertion, remove the terminal cover jig using right hand.						RMINAL CO		1. No wrong use of parts 2. No deformed terminal					
5		Wire insertion to Black vinyl tube Ø10 L=435±3mm			→		tube Ø10 L=435±3mm using right insert the B/W-GR wires using left					1. No wrong use of parts			

			WORK INSTRUCTION							May 18, 2021		
		Process Name/Title: TAPING ASSEMBLY PROCESS								n/a		
		Product Name/Code:	291B /	7L0036-7020	Customer:	TRQSS	Do	ocument No.:			WI-ENG-PDE-1	198A
		Purpose:	PROTOTY	PE	PRE-LAUNCH	PRE-LAUNCH MASSPRO		Revision No.:		2	Page No.:	4 of 4
		1					<u> </u>					
PARTS:	1. Assy 2. Black								JIG	n/a		
NO.	Р	ROCESS NAME	WORK PROCEDURE/ ILLUSTRATION					TOOLS/F	PPE	QI	UALITY POIN	NTERS
6	P1	Taping 1 Black vinyl tube to wire near terminal	Start	1 2 3 4 of taping R 34±3mm 34±3mm	2. Hold the v start taping v Refer to Wi-procedure.	1. Measure from end of the vir up to terminal pointed tip 54±3 vinyl tube using left hand then using right hand . PRO-ASY-001 for taping 3. After taping, check the measur wire alignment and taping conditions.	ement,	MEASURING 7 8 9 1 2 3 4	5 6 7 8 9	1. No loo 2. No flip 3. No pe 4. No wr 5. No wr	e use calibrated, uring tape whereasurement. ose tape pout tape eel-off tape rong use of tape rong dimension Wire alignment to	n getting