
NA			WORK INSTRUCTION							Effe	Effectivity Date:			May 10, 2024		
			Process Name/Title: OFFLINE ASSEMBLY PROCESS							Validity Date: n/a						
	- 1		Model code/Part number:	TM3 /	7L0114-7021A	Customer:	TRQSS	Car Model:	SUBAR	U-ASCE	NT Doc	ument No.:			WI-ENG-PDE-7	709
			Purpose:	PROTOTYP	E	PRE-LAUNCH		MASSE	PRO		Rev	sion No.:	2		Page No.:	1 of 5
PARTS:	S: 1. All parts: Connector 7283-1030 (W); Jointed wire B-B 7L0114-2001A; Black corrugated tube Ø7, L=2 NO. PROCESS NAME WORK PROCEDURE/ ILLUSTE							, ,				JIG:		Insertion jig QUALITY POINTERS		
110.		-								.0020///2		QOXETT FORTERS				
1		Offline	Connector 7283-1030 (W)/ Connector Tray Tayble Lay-out Jointed wire (7L0114-2001A) Insertion jig					Ø7, L:	Black Corrugated tube Ø7, L=245±3mm (no slit) Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.) Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker. Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.				on 2. No al a	1. No missing parts/tools 2. No excess parts/tools CONNECTOR ILLUSTRATION GOOD NG 7283-1030 (W) 7283-1138 (W)		
Revision History						1 1		I I		Prepared by	Reviewed I	у	Approved by	Noted by		
05/10/24		visual inspection.							C.Villanueva	A. Arañes	n/a					
09/27/23	27/23 1 Change pre-launch to mass pro. Inclusion of table lay-out.					A.Hernande z	J.Loterte	C.Villanueva	A. Arañes	Jestus	1/4	_	CHARLES			
07/25/23								D.Castillo	J.Loterte		A. Arañes	D. Castillo	C. Villanu	eva .	A. Arades	n/a
Eff. Date Rev. No Details of Change Revised Reviewed Approved Noted Est. Date: July 25, 2023																





	<u></u>		WORK INSTRU OFFLINE A	Effectivity Date: May 10, 2024					
		Process Name/Title:	Validity Date:	n/a					
		Model code/Part number:	TM3 / 7L0114-7021A	Customer: TRQSS	Car Model: SUBARU-ASCENT	Document No.:		WI-ENG-PDE-7	09
		Purpose:	☐ PROTOTYPE ☐ I	PRE-LAUNCH	MASSPRO	Revision No.:	2	Page No.:	3 of 5
PARTS:		ed wire B-B 7L0114-2001 k corrugated tube Ø7 L=24		JIG:	1. Insertion jig				
NO.	F	ROCESS NAME	WORK PROC	TOOLS/PPE	QUALITY POINTERS				
3	<u>/</u>	Wire insertion to Corrugated tube Ø7, L=245±3mm (no slit)		No wrong usage of parts No deformed terminal					
4	Offline	Wire insertion to Connector 7283-1030 (W)	Wind R Black 1. Get Jointed wire then insert to terminal slot 1 using right hand.		Press In the lock using left thumb then hold ull out the connector from jig using		4. No defoi 5. No wron Impor 1. Pleas termina 2. Make inserted Push af Do not e		ear roperly rush-Pull- es:

