					WORK INST			Effectivity Date:		January 26, 2	024		
			Process Name/Title:		TAPING	ASSEMBLY PROC	ESS	Validity Date:		n/a			
			Model code/Part number:	700B /	7N0037-7020B	Customer: TRJ	Car Model: TOYOTA-LAND CRUISER	Document No.:		WI-ENG-PDE-7	58B		
			Purpose:	PROTOTYPE	[PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	1 of 7		
PARTS:		1. Assy	parts					JIG:	1. Insertion 2. Locking	Insertion Jig Locking jig			
N	0.	PROCESS NAME /1 WORK PROCEDURE/ ILLUSTRATION						TOOLS/PPE		QUALITY POINTERS			
1		P2	Table Lay-out	Mar Assembly	Insertion Jig C	Locking Jig	Assy Part Orange Black tape with Tape Holder	Safety Instruction Be sure to wear prescribed personal protective equipmed during operation (gloves, finger cotsetc.) Housekeeping 1. Maintain and alway practice 5's. 2. Personal things of the workplace is prohibited. Keep it your locker. Alert level For any trouble, infort the Assembly Assist Supervisor or Lind Leader for immedia corrective action.	al int	Document referer to WI-PRO-CNC-to D Length Toleran sing parts/tools ess parts/tools	017 for Wire		
					Revision History			Prepared by	Reviewed by	Approved by	Noted by		
01/26/24	0		purpose from pre-launch to mass leckpoints ue.	oro. Improve Work proced	ure/illustration on pages 1 to	7. Additional table lay-out and		n/a Internal Arañes M. Apola	Jour Jour	A. Aranes	n/a		
Eff. Date	Rev. No			Details of C	hange			oted Est. Date:	December 13, 2023				
					·								




					WORK INST	RUCTION			Effectivity Date:		January 26, 202	4
		Process Name/Title:			TAPING	ASSEMBLY P	PROC		Validity Date:		n/a	
		Model code/Part number:	700B	7	7N0037-7020B	Customer: TR		Car Model: TOYOTA-LAND CRUISER	Document No.:		WI-ENG-PDE-758	В
		Purpose:	□PR	ROTOTYPE		PRE-LAUNCH		MASSPRO	Revision No.:	1	Page No.:	2 of 7
PARTS:	1. Assy 2. AVSS	Parts of 0.3 V L=768±3mm				3. AVSSf 0.3 G L= 4. AVSSf 0.3 B L=			JIG:	n/a		
NO.	F	ROCESS NAME		-	1\ WORK PR	OCEDURE/ ILLU	JSTR.	ATION	TOOLS/PPE	C	QUALITY POINT	ERS
2	P2	Wire Insertion to assy part			Ø5 L=165±3mm Ø5 L=186±3r		2. H	old the corrugated tube (no slit) Ø5 65±3mm using left hand then insert assy part using right hand. Hold the SV tube (Vinyl) Ø5 186±3mm using left hand then ert the assy part using right hands.	N/A	1. Referand Stri 1. No wrong 2. No defor	Document referent to WI-PRO-CNC-C p Length Tolerand g use of parts med terminal g use of insertion	017 for Wire



				WORK INS	TRUCTION		Effectivity Date:		January 26, 20)24
		Process Name/Title:			G ASSEMBLY P	ROCESS	Validity Date:		n/a	
		Model code/Part number:	700B /	7N0037-7020B					WI-ENG-PDE-7	58B
		Purpose:	PROTOTY	PE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	3 of 7
PARTS:	1. Assy 2. Conr	Parts ector 6098-3802 (W)					JIG:	1. Insertion	jig	
NO.	F	PROCESS NAME		<u>∕</u> 1\ WORK F	ROCEDURE/ ILLU	STRATION	TOOLS/PPE	(QUALITY POIN	TERS
3	P2		Visual eference 1. Press the lock using left thumb.	Button Guide Press of insertion jig	Lock INSER ORIE 2. Insert the connuhand and release	CONNECTOR ORIENTATION STION JIG NTATION Release ector 6098-3802 (W) into jig using right	N/A	1. No wron 2. No defo	g use of parts rmed terminal g use of insertion	

			WORK IN:	STRUCTION		Effectivity Date:		January 26, 202	24	
		Process Name/Title:	TAPI	NG ASSEMBLY PRO	CESS	Validity Date:	n/a			
		Model code/Part number:	700B / 7N0037-7020	B Customer: TRJ	Car Model: TOYOTA-LAND CRUISER	Document No.:		WI-ENG-PDE-75	8B	
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	4 of 7	
PARTS: 1. Assy parts JIG: 1. Insertion jig										
NO.	F	PROCESS NAME	1 WORK	PROCEDURE/ ILLUSTR	RATION	TOOLS/PPE	(QUALITY POINT	ΓERS	
NO. 4	P2	Wire Insertion to Connector 6098-3802 (W)	CONNECTOR ORIENTATION 1. Hold the insertion jig using left hand. Get the Green wire and insert to connector using right hand.	VISUAL REFERENCE 2. Push the guide using le	WIRE FACING		QUALITY POINTERS 1. No wrong orientation of connector 2. No wrong use of connector 3. No damaged connector 4. No wrong insertion of wires 5. No loose insertion 6. One by one insertion 7. No deformed terminal 8. No wrong wire facingthe Important reminders/Note/s: 1. Make sure wires are properly inserted. Conduct Pull-Push-Pull-Push after insertion. Do not exert extra force. 2. Please hold the wire near terminal Document references: 1. Refer to WI-PRO-CNC-017 for Wire and Strip length tolerance.			
			3. After insertion, hold the wires and gently pull out the connector from jig using right hand.	5. Get the Viusing right ha	3 Violet R solet wire and insert to connector and.					

				WORK INSTE	Effectivity Date:	January 26, 2024				
		Process Name/Title:		TAPING	ASSEMBLY PRO	CESS	Validity Date:		n/a	
		Model code/Part number:	700B /	7N0037-7020B	Customer: TRJ	Car Model: TOYOTA-LAND CRUISER	Document No.:		WI-ENG-PDE-75	8B
		Purpose:	PROTOTY	PE [PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	5 of 7
PARTS: 1. Assy parts								1. Locking jig		
NO.	F	ROCESS NAME		<u>∕1</u> \ WORK PR	OCEDURE/ ILLUST	RATION	TOOLS/PPE	QUALITY POINTERS		
5	P2	Connector lock	1. Load the conside of the conn Right: Left tl 3. Press the lower	thumb-Lower humb-middle er parts of connector usin left hand holding the middle ob-middle the connector in	de L. Press the hand while	s the lower part of connector to fully to the locking jig. Right thumb-upper Left thumb-middle The upper part of connector using right left hand holding the middle. It is in locked condition by slide touching on the sequence illustrated.	LOCKING JIG	2. No unlocal Importation 1. MANU DAMAGE 2. Use pravoid da Docum 1. Refer a verification Before	DOD N	onnector ote/s: AY CAUSE LOCK er model to 017 for the



	_				WORK INSTI	RUCTION			Effectivity Date:		January 26, 20	24	
	A	Process Name/Title:				ASSEMBL	Y PROC		Validity Date:		n/a		
		Model code/Part number:	700B	/ 7N	N0037-7020B	Customer:	TRJ	Car Model: TOYOTA-LAND CRUISER	Document No.:		WI-ENG-PDE-75	58B	
		Purpose:	□PRO	ГОТҮРЕ		PRE-LAUNCH		MASSPRO	Revision No.:	1	Page No.:	7 of 7	
PARTS:	n/a					∕1\ QUALI	ITV CHEC	KDOINTS	JIG:	n/a			
	/1\ QUALITY CHECKPOINTS												
P2	P2 7N0037-7020B												
					3			2	GOOD		GOO		
											12.00		
		4							NO GOO	D	NO GO	OD	
	ock	nlock/Half- ed Connector nector)	(on (lo Wrong onnector)	insert (On 2	3 No Missing	tap ⁴ No De	form	ed termir	nal	
	. 001										th vita vita		