

			WORK IN	STRUCTION			Effectivity Date:			October 01, 20	024	
		Process Name/Title:	TAPIN	IG ASSEMBLY PROC			Validity Date:			n/a		
		Model code/Part number:	241B / 7L0049-7023A	Customer: TRQSS	Car Model: LE	XUS ES	Document No.:			WI-ENG-PDE-10	67B	
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO		Revision No.:		1	Page No.:	1 of 9	
PARTS:										Insertion jig Locking jig Locking jig		
NO.	F	PROCESS NAME	WORK	ATION		TOOLS	/PPE	QI	JALITY POIN	TERS		
1	P2	Table Lay-out	Measuring jig	Terminal cover jig Black tap hold	AVSSf 0.3 B L=692mm	ector O (W)/ Tray	Safety Instr Be sure to required pe protective ec during ope (gloves, fing etc.) Houseker 1. Maintain ar practice 2. Personal t the workpl prohibited. K your loc Alert le For any troub the Assembly Supervisor Leader for im corrective a	wear personal puipment pration per cots, arm delay size of the cots of the cot	Refer to nd Strip L	reference/s: WI-PRO-CNC-0 ength Tolerand		
			Revision History		г		Prepared	I by Reviewe	ed by	Approved by	Noted by	
10/01/24 1 09/24/24 0	Change Initial issu	from Pre-launch to Masspro.			A.Hernandez C. Villanuev A.Hernandez C. Villanuev		n/a O'RINA CWA	dez / Josephadez / Villar	Theya	A Arrange	n/a	
Eff. Date Rev. No	5		Details of Change		Revised Reviewed	Approved	Noted Est. Date:	September		/ I. Paggaroo	1,, a	
1						11		11				




			WORK INST	TRUCTION	Effectivity Date:		October 01, 20	24
		Process Name/Title:	TAPINO	Validity Date:	n/a			
		Model code/Part number:	241B / 7L0049-7023A	Customer: TRQSS Car Model: LEXUS ES	Document No.:		WI-ENG-PDE-10	067B
		Purpose:	□РКОТОТУРЕ	☐ PRE-LAUNCH ■ MASSPRO	Revision No.:	1	Page No.:	3 of 9
PARTS:		Sf 0.3 B L=692±3mm ugated tube ø5 L=49±3mm	(No slit)		JIG:	1. Insertior	n jig	
NO.	F	PROCESS NAME	WORK PI	ROCEDURE/ ILLUSTRATION	TOOLS/PPE	(QUALITY POIN	TERS
3		Wire insertion to Corrugated tube ø5 L= 49±3mm (no slit)	L	1. Get the corrugated tube ø5 L=49±3mm using left hand and get two (2) of Black wires then insert using right hand.	N/A	1. No wror	ng use of parts	
4	P2	Wire insertion to connector 6098-3810 (W)	1. Get the first Black wire and insert to terminal slot ① using right hand.	R 2. Get the 2nd Black wire and insert to terminal slot ② using right hand. 3. After insertion, push the lock using left thumb and then hold the wires and gently pull out the connector from jig using right hand.	N/A	2. No wron 3. One by 4. No defo 5. No wron Importa 1. Insert to right. 2. Please 3. Make inserted Conduct insertion Do not e	one insertion rmed terminal g wire facing ant reminders/ ion sequence sta e hold the wire no sure wires are p	ear terminal. roperly Push after

			WORK INS	Effectivity Date:	October 01, 2024					
		Process Name/Title:	TAPIN	IG ASSEM	BLY PROCESS		Validity Date:		n/a	
		Model code/Part number:	241B / 7L0049-7023A	Customer:	TRQSS Car Model:	LEXUS ES	Document No.:		WI-ENG-PDE-1	067B
		Purpose:	PROTOTYPE	PRE-LAUNC	CH MASSPRO		Revision No.:	1	Page No.:	4 of 9
PARTS:	1. Assy		WORK	JIG:	1. Locking Jig					
NO.	P	PROCESS NAME	TOOLS/PPE		QUALITY POI	NTERS				
5	P2	Connector Lock	2. Ensure that connector is in lock connector lock based on the sequence. Before President American Sequence (Content of the Sequence)	ted condition by ence illustrated.	Put the connector into locking jn press 2x using both hands. Innector lock to confirm if proper R 2 R After Pressing	Touch the	Locking jig	CONN G Fu 1. Use the	INTERPORT IN THE PROPERTY OF T	CONDITION NG UnLocked

			WORK INST	RUCTION			Effectivity Date:		October 01, 20	24		
		Process Name/Title:	TAPINO	ASSEMBLY PROC	ESS		Validity Date:	n/a				
		Model code/Part number:	241B / 7L0049-7023A	Customer: TRQSS	Car Model:	LEXUS ES	Document No.:		WI-ENG-PDE-10	067B		
		Purpose:	☐PROTOTYPE	PRE-LAUNCH	MASSPRO		Revision No.:	1	Page No.:	5 of 9		
PARTS:	1. Assy 2. Black						JIG:	n/a				
NO.	F	ROCESS NAME	WORK P	ROCEDURE/ ILLUSTRA	ATION		TOOLS/PPE	(QUALITY POIN	TERS		
6	P2	Taping 2 COT to wire near Connector	Start taping 1. Hold corrugated tube using left hand then get black tape and conduct pretaping using right hand. L 30±3mm 20±3mm	2. Measure the end edge of connector 3 Continue taping pro	of the corrugate 0±3mm using b	oth hands.	search 3322, 500 XVZ.	1. Plea measu measu Docum 1. Refe taping 1. No flip-c 2. No peel- 3. No loos 4. No miss 5. No wron	off tape tape	d/verified letting the		



			Effectivity Date:	October 01, 2024							
		Process Name/Title:	TAPIN	G ASSEME	SLY PROCESS	3		Validity Date:		n/a	
	H	Model code/Part number:	241B / 7L0049-7023A	Customer:	TRQSS Car N	Model:	LEXUS ES	Document No.:		WI-ENG-PDE-10	67B
		Purpose:	PROTOTYPE	PRE-LAUNC	Н	MASSPRO		Revision No.:	1	Page No.:	7 of 9
PARTS:	1. Black 2. Assy	parts						n/a			
NO.	P	ROCESS NAME	WORK F	ROCEDURE	/ ILLUSTRATIO	N		TOOLS/PPE	(QUALITY POIN	TERS
8		Wire insertion to VM tube (Sunprene) Ø5 L=106±3mm (Assy parts)	1. Hold the VM tube (Sunprene) Ø5 L= hand.	106±3mm using		R rt the 2 Bla	ack wires using right	N/A	ng insert rmed terminal		
9	P2	Spot taping	L	R	I. Hold the assy par ape and attach in the Sunprene) then star Make 2 windings the star with the st	ne middle c rt taping us en cut the	of COT and VM tube sing both hand. tape.	N/A	No loose tape No missing tape		
				R							





		WORK INSTRUCTION						Effectivity Date:	Oate: October 01, 2024		
		Process Name/Title:	TAPIN	TAPING ASSEMBLY PROCESS					n/a		
		Model code/Part number:	241B / 7L0049-7023A	Custom	er: TRQS	S Car Model:	LEXUS ES	Document No.: WI-ENG-PDE-10		067B	
		Purpose:	PROTOTYPE	☐PRE-LAU	NCH	MASSPRO		Revision No.:	1	Page No.:	9 of 9
PARTS: 1	1. Assy	y parts						JIG:	n/a		

VISUAL INSPECTION/ QUALITY CHECKPOINTS

TAPING - P2

7L0049-7023A



- 1 No Unlocked/Half-locked Connector
- 2 No Wrong Insert

3 No Missing tape(BLACK)

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.