				Wo	Effectivity Date:		April 26, 2023					
JB(7	Process Name/Title:		TAPING ASSEMBLY PRO	Validity Date:		n/a				
		_	Model Code/Product Number:	780B / 7R010	2-7023A Customer:	TRMX	Document No.:			WI-ENG-PDE-	553B	
		4	Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	:	3 Pa	ge No.:	1 of 5	
	1								•	•		
PARTS:		1. Assy _I 2. Black						JIG n/a				
NC).	F	PROCESS NAME		WORK PROCEDURE/ ILLUST	RATION	TOOLS/F	PPE	QUALITY POINTERS			
1		P2	Table Lay-out	Assy parts	TABLE LAY-OUT	Tape holder/Black tape	Safety Instru Be sure to w prescribed per protectiv equipment d operation (gl finger cots, of Housekee 1. Maintain always practiv 2. Personal thi the workpla prohibited. Ker your locker Alert lev For any trou inform the Ass Assistant Supe or Line Leade immediat corrective ac	vear rsonal e 2. No oves, etc.) ping and ce 5's. ings on ce is ep it in er. el uble, sembly ervisor er for te ettion.	p peel-off tape of flip out tape of loose tape of wrong use of the loose tape of wrong use of the loose tape of the loose tape when g	e of tape reminders/N are calibrated/veretting the meas	lote/s: ified measuring urement.	
				Revision	History		Prepare	ed by F	Reviewed by	Approved by	Noted by	
04/26/23			of quality checkpoints			J. Loterte C. Villanueva A.Arañes	n/a				_	
11/10/22		-		es and references on page no.1 to 4 du	ue to document improvement.	M.Ariola J. Loterte C. Villanueva	A.Arañes		1/ 1- 11	Alak	2	
07/22/22	-		rom Pre-launch to Masspro. sue. QR code 7V4010-0020 la	abal direction		M.Ariola J. Loterte C. Villanueva	\ A	AN A	Jour Journ			
07/20/22 Eff Date	U Rev No	milliai iss	aue. Un code / V4010-0020 la	Details of Change		M.Ariola J. Loterte C. Villanueva	A.Arañes J. Lot		. Villarrueva	A.ARARES	n/a	

	WORK INSTRUCTION Effectivity Date: April 26, 2023												
					WORK INSTRUC				Effectivity Date:				
		Process Name/Title:			TAPING AS	<u>SEMBI</u>	LY PROCES		Validity Date:			n/	
		Model Code/ Part Number:	780B	/	7R0102-7023A	Custor	mer:	TRMX	Document No.:			WI-ENG-P	DE-553B
		Purpose:	☐ PF	OTOTYPE		PRE-LA	UNCH	MASSPRO	Revision No.:		3	Page No.:	2 of 5
											1	<u> </u>	
PARTS:	1. Black 2. Assy				JIG: n/a								
NO.	-	PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION		TOOLS/	PPE	(QUALITY F	POINTERS			
2	P2	Taping 1 Vinyl tube to wire near connector	of Vinyl up to	inyl tube ι	using left hand. Measure the ector 25±3mm using right	hand.	Black tape using Refer to WI-PRC	I tube using left hand. Get the right hand and start taping. P-ASY-001 for taping procedure. theck the measurement and .	MEASURING 6 7 8 9 10 1 2 3 4	5 6 7 8 9	2. No fi 3. No lo 4. No v	peel-off tape ilip out tape oose tape wrong use of t wrtant reminder ase use calibra uring tape whe urement.	rs/Note/s: ted/verified

				WORK INSTRUC	TION		Effectivity Date:			April 26	6, 2023	
		Process Name/Title:			SEMBLY PR		Validity Date:	n/a				
		Model Code/ Part Number:	780B	/ 7R0102-7023A		TRMX	Document No.:			WI-ENG-F	PDE-553B	
		Purpose:	☐ PRO	ОТОТҮРЕ	PRE-LAUNCH	MASSPRO	Revision No.:		3	Page No.:	3 of 5	
		<u> </u>								<u> </u>		
PARTS:	1. Black 2. Assy							JIG:	n/a			
NO.	I	PROCESS NAME		WORK PROC	EDURE/ ILLU:	STRATION	TOOLS/	PPE	QUALITY POINTERS			
3	P2	Taping 2 COT to Sunprene	to the edge o	176±3mm 2 3 4 5 6 7 8 9 50 1 2 3 4 COT using left hand. Measure the earth of hotmelted wire 176±3mm using tape width 1 tape width 3. After taping, check the measure	176±3mm	•	MEASURING		2. No flip 3. No loo 4. No wr Import 1. Pleat measur	eel-off tape p out tape ose tape rong use of t tant reminde se use calibra ring tape whe rement.	ers/Note/s:	

			WORK IN	STRUCTION			Effectivity Date:			April 26, 2	2023
		Process Name/Title:	TAPI	NG ASSEMBLY	PROCESS		Validity Date:			n/a	
		Model Code/ Part Number:	780B / 7R0102-7	7023A Customer:	TRM	X	Document No.:			WI-ENG-PD)E-553B
		Purpose:	☐ PROTOTYPE	PRE-LAUNCH	- I M.	ASSPRO	Revision No.:		3	Page No.:	4 of 5
	1	1					<u> </u>	1	' '		
PARTS:	1. Black 2. Assy							JIG	n/a		
NO.	I	PROCESS NAME	WORK	PROCEDURE/ ILL	.USTRATION		TOOLS/	PPE	Ql	UALITY PO	DINTERS
4	P2	Y-taping	shifting the oth Vinyl to tape w tape shifting 1/3 below tape shifting 1/2 below 5. Wind the tape	tube and vi then wind t tube, width tube, width tube, width tape 1/3 g until it reach her side of ube (must be idth) tape shift tape shift	Note: Do not exert excessive force during pulling & winding of tape. sing at the middle of combining tube Make 1 wind prethe tape going to corrugate must be same with tape of the width tape width t	ined Corrugated -tape before shifting red tube and vinyl	6 7 8 9 10 1 2 3 4	5,6789	1. Used visualizabut act 2. Plead calibrat tape with measur	out tape e tape e interval between use of tape ant reminder a Yellow tage the tape tual should ase use then getting arement.	ars/Note/s: ape to easily e shifting. d be <u>Black.</u> d measuring

WORK INSTRUCTION Effectivity Date:									April 26, 2023				
	Process Name/Title: TAPING ASSEMBLY PROCESS							n/a					
	Model Code/ Part Number: 780B / 7R0102-		102-7023A	D23A Customer: TRMX		Document No.:		WI-ENG-PDE-553B					
	Purpose:	PROTOTYPE		PRE-LAUNCH	MASSPRO	Revision No.:		3	Page No.:	5 of 5			
								1					
PARTS: 1. Assy	parts		•				JIG	n/a					
3 QAULITY CHECKPOINTS													
P2	P2 7R0102-7023A												
12(1 2 3 No MISSING TAPE 4 Correct Facing of Y-taping												