			WORK INS	TRUCTION		Effectivity Date:		May 26, 2021	
		Process Name/Title:	TAPINO	3 ASSEMBLY	PROCESS	Validity Date:		n/a	
		Product Name/Code:	096D / 7L0118-7020	Customer:	TRQSS	Document No.:		WI-ENG-PDE-24	1B
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	1 of 5
		I						<u> </u>	
PARTS:	1. Assy 2. Blac					JIG:	n/a		
NO.	PROCESS NAME WORK PROCEDURE/ ILLUSTRATION				TOOLS/PPE	(QUALITY POIN	TERS	
			3 9 8 D 1 2 3 4	audanderila Alambanh	Measure from end of vinyl tube up to end of connector 25±3mm using both hands.	Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.) Housekeeping 1. Maintain and always			
1	P2	Taping 1 Black vinyl tube to wire near connector	2. Get the Black tape using right hand then start taping process using both hands. Note: Please refer to WI-PRO-ASY-001 for taping procedure.	taping	25±3mm R o~5mm r taping, check the measurement and condition.	practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker. Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action. MEASURING TAPE	6. No wron	off tape e tape ing tape g use of tape g dimension	
Revision History Prepared by Reviewed by Approved by Noted by								Noted by	
05/26/21 1	Change	type of purpose from Pre-lau	unch to massoro		M. Catapang C. Villanueva A. Shimamura A.	Arañes Afracutage		Clip.	CANA
02/25/21 0	on angle style of purpose from the data of								A. Arañes
Eff. Date Rev. No			Details of Change		Revised Checked Approved N	loted Est. Date: Februa	ary 25, 2021	_	

NBC (Philippines)

MASTER COPY

DCC Stamp

				WORK INSTRU	CTION		Effectivity Date:	May 26, 2021	
		Process Name/Title:		TAPING AS	SEMBLY PRO	CESS	Validity Date:	n/a	
		Product Name/Code:	096D /	7L0118-7020	Customer:	TRQSS	Document No.:	WI-ENG-PDE-241B	
		Purpose:	☐ PROTO	OTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1 Page No.: 2 of 5	
PARTS:	1. Assy parts 2. Black tape PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION		JIG TOOLS/PPE	QUALITY POINTERS			
2	P2	Taping 2 Black corrugated tube to Black vinyl tube near connector	1. Fix the cousing both	orrugated tube and vinyl tube hands.	2. Get the blusing both hand hand hand hand hand hand hand han	e refer to WI-PRO-ASY-001 for edure.	MEASURING TAP	Mater	

			1	WORK INSTRUC		Effectivity Date:		May 26,	2021	
		Process Name/Title:		TAPING ASS	SEMBLY PRO	CESS	Validity Date:		n/a	
		Product Name/Code:	096D / 7I	L0118-7020	Customer:	TRQSS	Document No.:		WI-ENG-PI	DE-241B
		Purpose:	PROTOTYPE		PRE-LAUNCH	MASSPRO	Revision No.:		1 Page No.:	3 of 5
	1								1	
PARTS: 1. Assy pa 2. Black to								JIG	n/a	
NO.	P	ROCESS NAME		WORK PROCEDURE/ ILLUSTRATION			TOOLS/I	PPE	QUALITY P	OINTERS
3	P1	Taping 3 Black Corrugated tube to Black sunprene tube near terminal	2. Fix the corrugated tubusing both hands.	1. Measure from er terminal pointed tip	nd of corrugated tube p 176±3mm using both Start o 3. Get the blusing both	Itaping Relack tape and start taping process nands. Re refer to WI-PRO-ASY-001 for edure.	The Milk of Section 2000	5 TAPE 5 6 7 8 9	Note: Please use calibrate measuring tape whe measurement. 1. No flip-out tape 2. No peel-off tape 3. No loose tape 4. No missing tape 5. No wrong use of ta 6. No wrong dimension	n getting the

			Effectivity Date:		May 26	, 2021				
		Process Name/Title:	TAPING ASSEMBLY PROCESS Validity Date						n/a	а
		Product Name/Code:	096D /	7L0118-7020	Customer:	TRQSS	Document No.:		WI-ENG-P	DE-241B
		Purpose:	PROTOTYPE		PRE-LAUNCH	MASSPRO	Revision No.:		1 Page No.:	4 of 5
		I								
PARTS:	Assy parts Black tape							JIG	n/a	
NO.	PROCESS NAME			WORK PROCE	DURE/ ILLUSTRA	TION	TOOLS/I	PPE	QUALITY P	POINTERS
4	P2	Y-Taping	L tape shifting	1. Fix the	Corrugate left side , (19mm)	ping at the middle of combined and tubes, then wind the tape to width must be same with tape the tape 1/3 shifting until it reach side of corrugated tube (must be h)	n/a		NOTE: USE YELLOW TA VISUALIZATION LINES, BUT ACTI BE BLACK TAPE. 1. No flip-out tape 2. No peel-off tape 3. No loose tape 4. No missing tape 5. No wrong use of t 6. No wrong dimensi	OF SHIFTING UAL SHOULD

			WORK INSTRUC	CTION	Effectivity Date:	May 26, 2021	
		Process Name/Title:	TAPING ASS	SEMBLY PROCESS	Validity Date:	n/a	
		Product Name/Code:	096D / 7L0118-7020	Customer: TRQSS	Document No.:	WI-ENG-PDE-241B	
		Purpose:	☐ PROTOTYPE ☐	PRE-LAUNCH MASSPRO	Revision No.:	1 Page No.: 5 of 5	
PARTS:	1. Assy 2. Black		WORK PROCE	DURE/ ILLUSTRATION	JIG TOOLS/PPE	n/a QUALITY POINTERS	
4	P2	Y-Taping (Continuation)	taping direction tape shifting 1/2 below Tape shifting 9mm below Tape width Tape width	4. Wind the tape backward 1/2 shifting 5. Wind the tape 1/2 shifting going to other side of corrugated tube then cut the tape. After taping, check the condition of tape.		NOTE: USE YELLOW TAPE FOR EASY VISUALIZATION OF SHIFTING LINES, BUT ACTUAL SHOULD BE BLACK TAPE. 1. No flip-out tape 2. No peel-off tape 3. No loose tape 4. No missing tape 5. No wrong use of tape 6. No wrong dimension Note: Please use calibrated/verified measuring tape when getting the measurement.	