					WORK INSTRUCTION	Effectivity Date:	June 27, 2024				
			Process Name/Title:		TAPING ASSEMBLY PROC	Validity Date:	n/a				
			Model code/Part number:	311D /	7N0195-7020Ea Customer: TRJ	Car Model: TOYOTA-RAV4	Document No.:	w	VI-ENG-PDE-919	В	
			Purpose:	PROTOTYP	E PRE-LAUNCH	MASSPRO	Revision No.:	0 F	Page No.:	1 of 5	
	A Associate										
PARTS:		1. Assy parts 2. Black Corrugated tube (with slit) &		05 L=164±3mm	3. Black tape	JIG:	n/a				
N	NO. PROCESS NAME				WORK PROCEDURE/ ILLUSTR	TOOLS/PPE	QUALITY POINTERS				
1		P2	Table lay-out	Tape h	Black Corrugated tube (with slit) Ø5 L=164±3mm Assy	parts COT Adaptor	Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.) Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker. Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.	1. No missing p 2. No excess pa			
					Revision History		Prepared by Re	eviewed by	Approved by	Noted by	
									0		
6/27/24	0	Initial issu	e.			M. Ariola C. Villanueva A. Arañes	n/a M. Ariola	/out/):/for-	A Arabes	n/a	
Eff. Date	Rev. No			Details of C	Change		17 /	27, 2024	/ 1. YOURSHIPS	11/0	
				25.5.110 01 0		, , , , , , , , , , , , , , , , , , , ,	- Journal Land				



	_		WORK INSTRUCTION Effectivity Date:						June 27, 2024			
		Process Name/Title:		Validity Date:	n/a							
		Model code/Part number:	311D /	TAPING ASSEMBLY F 7N0195-7020Ea Customer: TR		TOYOTA-RAV4	Document No.:		WI-ENG-PDE-9	19B		
	<u> </u>	Purpose:	□РКОТОТУР		MASSP		Revision No.:	0	Page No.:	2 of 5		
PARTS:	1. Assy	parts		JIG:	n/a							
NO.	F	PROCESS NAME		WORK PROCEDURE/ ILLU	JSTRATION		TOOLS/PPE QUALITY PO			TERS		
2	P2	Wire insertion to Black Corrugated tube (with slit) Ø5 L=164±3mm	L	1. Hold the COT Adwires using right has	2. Hold the COT using left hand corrugated tubes \$\tilde{\gamma}\$5 L=164±3mr insert to COT acadaptor and pus	T Adaptor with wires, get the Black pe (w/ slit) nusing right hand then daptor. Hold the COT same the hands. Make sure	COT Adaptor	1. Please measure measure 1. No peel 2. No flip of 3. No loose 4. No wron	-off tape out tape e tape ng use of tape ng dimension	verified		

	_		WOR	K INSTRUCTION	Effectivity Date: June 27, 2024					
		Process Name/Title:		APING ASSEMBLY PROC	Validity Date:		n/a WI-ENG-PDE-919B			
		Model code/Part number:		7020Ea Customer: TRJ	Car Model: TOYOTA-RAV4	Document No.:		WI-ENG-PDE-9	19B	
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	3 of 5	
PARTS:	Assy parts Black tape					JIG:	n/a			
NO.		PROCESS NAME	W	ORK PROCEDURE/ ILLUSTR	TOOLS/PPE	QUALITY POINTERS				
3	P2	Half-wrap Taping	1. Hold the corrugated tube (wslit) using left hand. Get the black tape using right hand. Conduct 2 windings of tape before shifting using both hands. 3. Check the taping condition.	2. Make 1/2 shifting. Repeat the corrugated tube. Make 3 windin	e process until the end of gs of tape then cut the tape.	Total Service 1997 Annual Control Service 1997 Annual Cont	1. Please measurin measurer 2. Used Variation the tape of BLACK 1 3. International shifting significant shifting	we use calibrated/ve g tape when getti ment. WHITE TAPE to e shifting, but actual TAPE. If tolerance for hall should be 0~14mm but tape enter tape enter tape ing tape	erified ing the asily visualize I should be Ifwarp taping	

	WORK INSTRUCTION Effectivity Date: June 27, 2024											
				Effectivity Date:	June 27, 2024							
		Process Name/Title:		TAPING ASSEMB				Validity Date:		n/a		
		Model code/Part number:	311D /	7N0195-7020Ea Customer:	TRJ	Car Model: T	OYOTA-RAV4	Document No.:		WI-ENG-PDE-9	19B	
		Purpose:	PROTOTYPE	PRE-LAUNCH		MASSPRO		Revision No.:	0	Page No.:	4 of 5	
		•										
PARTS:	1. Assy 2. Black							JIG:	n/a			
NO.	F	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION					TOOLS/PPE	(QUALITY POINTERS		
4	P2	Taping 2 Black Corrugated tube (No slit) to Corrugated tube (w/ slit)	2. Fix the Corrugate tube (No slit) and the Corrugated tube (w/slit) using both hands.	e 3. Get the black tape and start taping process using both hands.	4. Meas of Corru	Corrugated to end of he 272mm using the conduction of the 272mm using th	ape up to end it) 25±3mm. 2 3 R 3mm Corrugated ape 25±3mm.	6 7 8 9 (1) 1 2 3 4 5 6 7 8 9 (1. Please measuris measure 1. No peel- 2. No flip o 3. No loose 4. No wron	off tape out tape e tape g use of tape g dimension	verified	

			WORK INSTR TAPING	Effectivity Date:	June 27, 2024					
	Process Name/Title:		Validity Date:		n/a					
	Model code/Part number:	311D /	7N0195-7020Ea	Customer: TRJ	Car Model:	TOYOTA-RAV4	Document No.:		WI-ENG-PDE-91	19B
	Purpose:	☐ PROTO	YPE	PRE-LAUNCH	MASSPR	0	Revision No.:	0	Page No.:	5 of 5
	-							1		
PARTS: n/a							JIG:	n/a		
				QUALITY CH	ECKPOINTS					
P2				7N0 19	5-70	20Ea				
					TR	1.				
A STATE OF THE STA										
ATT TO THE PARTY OF THE PARTY O					1	2				
									-	-
	- communication	***************************************								
		AND THE PERSON NAMED IN		iliya ay			The state of the s			
-										
三人。多利曼						THE REAL PROPERTY OF THE PARTY				Print .
and the					2	FULL TAPING N				
						HALF WRAP (N EXPOSE COT)	0			
						EXPOSE COT)				
\parallel (1)	No MISSING TA	APE	(2) N	No EXPOSED	COT					
			\bigcirc							