			WORK INSTR	UCTION		Effectivity Date:			May 12,	2022	
		Process Name/Title:	TAPING A	SSEMBLY PROC	ESS	Validity Date:		n/a			
		Model Code/Product Number:	749W / 7H0337W7020B	Customer:	NBS	Document No.:			WI-ENG-PD	E-489B	
		Purpose:	☐ PROTOTYPE ☐	PRE-LAUNCH	MASSPRO	Revision No.:		1	Page No.:	1 of 5	
						1					
PARTS:	1. All p	arts; (Assy parts;Black Cor	rugated tube Ø5 L=174±3mm;Black Vinyl Tube &	Ø5 L=63±3mm;White Tape;	Blue tape (10mm))		JIG	1.Terminal cov	er jig		
NO.	P	ROCESS NAME	WORK PRO	CEDURE/ ILLUSTRA	ATION	TOOLS/P	PE	QUALITY POINTERS			
1	P2	Table Lay-out	Black Corrugated tube Ø5 L=174±3mm		Black Vinyl Tube Ø5 L=63±3mm Tape holder/Blue tape (10mm)	Safety Instructio Be sure to w prescribed per protective equipment du operation (glo finger cots, e Individual of the cots always practic 2. Personal th on the workpla prohibited. Ke in your lock Inform the Assembly Assi Supervisor or Leader for immediate corrective act	ear sonal control cont	1. No Missing p 2. No excess p Reviewed by		by Noted	, by
05/12/22 1	Chora	from Pre-Launch to Masspr	,		Tarana Tarana Tarana Taran	1			Approved		
05/12/22 1	Initial I	·	o. Additional Table Lay-out.		M. Ariola J. Loterte C.Villanueva A. A. M. Ariola J. Loterte C.Villanueva A.	rañes M.Ario		J. Loterte	C. Villana	veva A.Aran	2
Eff.Date Rev.No	illitial I	ouc.	Details of Change			oted Est. Date:		April 26, 2022	O. Villalia	-A.Aldi	103
<u> </u>											

				WORK INSTR	UCTION				Effectivity Date:			May 12,		
		Process Name/Title:				Y PROCES	S		Validity Date:		n/a			
		Model Code/Product Number:	749W	/ 7H0337W7020B	Custon	ner:	NBS		Document No.:			WI-ENG-PD	E-489B	
		Purpose:		☐ PROTOTYPE		UNCH	MASSPRO		Revision No.:		1	Page No.:	2 of 5	
										I	1			
	1. Assy 2. Black	Parts. Corrugated tube Ø5 L=17	74±3mm	3. Black Vinyl Tube	Ø5 L=63±3m	m				JIG	1.Termir	nal cover jig		
NO.	PF	ROCESS NAME		WORK PRO	CEDURE/	ILLUSTRATIO	ON		TOOLS/	PPE	QI	UALITY PO	DINTERS	
2	Wire Insertion to Black Corrugated tube Ø5 L=174±3mm (No Slit)			e terminal cover jig using right insert the V-V wires using left	cover		COT Ø5 L=174±3mm usin nsert V-V wires using left	R				No wrong Insertion No deformed terminal.		
3		Wire Insertion to Black Vinyl tube Ø5 L=63±3mm	L)	R		1.Get the Black Vinyl Tube Ø5 L=63±3mm using right hand and insert V-V wires using left hand.			n/a		No wrong use of parts No deformed terminal			

			WORK INSTRUCTION	Effectivity Date:	May 12, 2022				
	Process Name/Title:		TAPING ASSEN	Validity Date:	n/a				
		Model Code/Product Number:	749W / 7H0337W7020B Co	ustomer: NBS	Document No.:	WI-ENG-PDE-489B			
		Purpose:	☐ PROTOTYPE ☐ PR	RE-LAUNCH MASSPRO	Revision No.:	1 Page No.: 3 of 5			
<u> </u>									
PARTS:	1. Assy 2. White				JIG	n/a			
NO.	PF	ROCESS NAME	WORK PROCEDU	RE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS			
4	P2	Taping 1 Black Vinyl tube to Wire near terminal	Tape Width 35±3mm 6	2. Get Black tape, hold the vinyl tube (ø5 L=22±3mm) using left hand then fold the vinyl tube and start taping using right hand. Refer to WI-PRO-ASY-001 for taping procedure 3. After taping, check the measurement, alignment and tape condition.	6 7 8 9 10 1 2 3 4 5 6 7 8 9 1	Note: Please use calibrated/verified measuring tape when getting the measurement. 1. No flip-out tape 2. No peel-off tape 3. No loose tape 4. No missing tape 5. No wrong dimension 6. No wrong use of tape Wire alignment tolerance 0~1 mm			

WORK INSTRUCTION Effectivity Date: May 12, 2022									
		Process Name/Title:	TAPING ASSEN		Effectivity Date: Validity Date:	May 12, 2022 n/a			
	Model Code/Product Number:			stomer: NBS	Document No.:	WI-ENG-PDE-489B			
				E-LAUNCH MASSPRO	Revision No.:	1 Page No.: 4 of 5			
		Purpose:	PROTOTYPE PR	E-LAUNCH MASSPRO	Revision No.:	1 Page No.: 4 01 5			
PARTS: 1. Assy parts 2. White tape									
NO.	PF	ROCESS NAME	WORK PROCEDUR	RE/ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS			
5	P2	Taping 2 Black COT to Black Vinyl tube	1. Measure the end of the COT up to the end of the terminal pointed tip 120mm using both hands. Tape Width Tape 1. Tape Width	2. Hold the COT using left hand, get the White tape using right hand then start pre-taping using both hands. 3. After taping, check the measurement, alignment and tape condition.]	Note: Please use calibrated/verified measuring tape when getting the measurement. 1. No flip-out tape 2. No peel-off tape 3. No loose tape 4. No missing tape 5. No wrong dimension 6. No wrong use of tape Wire alignment tolerance 0~1 mm			

		WORK INSTRUCTION						May 12, 2022				
		Process Name/Title:	TAPING A	SSEMBLY PRO	CESS	Validity Date:		n/a				
		Model Code/Product Number:	749W / 7H0337W7020B	Customer:	NBS	Document No.:			DE-489B			
		Purpose:	☐ PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:		1	Page No.:	5 of 5		
	1	l .					•	1	Į.			
PARTS:	1. Assy 2. Blue	parts. tape (10mm)					JIG	n/a				
NO.	PI	ROCESS NAME	WORK PRO	CEDURE/ ILLUSTR	ATION	TOOLS	/PPE	QU	JALITY P	OINTERS		
6	P2	Spot Taping	1. Measure from Vinyl tube up to terminal pointed tip 65mm using both hands. NOTE: This dimension is for internal control only. Not specified in the drawing.	2. Get the Blue t taping process, of hands.	art of taping R ape (10mm) using right hand, begin conduct 2 windings using both ot taping, check the measurement, and tape condition.			1. No flip 2. No pee 3. No loo 4. No mis 5. No wro	easuremer -out tape el-off tape	on		