
NA			WORK INSTRUCTION									ectivity Date:		December 4, 2024		
			Process Name/Title: TAPING ASSEMBLY PROCESS									lidity Date:		n/a		
			Model code/Part number:	350B/320B/014B/ 360B/150B/	17J796-7051	Customer:	TRP	Car Model:		A-COROLL HIGHLANDE		cument No.:		WI-ENG-PDE-0	91A	
			Purpose:	☐ PROTOTYPE		PRE-LAUNCH	ł	■ MASSE	PRO		Re	vision No.:	18	Page No.:	1 of 3	
		1. Connector 1827842-1 (W)										JIG:		1. Insertion jig		
NO.		PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION								TOOLS/PPE	G	QUALITY POINTERS		
				INSERTION JIG Visual reference Guide Lock CONENECTOR ORIENTATION							-	Safety Instruction Be sure to wear required personal protective equipmed during operation (gloves, finger cost etc.)	1. Use the pi 2. No wrong 3. No wrong 4. No damag 5. No half-lo	1. Use the provided jig per model 2. No wrong usage of parts 3. No wrong orientation of connector 4. No damaged connector 5. No half-locked connector Important reminders/Note/s: 1. Automatically dispose and replace		
1			HIGH Connector setting to insertion jig 1827842-1 (W)	1. Get the connector 1827842-1 (W) using left hand then set to							Housekeeping 1. Maintain and always practice 5's 2. Personal things the workplace is prohibited. Keep it your locker.	terminal, locked co 2. If encourand immediate leader and contile Do not atterning the leader and contile and conti	the unit if once encountered Bend terminal, Difficulty of insertion, Half-locked connector. 2. If encountered abnormality, STOP and immediately CALL the attention of the leader. WAIT for further instruction and continue the process. Do not attempt to repair. 3. Follow the connector orientation.			
				L BEFORE PRESS	insertion insert	on jig.						Alert level For any trouble, inform the Assemb Assistant Supervise or Line Leader for immediate correctivaction.	dam or ve	Connector must be no damaged/half-locked/locked GOOD NG UNLOCK HALF-LOCKED		
		Indusion	of Quality improvement manage	rea (based on Mizen Booki	Revision History	andal "TOVOT	A COROLLA/					Prepared by	Reviewed by	Approved by	Noted by	
12/04/24	18	Inclusion of Quality improvement measures (based on Mizen Boshi activity). Inclusion of Car model "TOYOTA-COROLL RAV-4/ HIGHLANDER"						D.Castillo	C. Villanueva	A. Arañes	n/a	_				
03/02/23								M. Ariola M. Catapang	J. Loterte J. Loterte	C.Villanuev a C.Villanuev	A. Arañe	4				
08/18/22	16 15	Change s	hange setting of connector from right hand to left hand - process1, procedure1. Additional: Wire insertion procedure in ocess2, procedure4. Note for wire and strip length of tolerance.						J. Loterte	a C.Villanuev a	A. Arañe A. Arañe	1 1 2 2 2 2	C. Villanueva		2/5	
Eff. Date	Rev. No	,	Details of Change						Reviewed	Approved	Noted	Est. Date:	June 02, 2017	A. ARTHES	n/a	

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COI


MASTER COPY



CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY



CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY