

Process Name/ Title:				
Procedure of machine checking	Document No:	WI-PRO-CNC-063		
WORK INSTRUCTION	Effective Date:	May 17, 2021		

Product Code/Name: Customer Code: Rev. No.: 0 Page No.: Page 1 of 2 ALL ALL Records/Remarks/ No. Work Procedure/ Illustration **Quality Pointers** Confirm 1st. Sound of gush from air nozzle for insulation scum 1 1.1 Click the memory botton No.1 Crimper No. Memory Wire Type Front Crimping Res Total Length 563.6mm Length 4.8mm 1.2 Select the memory of DANKI B C D E
Search Obserts 7116-4025
AVSSF0 3 7114-4025
AVSSF0 3 7116-4025
AVSSF0 3 710390-0060
AVSSF0 3 710390-0060
AVSSF0 3 710349-0060
AVSSF0 3 710349-0060 8 0 1.3 Press the read botton and recall the memory 8100-3625 7D0349-0060 Regall From Memory Write(FI Search Write 1.4 Input the quantity on target pieces and then press the set botton 5 9 8 0 1.5 Press The start botton and proceed to normal operation Note:hear the sounds if there is unusual sound.if you hear unusual sound meaning there is a problem 8 in machine.operator must STOP-CALL-WAIT. O

						Prepare	Check	Approve
						my	1-	(Me'
			S.Apil	Y.Yamamoto	O. Merin	S.Apil	Y.Yamamoto	O. Merin
Eff./Rev. Date	Rev. No.	Details of change	Revise	Check	Approve	Est. date: 0	5/17/2021 /	



Procedure of machine checking

Document No:

WI-PRO-CNC-063

WORK INSTRUCTION

Effective Date:

May 17, 2021

Product Code/Name:

Customer Code:

Rev. No.:

Page No.:

Page 2 of 2

		ALL	ALL	Rev. No.:	U	Page	e No.:	Page 2 of 2	
No.			Work Procedure/ Illust	ration				Records/Remarks/ Quality Pointers	
2		gency switch to stop the mach	nine during running to che	eck if the emerge	ency botton will function				
3	Confirm position The pipe must be	of guide pipe e center on the cutter blade							
4	Confirm air press Check if the press Insulation scum (Grip (0.3 ~ 0.5 N Guide Plate (0.2 Chuck (0.1 ~ 0.3	sure is within the tolerance 0.2 ~ 0.4 MP) MP) ~ 0.4 MP)		3 8 8		1			

Thermo label (FRONT and REAR)

Waterproofseal (0.4 ~ 0.6 MP)

Blue color must be at the edge of circle

Unusual Sound









Note: If the whole circle covered by blue, machine reach the maximum degree temperature (80°c) and can cause over heat the machine.

Check after Operation is finished 6 Last sound of gush from air nozzle for Insulation scum Note: Repeat Procedure no. 1