

	Process Name/ Title:							
1	Leak Voltage N	Leak Voltage Measurement				WI-PRO-SHM-029		
	WORK INST	Effective Da	te:	April 23, 2025				
	Product Code/Name:	Customer Code:	Rev. No.:	4	Page No.:	1 of 1		
	ALL	<u></u> ALL	Nev. No	"		1 01 1		

No.	Work Procedure/ Illustration
-	

- 1 Procedure of measuring leak voltage
 - (1) Insert power plug of soldering equipment's body to tester of iron.
 - (2) Turn tester in. (1)
 - (3) Put string solder on iron and adapt it. (2)
 - (4) Before measuring, remove surplus solder on iron with cleaner. (3)
 - (5) Put iron on conduction plate and supply string solder to iron. (4), (5)
 - (6) Read display when data is settled. (6)
 - (7) In case of re-measure leak voltage, repeat above (2) ~ (6).



(1) Turn ON Tester



(2) Put small amount of lead on tip



(3) Clean the tip



(4) Put iron tip on conduction plate



(5) Supply string solder between iron tip and plate, then form heat bridge



(6) The leak voltage reading will appear on the display monitor.

Standard of Judgment:

When t it was higher than 2.0mV, it judges defect and must do below countermeasure;

- (1) Change soldering tip
- (2) In case, the reading is above 2.0mV even the iron is already changed, change the body of soldering iron.

							Prep	are	Check	Approve
Γ										
							N 1		~ /	_
Г	4/23/2025	1	Change Customer code	L.Famodulan	A.Ayop	W.Carbillon	Ams	صله	(Samo	Soulsh
ſ	7/1/2017	0	Previously established Work Instruction from NBC Japan (for history purpose only)	J. Ramilo	O. Merin	T. Suguyama	L.Fam	odulan	A.Ayan	W.¢arbillon
	ff./Rev. Date	Rev. No.	Details of change	Revise	Check	Approve	Est.	date:	July 1	, 2017