

										ectivity Date: November 20, 2024			024	
			Process Name/Title:						Validit	Validity Date:		n/a		
	- 1		Model code/Part number:	NB8 / 7N0208-	7020Aa Customer: TRJ	Car Model:	SUBAR	U-LEGACY	Docur	ment No.:			WI-ENG-PDE-11	09
			Purpose:	PROTOTYPE	PRE-LAUNCH	MASSP	RO		Revis	ion No.:		1	Page No.:	1 of 6
PARTS:			Clamp RT18RSF (W)							JIG:		2. Bando G		
NC	).	P	ROCESS NAME		WORK PROCEDURE/ ILLUSTR	ATION				TOOLS/PPE		C	<b>UALITY POIN</b>	TERS
1		Clamp Assy	Table Lay-out	Band Clamp RT18RSF (W)	TABLE LAY-OUT  Assy Part  Clamp Assembly Jig	Bando	Gun	A CARRIED TO SERVICE OF THE PARTY OF THE PAR	pri pro (g	Bafety Instructio Be sure to wear rescribed person otective equipme during operation gloves, finger cotect.)  Housekeeping Maintain and alway practice 5's. Personal things the workplace is ohibited. Keep it your locker.  Alert level rany trouble, infort Assembly Assist Supervisor or Lineader for immedia corrective action.	al ent s, s, ays on in trant e e ate	D 1. Please o	s/lacking parts/too	ce/s: first before
		1		Revisi	ion History			ı		Prepared by	Re	viewed by	Approved by	Noted by
11/20/24	1 0	Change p	re-launch to mass pro. ie.			1 1	C. Villanueva C. Villanueva	A. Arañes A. Arañes	n/a n/a	Okumomodu A.Hernandezi)		will of form	A. Aranes	n/a
Eff. Date	Rev. No			Details of Change			Reviewed			Est. Date:		r 08, 2024		
			·											<u> </u>



			Effectivity Date:	November 20, 2024							
		Process Name/Title:	Validity Date:	n/a							
		Model code/Part number:	NB8 / 7N0208-7020A	a Customer: TRJ	Car Model:	SUBARU-LEGACY	Document No.:	WI-ENG-PDE-1109			
		Purpose:	□РГОТОТУРЕ	PRE-LAUNCH	MASSF	PRO	Revision No.:	1	Page No.:	3 of 6	
PARTS:	1. Assy	Part					JIG:	1. Clamp a	assembly jig		
NO.	F	PROCESS NAME	WORK	PROCEDURE/ ILLUST	TRATION		TOOLS/PPE	QUALITY POINTERS			
3	Clamp			CROSS SECTIONS NO No No Half-I	1. Put the right hand hands. Ch	Fully locked	using na both	1. Use the provided locking jig per model 2. No unlock/half-locked connector 3. No damaged connector 4. No skip of locking process  Important reminders/Notes: 1. Manual locking may cause damaged connector lock. 2. Do not exert extra force. It may cause damaged of connector.  GOOD  NG  UNLOCK/ HALF-LOCK  Document references: 1. Refer to GL-PRO-ASY-017 for the		ig per model nector  s  rs/Notes: use damaged  . It may cause  NG  UNLOCK/ ALF-LOCK	

WORK INSTRUCTION Effectivity Date: Nov								November 20, 2024		
		Process Name/Title:	CLAMP ASSEM	Validity Date: n/a						
		Model code/Part number:	NB8 / 7N0208-7020Aa Custome	r: <b>TRJ</b> Car Model:	SUBARU-LEGACY	Document No.:		WI-ENG-PDE-11	09	
		Purpose:	PROTOTYPE PRE-LAUN	NCH MASS	PRO	Revision No.:	1	Page No.:	4 of 6	
PARTS:	1. Assy 2. Band	/ Parts d Clamp RT18RSF (W)				JIG:	1. Clamp Assembly Jig 2. Bando Gun			
NO.	F	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	QUALITY POINTERS			
4	Clamp Assy	Clamp Assembly	Connector Lock  1. Get the assy parts and set to jig using both hands. (See above picture for correct setting). First, set the connector 7C83-5524-70 (Y) in Receiver base 1. Continue to set the harness then last, set the W-BW wires together within the stopper then press by Toggle clamp.    BANDO GUN POSITION ON ON Continue to set the description of the size of the COT/Vinyl tube. For: Ø5 - 1~2, Ø7 - 3~4	hands. (Note: Hold protightening)  3. Get the bando gun u 1.  4. Conduct POINT CH	and clamp RT18RSF (W) operly the band clamp using using right hand then cut the ECKING before removing to BANDO GUN ALIGNMENT  PERPENDICULARITY  OK  NG  NG  NG  NG  NG  NG  NG  NG  NG  N	e band clamp on location	Impor  1. Make su stopper jig, use of tape  2. Setting of	tant reminders/Note re no gap between the and missing tape. of band clamp cutter COT/Vinyl tube.	e/s: ne terminal and	



		WORK INST	Effectivity Date:		November 20, 2024			
	Name/Title:	CLAMF	Validity Date:					
Model co	ode/Part number:	B8 / 7N0208-7020Aa	Customer: TRJ	Car Model: SUBARU-LEGACY	Document No.:		WI-ENG-PDE-1	109
Purpose	:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	1	Page No.:	6 of 6
PARTS: n/a					JIG:	n/a		
		VISU	UAL INSPECTION/QUA	ALITY CHECKPOINTS				
CLANA	D ACCV			700000 70	204-			
CLAIVI	P ASSY			7N0208-70	ZUAa			
2			_					
Been		(1)					~	
		2					(2)	100
								7
			4 17			-		
			1		-			
		(3)						
			The state of the s					
					Left.			
		The second second						
55000		ESTATE OF THE STATE OF THE STAT						
Qui. II	161 1-71 1	-lasta Ossus						1.11
( 1 )NO Ha	IITIOCK/U	nlock Conn	ector	(3)No	Missing T18RSF (	Clar	nn	ı
				(J)	Missing	Olul	iib.	
O	and the second second				T18RSF (	WII		
(2)No Mi	ssing Ta	pe (WHITE	and BLA	CK) (IX	101101	••//		ı
				,				
138.338								