CITABRIA 7ECA GROUND PROCEDURES			
DISPATCH	Throttle 1000 RPM	FIRE ON START	
Weather BRIEF	Oil Pressure CHECK	IF START	
NOTAMsCHECK	Mixture LEAN	Run 5 sec	
W&B <b>CHECK</b>	Lights ON	Mixture IDLE C/O	
Perf. Reqs CHECK	Radios SET	Evacuage GO	
SquawksCHECK	ATIS GET Barometer SET	IF NO START	
Illness CHECK	XPDRSET	Crank CONTINUE	
Medication CHECK Stress CHECK	Taxi Diag OPEN	Mixture IDLE C/O	
Alcohol CHECK	TAXI	Throttle FULL	
Fatigue CHECK	BrakesTEST	Fuel Shutoff OUT	
Eating CHECK	Controls WIND	Evacuage GO	
INSPECTION	RUNUP		
Fuel DRAIN, CHECK	Brakes SET		
AV1ATE CHECK	Controls CORRECT		
AROWCHECK	Trim TAKEOFF		
Mags <b>OFF</b>	Flight Inst CHECK		
Fuel Gauges TRUE	Fuel Shutoff IN		
Fuel Shutoff IN	Mixture BEST POWER		
Master ON	Throttle 1800 RPM		
Lights CHECK	Mags CHECK		
Stall Horn CHECK	Carb. HeatCHECK		
Master OFF	Engine Inst CHECK Throttle 1000 RPM		
ELT ARMED	Doors CLOSED		
Oil 6 qts Exterior CHECK	Seatbelts CHECK		
Ties/Chocks REMOVE	SWITCH TO FLIGHT		
Walkaround EXECUTE	SHUTDOWN		
START	XPDR SET, OFF		
Passengers BRIEF	Brakes SET		
Seatbelts CHECK	Lights OFF		
Stick FULL AFT	GPS <b>OFF</b>		
Fuel Shutoff IN	Mixture IDLE C/O		
Brakes <b>SET</b>	Mags <b>OFF</b>		
Electrical OFF	Master OFF		
Door CLOSED	Flight Plan CLOSE		
Carb. Heat OFF	SECURING		
MixtureRICH HOT: SKIP PRIME	Front Lap Belt . AROUND		
	STICK		
Prime	Back Lap Belt . <b>BUCKLE</b> Hobbs/Tach <b>NOTE</b>		
Master Switch ON	Squawks <b>NOTE</b>		
MagsON	Sun Shades REPLACE		
ThrottleSLIGHT	WheelsCHOCK		
Dueline	Tail Mile and DEODIENT		

Tail Wheel ... REORIENT

Ties ..... **TIE** 

Doors ..... LOCK

Brakes ..... SET

Clear Prop . ANNOUNCE

Starter ......PUSH

CITABRIA 7ECA FLIGHT PROCEDURES			
TAKEOFF BRIEF	APPROACH CFGS	NOTES	
Runway CHECK Crosswind CHECK Abort Speed NOTE Technique NOTE Min. Ret. Alt NOTE Best Glide NOTE Time NOTE Mixture BEST POWER	NORMAL Speed	<ul> <li>All airspeeds in MPH</li> <li>Carb. heat always on if icing suspected, indicated by gradual loss of RPM</li> <li>Only use rudder on</li> </ul>	
CLIMB	LOW VOLTAGE Master	takeoff and landing (no brakes)	
ThrottleOPEN  IF BELOW 5000	Nonessentials OFF Flight TERMINATE	Mixture should be leaned	
Mixture BEST POWER	OVERVOLTAGE	at any altitude when un- der 75% power. Lean	
Engine Inst CHECK Speed 75-80	Master CYCLE Flight TERMINATE ENGINE FAILURE	until engine roughness, then enrichen to smoothness.	
Best Rate 69 Best Angle 58	Best Glide 65 min		
PRE-DESCENT	Fuel Shutoff ON	V-SPEEDS V <sub>rotate</sub> 60	
Engine Inst	Throttle HALF Throttle FULL Mixture VARY Primer TRY Carb. Heat ON Mags TEST BOTH	$\begin{array}{cccc} V_x & & & 58 \\ V_y & & & 69 \\ V_a & & & 120 \\ V_{no} & & & 120 \\ V_{ne} & & & 162 \\ Best Glide & & 65 \\ \end{array}$	
	IF NO RESTART		
AFTER LANDING  TrimTAKEOFF MixtureLEAN Taxi DiagOPEN Carb. HeatOFF  SWITCH TO GROUND	Squawk		
TAKEOFF CFGS	Mixture IDLE C/O		
NORMAL  Rotate	Fuel Shutoff OUT Switches ALL OFF Cabin Heat OFF Extinguisher USE Flight TERMINATE		
Rotate	ELECTRICAL FIRE ElectricalOFF		
SOFT	VentsOPEN		
Attitude TAIL LOW After Liftoff LEVEL	ExtinguisherUSE  IF FIRE CONTINUES		

Flight ..... TERMINATE