C172SP GROUND PROCEDURES		
DISPATCH	Baggage Door CLOSED	RUNUP
Weather BRIEF W&B CHECK Perf. Reqs. CHECK NOTAMS CHECK IMSAFE CHECK Charts PACK Squawks CHECK	Ties/Chocks REMOVED Walk Around START Passengers	Brakes SET Fuel BOTH Controls FREE & CORR Annunciators CHECK Instruments CHECK Mixture BEST POWER Throttle 1,800 RPM Mags <150↓ <50△
INTERIOR Pitot Cover REMOVE Papers AROW Fuel Selector BOTH Fuel Shutoff IN Trim TAKEOFF Master ON	Seatbelts CHECK Circuit Breakers IN Avionics OFF Throttle 1/4" Mixture LEAN Prop CLEAR Master ON Beacon ON	Vacuum Sys GREEN Electric. Sys CHECK Oil Pressure GREEN Oil Temperature GREEN Throttle1,000 RPM MixtureLEAN Throttle Friction SET RadiosSET
Flaps	Aux Fuel Pump ON Mixture RICH Fuel Flow 3-5 GPH Mixture IDLE C/O Aux Fuel Pump OFF Mags START Mixture RICH Oil Pressure GREEN Throttle 1,000 RPM Mixture LEAN	SWITCH TO FLIGHT SHUTDOWN ELT CHECK 121.5 Avionics OFF Mixture C/O Mags OFF Master OFF Fuel LEFT Lights OFF SECURING Hobbs & Tach RECORD
Fuel QUANTITY Fuel QUALITY Static Port CLEAR Leading Edges CHECK Stall Indicator CLEAR Fuel Vent CLEAR Ailerons CHECK Flaps CHECK Elevator CHECK Rudder CHECK Trim Tab CHECK Exhaust SECURE Intake CLEAR Prop CHECK Engine COWL,, BELT Oil 6-8 QT. Fuel Caps SECURE Windscreen CLEAN	Seat Belts CHECK Flaps UP Heat/Vent/Defrost CHECK Avionics ON ATIS GET Altimeter SET XPDR ALT. & SQWK ADS-B ON Radio TEST Taxi Lights AS REQ'D Brakes TEST TAXI Controls WIND Attitude Indicator . CHECK Turn Coordinator . CHECK Heading Indicator SET	Control Lock SET Tie Downs SECURE Pitot Cover REPLACE Sun Shades REPLACE Doors LOCK Squawks RECORD Flight Plan CLOSE FIRE ON START IF START Throttle 1,800 RPM Run Mixture IDLE C/O IF NO START Crank CONTINUE Throttle FULL Mixture IDLE C/O Fuel Shutoff OUT Master & Mags OFF

C172SP FLIGHT PROCEDURES

PRE-TAKEOFF	ENGINE FAILURE	ELECTRICAL FIRE
Runway CHECK	Best Glide68	All Switches OFF
Technique NOTE	Landing Site FIND	Vents/Air CLOSE
Crosswind CHECK	Wind IDENTIFY	ExtinguisherUSE
Abort Plan BRIEF	Fuel CutoffIN	Ensure Fire Extinguished
TPA/Departure BRIEF	Fuel Selector BOTH	Vents OPEN
	Aux Fuel Pump ON	BreakersCHECK
HI SET & BUG	Mixture RICH	Master ON IF CRITICAL
Flaps SET	MagsTEST BOTH	Flight TERMINATE
Trim TAKEOFF	MasterON	IMPORTANT NUM.
Lights ON		V _X 62 V _Y 74
XPDR SET	FORCED LANDING	S ₀ 40 V _{S1} 48
Mixture BEST POWER	Best Glide 68	V _{FE 10} 110 V _{FE} 85
Time NOTE	Squawk 7700	V _{NO} 129 V _{NE} 163
CLIMB	Emergency DECLARE	V _{ROT} 55 V _{A₂₅₅₀} 105
Speed 70-85	MixtureIDLE C/O	V _{A2200} 98 V _{A1900} 90
Flaps UP	Fuel Shutoff OUT	Fuel 56 Usable 53
Power	Mags OFF	Best Glide68
Mixture LEAN >3K	Flaps AS REQ'D	Max Gross2550
Engine Inst CHECK	Master OFF	Max Crosswind15
CRUISE	SeatbeltsSECURE	
Power SET	Doors	TAKEOFF CFGS
Mixture LEAN >3K	Landing EXECUTE	NORMAL
Instruments CHECK	LOW VOLTAGE	Flaps
Flaps	Power>1000 RPM	Rotate
Switches (Pump)		Climb74
DESCENT	Avionics Master OFF	SHORT
Fuel BOTH	Alt. CB CHECK IN Master Switch CYCLE	Flaps 10 °
Power SET	"VOLTS" CHECK OFF	Brakes APPLY
Mixture ENRICH	Avionics MasterON	Climb56
Instruments CHECK	If "VOLTS" illumniated:	Flaps UP AT >60 KIAS
Lights ON	MasterALT OFF	APPROACH
ATIS GET	Nonessential Equip OFF	NORMAL
AltimeterSET	Flight TERMINATE	Downwind85
Tower CONTACT		Base
PRE-LANDING	OVERVOLTAGE	Final 60 - 70
AutopilotOFF	Master ALT. OFF	
Seat Belts SECURED	Nonessential Equip OFF	
Fuel BOTH	Flight TERMINATE	
Brakes TEST	Beware Compass Deviat'n	
Mixture RICH	<u> </u>	
Lights ON	ENGINE FIRE	
Flaps AS REQ'D	MixtureIDLE C/O	
AFTER LANDING	Fuel ShutoffOUT	
FlapsUP	Master OFF	
Trim TAKEOFF	Heat & AirCLOSE	
Switches OFF	Airspeed 100+	
Mixture LEAN	Forced Landing	v1.1