CITABRIA 7ECA GROUND PROCEDURES			
DISPATCH	Mixture LEAN	FIRE ON START	
Weather BRIEF	Lights ON	IF START	
NOTAMsCHECK	Radios SET	Run 5 sec	
W&B CHECK	ATIS GET	Mixture IDLE C/O	
Perf. Reqs CHECK	BarometerSET	EvacuageGO	
Squawks CHECK	XPDR SET	IF NO START	
IMSAFE CHECK	Taxi Diag OPEN		
INSPECTION	TAXI	Crank CONTINUE Mixture IDLE C/O	
AV1ATE CHECK	BrakesTEST	Throttle FULL	
FuelSTICK	Controls WIND	Fuel ShutoffOUT	
AROWCHECK		EvacuageGO	
Mags OFF	RUNUP		
Fuel Gauges TRUE	Door CLOSED		
Fuel ShutoffIN	Seatbelts CHECK		
Master ON	Brakes SET		
Lights CHECK	Controls CORRECT		
Stall Horn CHECK	Trim TAKEOFF		
Master OFF ELT ARMED	Flight Inst CHECK		
Oil5-6 qts	Fuel Shutoff IN		
Fuel DRAIN	Mixture BEST POWER		
Exterior CHECK	Throttle 1800 RPM		
Ties/Chocks REMOVE	Mags CHECK		
Walkaround EXECUTE	Carb. HeatCHECK		
START	Engine Inst CHECK Throttle 1000 RPM		
Passengers BRIEF			
Seatbelts CHECK	SWITCH TO FLIGHT		
BreakersCHECK	SHUTDOWN		
Fuel Shutoff IN	Brakes SET		
Electrical OFF	Lights OFF		
Door CLOSED	GPS OFF		
Stick FULL AFT	XPDR SET, OFF		
Carb. Heat COLD	Mixture IDLÉ C/O		
Mixture RICH	Mags OFF		
HOT: SKIP PRIME	Master OFF		
Prime2x	Flight Plan CLOSE		
Primer LOCKED	SECURING		
Master Switch ON			
MagsON	Tail Wheel REORIENT		
Beacon	Front Belt STICK Back Belt BUCKLE		
Brakes SET	Hobbs/TachNOTE		
Clear Prop DECLARE	Squawks NOTE		
StarterPUSH	Sun ShadesREPLACE		
Throttle 1000 RPM	WheelsCHOCK		
Oil Pressure CHECK	TiesTIE		
Ammeter CHECK	Door LOCK		

Door LOCK

Ammeter CHECK

CITABRIA 7ECA FLIGHT PROCEDURES			
TAKEOFF BRIEF	APPROACH CFGS	NOTES	
Runway CHECK Crosswind CHECK Abort Speed NOTE Technique NOTE Min. Ret. Alt NOTE Best Glide NOTE Time NOTE Mixture BEST POWER	NORMAL Speed	 All airspeeds in MPH Carb. heat always on if icing suspected, indicated by gradual loss of RPM Use only rudder on takeoff and landing (no 	
CLIMB	Master CYCLE	brakes)	
ThrottleOPEN	Nonessentials OFF Flight TERMINATE	Mixture should be leaned at any altitude when un-	
IF BELOW 5000	OVERVOLTAGE	der 75% power. Lean	
Mixture BEST POWER Engine Inst CHECK Speed 75-80	Master CYCLE Flight TERMINATE ENGINE FAILURE	until engine roughness, then enrichen to smoothness.	
PRE-DESCENT	Best Glide 65	IMPORTANT NUM.	
Engine Inst CHECK ATIS GET Barometer SET Tower CONTACT Mixture ENRICH Lights ON	Fuel Shutoff ON Throttle HALF Throttle FULL Mixture VARY Primer TRY Carb. Heat HOT Mags TEST BOTH	Vso 50 Vrotate .55 Vx 58 Vy 69 Va 120 Vno 120 Vne 162	
AFTER LANDING	IF NO RESTART	Best Glide65	
Carb. Heat COLD Trim TAKEOFF Mixture LEAN Taxi Diag OPEN SWITCH TO GROUND	Squawk	Max Gross1750 Max Crosswind15 Fuel35	
TAKEOFF CFGS	ENGINE FIRE		
NORMAL	Mixture IDLE C/O		
Rotate	Fuel Shutoff OUT Switches ALL OFF Cabin Heat OFF Extinguisher USE Flight TERMINATE		
Climb 58	ELECTRICAL FIRE		
SOFT	Electrical OFF Vents OPEN Extinguisher USE		
Attitude TAIL LOW After Liftoff LEVEL	IF FIRE CONTINUES		

Flight **TERMINATE**