DIAGNOSTIC TROUBLE CODE CHART

DI1KH-09

DTC No. (See page)	Detection Item	Trouble Area
B2785 (DI-498)	Ignition Switch ON Malfunction	Ignition switch EFI main relay Wire harness ECM
B2786 (DI-498)	Ignition Switch OFF Malfunction	
B2791 (DI-502)	Key Unlock Warning Switch OFF Malfunction	Key unlock warning switchWire harnessECM
B2795 (DI-504)	Unmatched Key Code	Key Unregistered key inserted before
B2796 (DI-505)	No Communication in Immobiliser System	 Key Transponder key coil Transponder key amplifier Wire harness ECM
B2797 (DI-507)	Communication Malfunction No. 1	Communication contests Unregistered key inserted before ECM
B2798 (DI-509)	Communication Malfunction No. 2	 Key Transponder key coil Transponder key amplifier Wire harness ECM

HINT:

To reduce the unnecessary exchange of ECM, check that a trouble occurs with the original ECM at the time of exchanging ECM and the trouble will disappear with a new ECM.

Author: Date: 670

2002 4RUNNER (RM887U)