

VAN'S AIRCRAFT, INC.



Note: This entire section depicts the wing rib installation for the left wing only. The right wing is a mirror of the left.

Step 1: Flute and straighten all ribs per Section 5N.

Step 2: Cut a piece of AA6-063X3/4X3/4, 7 13/16 inches long as shown in Figure 1.




FIGURE 1: CUTTING THE W-1029C ANGLE

Step 3: Cut a piece of .063 2024-T3 ALCLAD and mark the alignment lines per the dimensions in Figure 2.




FIGURE 2: CUTTING AND MARKING THE W-1029D SPACER

Step 4: Cut a piece of .063 2024-T3 ALCLAD and mark the alignment lines per the dimensions in Figure 3.





FIGURE 3: CUTTING AND MARKING THE W-1029E SPACER

Step 5: Clamp W-1029A-L Torque Tube Support Bracket, W-1029D Spacer and W-1029E Spacer together with the centerlines drawn in steps 2 and 3 aligned with the holes in the support bracket as shown in Figure 4. Match-Drill the spacers #30 using the torque tube support bracket as a drill guide.



Step 6: Cleco the VA-146 Flange Bearing in-between the W-1029A-L and W-1029B-L Torque Tube Support Brackets. Cleco the assembly to the upper and lower flanges of the W-1010-R Inboard Wing Rib as shown in Figure 5. (The support brackets cleco into the fourth and fifth holes back from the front of the main flange not counting the tab.) Clamp the W-1029C Angle flush against the aft face of the W-1029B-L Torque Tube Support Bracket and the inboard face of the inboard wing rib.

Step 7: Match-Drill #30 and cleco the W-1010 R Inboard Wing Rib to the W-1029C Angle using the holes in the rib as a drill guide.

Step 8: Match-Drill #30 and cleco the W-1029A-L and W-1029B-L Torque Tube Support Brackets to the W-1029C Angle at two attach points using the support brackets as a drill guide. Use a right angle drill or extension bit for best results. Match-drill the holes common between the torque tube support brackets and the VA-146 Flange Bearing. Disassemble all parts from the inboard wing rib. Cleco the W-1029B-L Torque Tube Support Bracket to the angle at the two locations just drilled and Match-Drill #30 the remaining attach holes.




FIGURE 5: MATCH-DRILLING W-1029C ANGLE

Step 9: Cleco the W-1025B-L Flap Hinge Rib and W-1025A Flap Hinge Bracket to the W-1010-R Inboard Wing Rib as shown in Figure 7. Final-Drill all common attach holes in the assembly to #30.

Step 10: Cleco the W-1025B-R Flap Hinge Rib and W-1025A Flap Hinge Bracket to the two alignment holes in the W-1011-1 Inboard Wing Rib as shown in Figure 8. Match-Drill #30 the inboard wing rib using the holes in the flap hinge rib and bracket as a drill guide. Final-Drill #30 the two alignment holes. Repeat this process to create two assemblies as shown in Figure 8. Ream the flap attach hole in all flap hinge brackets to 3/8.





FIGURE 7: INBOARD FLAP HINGE ASSEMBLY


FIGURE 8: OUTBOARD FLAP HINGE ASSEMBLIES



Step 1: Remove the flange and flange radius from the top and bottom tabs of a **single** W-1011 R Inboard Wing Rib as shown in Figure 1. This notch will remove interference between the outboard-most tank attach nutplate and the W-1011 R Inboard Wing Rib that attaches to the main spar assembly at that span wise location. The amount of trim is the same on both the top and bottom tab.



Step 2: Remove the aft flange but not the flange radius from the W-1012-R Outboard Wing Rib as shown in Figure 2.



Step 3: Cleco the W-1010-R Inboard Wing Rib, W-1011-L/R Inboard Wing Ribs and W-1012-L/R Outboard Wing Ribs to the main spar assembly as shown in the isometric view on Page 14-1.

Match-Drill to #12 the upper and lower attach points on the W-1010-R and all the W-1011-L/R Inboard Wing Ribs that will be attached with bolts to the main spar assembly (see Page 14-6, Figure 1), using the holes in the main spar assembly as a drill guide. Use a wood block to support the forward flange of the ribs while drilling.


Final-Drill #30 all the remaining common attach holes in the forward flange of the ribs and web of the main spar assembly.

Final-Drill #40 all the common attach holes in the upper and lower rib tabs and the flanges of the main spar assembly.

Step 4: Disassemble the ribs from the main spar assembly. Disassemble the W-1025A Flap Hinge Brackets and W-1025B Flap Hinge Ribs from the inboard ribs.

Deburr all holes in all parts. Prime all parts if/as desired.

Step 5: Cleco the W-1025E-R Flap Hinge Rib and W-1025A Flap Hinge Bracket to the W-1011-L Inboard Wing Rib. Rivet the flap hinge rib and flap hinge bracket to the inboard wing rib as shown in Figure 3. Repeat this process to create two assemblies using the W-1011-L Inboard Wing Rib.



Step 6: Cleco and rivet the VA-146 Flange Bearing, W-1029AL and W-1029B-L Torque Tube Support Brackets, W-1029C Angle, W-1029D and W-1029E Spacers together as shown in Figure 4.

Step 7: Cleco and rivet the W-1029C Angle and support bracket assembly to the web of the W-1010-R Inboard Wing Rib as shown in Figure 4.

Step 8: Cleco and rivet the W-1025B-L Flap Hinge Rib and W-1025A Flap Hinge Bracket to the W-1010-R Inboard Wing Rib as shown in Figure 4.

