



SW/FW Release note 2020.09.30

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of DADman control software Product firmware. The released DADman is applicable for the products AX32, DX32, Penta 720, Penta 721, Avid MTRX and Avid MTRX Studio, generally denominated the Products in this document. The Firmware is divided into a version dedicated MTRX studio and a common version for the other Products.

DADman control software:	v.5.4.4 build 2
Compatible with Windows 7, 8 and 10 and Mac OS X, 10.10 to 10.15	
Main board firmware for:	
AX32, DX32, Penta 720, Penta 721, Avid MTRX	v.2.3.2.1
Brooklyn II firmware (Dante version 4.0.9.1)	No update, still v.1.0.2.1
Main board firmware for:	
MTRX Studio	v.1.0.3.2
MTRX Studio Dante 64 IPCore (Dante version 1.3.7.1)	v.1.0.0.4

New features

DADman software v.5.4.4 build 2 has some improvements related to:

The new features are:

- ☐ No new features

Bug fixes:

- ☐ Bass management on multiple subs should now be handled correct.
- ☐ Recall of layouts on S6. The EuCon persistent ID of a DADman node is changed to "DADman" which I hope solves this issue.
- ☐ FW update of MTRX Studio. This is actually an MTRX Studio problem (see below). In the new version of DADman we have added a small amount of delay between each record programmed for MTRX Studios running FW versions pre version 1.0.3.2. In my setup this solves the problem.
- ☐ SPQ config error introduced in v. 5.4.4 build 1 is corrected.

We have also made a new FW version for the MTRX Studio (ver 1.0.3.2). This version corrects a problem in the handling of IP packages send in quick succession which again caused the firmware update problem.



We would suggest you first update DADman to the new version and try programming the old MTRX Studio FW version (1.0.3.1) a couple of times in your setup. In my setup this takes approx. 3½ minutes. It should not be significantly slower in your setup.

Update the MTRX Studio to FW version 1.0.3.2. and repeat the programming test with FW version 1.0.3.2 a couple of times. The update should now be approx. 20 seconds faster.