



SW/FW Release note 2024.12.01

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of the DADman control software and the updated firmware. The released functionality is applicable for the products AX32, DX32, Penta and DAD Thunder | Core series, MOM, Avid MTRX, Avid MTRX Studio, Avid MTRX II and Dynaudio Control 01, generally denominated the Products in this document.

This new release addresses various new functionality enhancements and bug fixes in DADman and in the Firmware for all Products except the MOM. The primary new functionality is the Control | Pack functionality, support for the new MADl card CARD-2MADI-SO with sample rate converter also on the output, and support for an updated version of the Thunderbolt 3 module 722-150B. The 722-150B module is an Intel certified redesign of the previous module 722-150A due to some component changes. The functionality of the two version is 100% identical.

The details are listed below.

DADman control software:	MacOS	New
Compatible with MacOS 10.13 to 10.15 and MacOS 11, 12, 13, 14 and 15 with Intel or Apple silicon processor	v.5.8.0 build 8	
Please see note below on MacOS 15 compatibility		
Windows 10 and 11	Windows	New
	v.5.8.0 build 8	
Thunder Core driver software:	MacOS	New
DAD Thunderbolt 3 Core Audio Driver:	v.1.2.2	
Compatible with macOS 11, 12, 13, 14 and 15 Apple Silicon and Intel Computers		
DAD Thunderbolt 3 Windows ASIO driver	Windows	No change
Compatible with Windows 10 and 11	v. 1.1.2	
Main board firmware for:		
AX64, AX Center, Core256, Avid MTRX II and Control 01	v.1.1.0.3	New
Dante 256 IPCore (Dante version 4.1.1.1)	v.1.0.2.1	No change



Main board firmware for:

AX32, DX32, Penta 720, Penta 721s, Avid MTRX	v.2.4.4.1	New
Brooklyn 2 Dante module (Dante version 4.0.9.1)	v.1.0.2.1	No change
Brooklyn 3 Dante module (Dante version 4.2.3.8)	v.1.1.0.2	No change

Main board firmware for:

MTRX Studio	v.1.1.5.1	New
MTRX Studio Dante 64 IPCore (Dante version 1.3.7.1)	v.1.0.0.4	No change

New in DADman

Added functionality

- **Control | Pack** functionality with Routing Presets support for AX Core devices.
- Support for 720251A MADI card with bi-directional sample rate conversion.
- In the Monitor view the folddown controls is shown in columns instead of just expanding horizontally in the view, when many folddowns are allocated.

Changed functionality

- **Windows:** The oldest supported OS version is now Windows 10

Known issues

- **macOS:** When running on Sequoia (macOS 15), DADman may not be able to connect to devices on the network. This does not affect connecting to Thunderbolt devices.
To workaround the problem, log out of the system and log in again.
The problem is of a general nature which has appeared in the recent Sequoia MacOS version and therefore also an issue for previous DADman versions.

Fixed

- After clicking "Cancel" when loading a monitor profile, DADman would corrupt the file on the next save.
- **macOS:** When scrolling on scaled display resolutions, sometimes thin black vertical or horizontal lines would show up.



- **macOS:** DADman would crash if started by double-clicking a file in the Finder.
- **macOS:** When hidden in the menu bar and running on Sonoma, DADman would sometimes fail to become the frontmost application when clicking the "Show" menu item.
- **macOS:** DADman could become unresponsive if an error was shown while it was hidden in the menu bar.
- **macOS:** Fix a rare Thunderbolt issue that would cause DADman to be unable to communicate with the device. To fully eliminate the problem, please also upgrade the DAD Thunderbolt Driver to version 1.2.2 or newer.
- **macOS:** It is no longer possible to choose directories instead of files in "Open" dialogs.

New in DAD Thunderbolt 3 Core Audio Driver (DADdriver)

Added functionality

- When the DriverKit extensions are not properly activated, a message is shown along with a screenshot illustrating how to activate it.
- When DADDriverSetup.app is launched from the installer and the DriverKit extension is successfully activated, the application brings the installer to the front and terminates
- When no device is connected, instead of empty dropdown boxes, the window shows a "No device connected" message.

Fixed

- In rare circumstances, DADman would be unable to communicate with a device

New in the firmware

Native functionality for Thunder Core products and MTRX II

- Control | Pack functionality with Routing Presets support for AX Core devices.
- Support for CARD-2MADI-S0 / 720251A MADI card with bi-directional sample rate conversion.
- Official (Intel signed and secured FW) support for the new Thunderbolt module with a Titan Ridge thunderbolt controller
- Improved and stabilized DADman communication over Thunderbolt. For best performance also update the Thunderbolt driver to the new version (mac only).
- Various minor bug fixes.

Native functionality for Thunder Core products and AX32 and Penta



- Support for 720251A MADI card with bi-directional sample rate conversion.

Native functionality for Thunder Core products and MTRX Studio

- Official (Intel signed and secured FW) support for the new Thunderbolt module with a Titan Ridge thunderbolt controller
- Improved and stabilized DADman communication over Thunderbolt. For best performance also update the Thunderbolt driver to the new version (mac only).