Information Systems and Technology March 25, 1999

WYSE 55 Terminal Parameters

- 1) Press the **<Shift>** and **<SetUp>** keys to display the Setup Directory screen. Setup Menus are accessed by pressing the corresponding Function Key (indicated at the bottom of the screen).
- 2) Press a Function Key to access the Setup Menu.
- 3) Use the arrow keys to select a parameter.
- 4) Press the **<SPACEBAR>** to change the option for the highlighted parameter.

The recommended settings are:

F1 (Disp)	Columns = 80	Cursor = Blink Blk	Scrn Saver = Off
	Lines = 24	Display = Dark	$Char Cell = 10 \times 16$
	Page = $1 \times \text{Lines}$	Autopage = Off	80/132 Clear = Off
F2 (Genrl) F3 (Keybd	Personality = TVI 925	Enhance = On	Status Line = Off
	Scrl = Jump	Autoscrl = On	Wrap EOL = On
	Rcv CR = CR	Monitor = Off	Recognize DEL = Off
	Keyclick = Off	Repeat = On	Keycode = ASCII
	Keylock = Caps	Language = US	Corner Key = Meta
)	_		
F4 (Comm)	Comm = FDX	Xmt Lim = None	Answerback Mode =
			Off
	Mdm Rc Hsk = XON-		Mdm Xmt Hsk =
	XOFF/XPC	= 192	XON-XOFF
	Aux Rc Hsk = None	Send $ACK = Off$	Aux Xmt Hsk =
	_		None
F5 (Ports)	Mdm Baud Rate =	Mdm Data/Parity	Mdm Stop Bits = 1
	9600	= 8/None	
	Aux Baud Rate =	Aux Data/Parity =	Aux Stop Bits $= 1$
	9600	8/None	
	Host Port = Modem	Printer Attached =	Nulls Suppress = Off
	Port	On	WIDDELY 11 000
F6 (Misc)	WPRT Intensity =	WPRT Rev = Off	WPRT $Undrln = Off$
	Dim	Auglio Die	M let l D . Off
	Blk End = US/CR	Attribute = Page	Multiple Page = Off
	Margin Bell = Off	Bell Volume = 1	Rest/Act.
	Cl. C. LCO	Cl. M. L.	Times=None
F7	Char Set = ISO	Char Mode =	ANSI $ID = VT 100$
(ANSI1	Latin-1	Multinational	

1

)	Cursor Keys =	Keypad = Numeric	DEL = DEL/CAN
	Normal		
	Feature Lock = Off	Fkey Lock = Off	Newline = Off
F8 (ANSI2)	Print = All	Print Area = Page	Print Term = None
	Send = All	Send Area = Page	Send Term = None
	Xfer Term = Cursor	Auto Answerback = Off	Keys = Typewriter
F9 (TABS)	Undefined		
F10			
(Ansbk	ANSWERBACK=		
)			
F11	(see next section)		
(Fkeys)	(See Heat Section)		

- 5) To save the parameters, press < **F12**>.
- 6) Press the **<SPACEBAR>** until "**All**" appears in the field beneath the **Save?** setting.
- 7) Press < **F12**> to exit setup mode.

To program function keys:

The Wyse 55 does not restrict the number of characters associated with one function key; it sets a maximum number of characters (64) for all the function keys taken together.

- 1) Press the **<Shift>** and **<SetUp>** keys to display the Setup Directory screen.
- 2) Select the Fkeys category by pressing the $\langle \mathbf{F11} \rangle$ key.
- 3) Hold down < **Ctrl**> and press any function key.
- 4) Use the up and down arrow keys to program either the "shifted" ($\mathbf{F3}$ =) or "unshifted" ($\mathbf{sF3}$ =) state of the function key by highlighting the appropriate box
- 5) Enter the desired data for the chosen key.

Tips

- a. Use the left arrow key (not < **BackSpace**>) to erase characters.
- b. Press < **Home**> to clear an entry entirely.
- c. Press < **Return**> to enter a Return/Send character.

- 6) Repeat Steps 3 5 for any additional keys.
- 7) To save the parameters, press < **F12**>.
- 8) Press the **SPACEBAR**> until "**All**" appears in the field beneath the **Save?** setting.
- 9) Press < **F12**> to exit setup mode.