

4	<i>I</i> .	-	
V0.0.2 — Removed 10k resistor between SJ5 and SIG_EMCYSTOP. Would have prevented ESTOP signal Corrected mini mainboard symbol voltage on throttle input to 0—6.6v (V2 bottom right corne	from going high with mini mainboard rer,) also corrected in notes.	resistor divider circuit.	
V0.0.3 — L2 was (C1046) a 10uH 0805 but only 15ma. Changed to a Sunlord 4030 / 4.0mmx4.0mm	n inductor footprint.		
	Sheet: /Revisions/		
	File: Revisions.kicad_sch		
	Title: Size: A4 Date:	Rev	: V0.0.3
	KiCad E.D.A. kicad (6.0.5)	ld:	2/2