

EXPRESS DIAGNOSTICS

Advanced Vehicle Diagnostic & ADAS Analysis Report

Vehicle	Year) Ford Post-scan Report
VIN	Not detected
Mileage	Not detected
Scan Date	Not detected
Scan Type	Pre & Post Scan
DTCs Found	5
Generated By	Express Diagnostics

Scan Summary

The scan report was processed and 5 Diagnostic Trouble Code(s) were identified. The following explanations are intended to support repair planning, ADAS documentation, and post-repair verification.

Detected DTCs & Professional Analysis

DTC	U0140:00-08
Description	Lost Communication With Body Control Module CMDTCs
What This Means	Lost communication with the Body Control Module.
Possible Causes	• Low voltage or battery disconnect • CAN network communication issue • Loose, damaged, or corroded wiring
Recommended Actions	• Verify battery voltage and charging system • Inspect BCM connectors and grounds • Repair damaged wiring
ADAS / Safety Impact	May affect communication between ADAS, lighting, body, and safety-related modules.

DTC	B1445:15-48
Description	Rear park lamps output CMDTCs
What This Means	Rear park lamp output circuit fault.
Possible Causes	• Damaged rear lighting circuit • Open or shorted wiring • Corroded connector • Rear body electrical concerns
Recommended Actions	• Inspect rear lamp wiring and connectors • Check for short/open circuit • Repair damaged wiring
ADAS / Safety Impact	Rear body electrical concerns may require inspection of nearby sensors, harnesses, and parking aid system

DTC	B153E:08-08
Description	Trailer Hitch Light Output CMDTCs
What This Means	Trailer hitch / trailer lighting output fault.
Possible Causes	• Trailer wiring fault • Damaged hitch wiring • Corrosion at trailer connector • Shorted or open circuit
Recommended Actions	• Inspect trailer connector • Check hitch wiring harness • Test lighting circuits • Repair damaged wiring
ADAS / Safety Impact	Rear wiring issues may overlap with parking aid, blind spot, and rear body harness inspection

DTC	B115E:08-08
-----	-------------

Description	Camera Module CMDTCs
What This Means	Camera module / image processing system fault.
Possible Causes	• Camera misalignment • Camera calibration lost • Windshield or camera bracket distu
Recommended Actions	• Inspect camera mounting and windshield area • Verify camera/module communication
ADAS / Safety Impact	Critical ADAS concern. May affect lane keep assist, pre-collision assist, forward collision warnin

DTC	U0146:00-08
Description	Lost Communication With Serial Data Gateway A CMDTCs
What This Means	Lost communication with gateway module.
Possible Causes	• Network interruption • Gateway module power/ground issue • Damaged CAN wiring
Recommended Actions	• Perform network health check • Inspect gateway module connectors • Verify module
ADAS / Safety Impact	Gateway communication issues can prevent ADAS modules from communicating properly.

Required / Recommended ADAS Operations

- 1
- Forward camera calibration / camera system verification
- 2
- Forward camera calibration may be required
- 3
- Network communication verification
- 4
- Network communication verification required
- 5
- Parking aid system verification may be required
- 6
- Post-repair road test and functional validation

Insurance / Repair Documentation Statement

Fault codes and ADAS-related module concerns must be evaluated according to OEM repair procedures. Clearing codes alone does not confirm system integrity. After repairs, affected systems should be verified through post-scan documentation, calibration when required, and functional road testing.