



CUSTOMER READY DIAGNOSTIC & ADAS REPORT

Precision. Safety. Confidence.

Vehicle Information

Vehicle	2019 Ford Expedition
VIN	1FMJK2AT9KEA72366
Mileage	122296.46
Scan Date	2026-05-04
Scan Type	Pre & Post Scan
DTCs Found	5

Scan Summary

This report explains the fault codes found during the scan and identifies safety-related systems that may require additional inspection, repair, calibration, or verification.

Detected DTCs & Professional Analysis

DTC	U0140:00-08
Description	Lost Communication With Body Control Module CMDTCs
What This Means	Lost communication with the Body Control Module.
Possible Causes	• Low voltage or battery disconnect • CAN network communication issue • Loose, damaged, or corroded connector • Body Control Module power/ground issue
Recommended Next Steps	• Verify battery voltage and charging system • Inspect BCM connectors and grounds • Check CAN network communication • Clear codes and verify they do not return
Safety System Impact	May affect communication between ADAS, lighting, body, and safety-related modules.

DTC	B1445:15-48
Description	Rear park lamps output CMDTCs
What This Means	Rear park lamp output circuit fault.
Possible Causes	• Damaged rear lighting circuit • Open or shorted wiring • Corroded connector • Rear body damage or repair-related harness issue
Recommended Next Steps	• Inspect rear lamp wiring and connectors • Check for short/open circuit • Repair damaged harness • Verify lighting operation

Safety System Impact	Rear body electrical concerns may require inspection of nearby sensors, harnesses, and parking/side detection systems.
-----------------------------	--

DTC	B153E:08-08
Description	Trailer Hitch Light Output CMDTCs
What This Means	Trailer hitch / trailer lighting output fault.
Possible Causes	• Trailer wiring fault • Damaged hitch wiring • Corrosion at trailer connector • Shorted lighting output
Recommended Next Steps	• Inspect trailer connector • Check hitch wiring harness • Test lighting circuits • Repair or replace damaged wiring
Safety System Impact	Rear wiring issues may overlap with parking aid, blind spot, and rear body harness inspection needs.

DTC	B115E:08-08
Description	Camera Module CMDTCs
What This Means	Camera module / image processing system fault.
Possible Causes	• Camera misalignment • Camera calibration lost • Windshield or camera bracket disturbance • Camera wiring or connector issue • Camera module fault
Recommended Next Steps	• Inspect camera mounting and windshield area • Verify camera/module communication • Perform OEM forward camera calibration • Complete post-calibration road test
Safety System Impact	Critical ADAS concern. May affect lane keep assist, pre-collision assist, forward collision warning, and related camera-based systems.

DTC	U0146:00-08
Description	Lost Communication With Serial Data Gateway A CMDTCs
What This Means	Lost communication with gateway module.
Possible Causes	• Network interruption • Gateway module power/ground issue • Damaged CAN wiring • Module unplugged during repair
Recommended Next Steps	• Perform network health check • Inspect gateway module connectors • Verify module communication after repairs
Safety System Impact	Gateway communication issues can prevent ADAS modules from communicating properly.

Recommended Safety System Checks

- Forward camera calibration / camera system verification
- Forward camera calibration may be required
- Network communication verification
- Network communication verification required

- Parking aid system verification may be required
- Post-repair road test and functional validation

Customer Summary

Customer Note:

This report explains the fault codes found during the scan in easier-to-understand language. Some systems may affect safety features such as cameras, parking sensors, blind spot monitoring, steering assist, braking systems, or collision avoidance features. Final repair decisions should be based on proper diagnostics and manufacturer repair procedures.

EXPRESS DIAGNOSTICS — Precision. Safety. Confidence.