



DIAGNOSTIC & ADAS REPORT

EXPRESS DIAGNOSTICS

Vehicle Information

Vehicle	2019 Ford Expedition
VIN	1FMJK2AT9KEA72366
Mileage	122296.46
Scan Date	2026-05-04
Scan Type	Pre & Post Scan
DTCs Found	5

Detected DTCs & Professional Analysis

DTC	U0140:00-08
Description	Lost Communication With Body Control Module CMDTCs
What This Means	Lost communication with the Body Control Module.
Possible Causes	• Low voltage or battery disconnect • CAN network communication issue • Loose, c
Recommended Actions	• Verify battery voltage and charging system • Inspect BCM connectors and grounds
ADAS Impact	May affect communication between ADAS, lighting, body, and safety-related modules.

DTC	B1445:15-48
Description	Rear park lamps output CMDTCs
What This Means	Rear park lamp output circuit fault.
Possible Causes	• Damaged rear lighting circuit • Open or shorted wiring • Corroded connector
Recommended Actions	• Inspect rear lamp wiring and connectors • Check for short/open circuit • Repair da
ADAS Impact	Rear body electrical concerns may require inspection of nearby sensors, harnesses, and pa

DTC	B153E:08-08
Description	Trailer Hitch Light Output CMDTCs
What This Means	Trailer hitch / trailer lighting output fault.
Possible Causes	• Trailer wiring fault • Damaged hitch wiring • Corrosion at trailer connector • S
Recommended Actions	• Inspect trailer connector • Check hitch wiring harness • Test lighting circuits •
ADAS Impact	Rear wiring issues may overlap with parking aid, blind spot, and rear body harness inspection

DTC	B115E:08-08
Description	Camera Module CMDTCs
What This Means	Camera module / image processing system fault.
Possible Causes	• Camera misalignment • Camera calibration lost • Windshield or camera bracket d
Recommended Actions	• Inspect camera mounting and windshield area • Verify camera/module communication
ADAS Impact	Critical ADAS concern. May affect lane keep assist, pre-collision assist, forward collision wa

DTC	U0146:00-08
Description	Lost Communication With Serial Data Gateway A CMDTCs
What This Means	Lost communication with gateway module.
Possible Causes	• Network interruption • Gateway module power/ground issue • Damaged CAN wiri
Recommended Actions	• Perform network health check • Inspect gateway module connectors • Verify mod
ADAS Impact	Gateway communication issues can prevent ADAS modules from communicating properly.

Required / Recommended ADAS Operations

- 1 Forward camera calibration / camera system verification
- 2 Forward camera calibration may be required
- 3 Network communication verification
- 4 Network communication verification required
- 5 Parking aid system verification may be required
- 6 Post-repair road test and functional validation

Disclaimer:

Fault codes and ADAS-related module concerns must be evaluated according to OEM repair procedures. Clearing codes alone does not confirm system integrity. After repairs, affected systems should be verified through post-scan documentation, calibration when required, and functional road testing.

EXPRESS DIAGNOSTICS — Precision. Safety. Confidence.