



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

To:

Simon Barclay
Unit 7, 140 Francis Street
RICHMOND NSW 2753

From:

KLR Automotive ABN 58 633 010 965
6 Sovereign Place
SOUTH WINDSOR, NSW 2756

Vehicle Rego: DGA08D **Invoice Date** 27/11/2023 **Invoice No:** 10323

Payment Terms: COD

TAX INVOICE**Labor:**

	<i>Hours</i>	<i>Rate</i>	<i>Subtotal</i>
Carry out service as required, replaced engine oil and filter, replaced air filter as required.			\$0.00 \$210.00
Faults evident relating to turbo actuator, removed turbocharger, replaced with new turbo, replaced gaskets, primed turbo, reprogrammed using autologic, road tested vehicle, no further faults evident.			\$0.00 \$0.00 \$525.00 \$0.00
Transfer case leaking from intermediate shaft, removed transfer case, stripped transfer case, rebushed transfer case, replaced all bearings, centre diff shims and overhaul as necessary, replaced intermediate shaft, reassembled.			\$0.00 \$0.00 \$0.00 \$1,400.00
removed transmission from vehicle, removed clutch, replaced spigot bush, replaced slave cylinder, fit new HD LOF clutch, refit gearbox to vehicle, filled gearbox with new 75-90 GL4 oil, refit transfer case as required, filled transfer case with new oil.			\$0.00 \$0.00 \$0.00 \$1,400.00
Bled clutch and road tested vehicle, all ok			\$0.00 \$0.00
Install supplied driving lights as required.			\$175.00 \$0.00
Condensor is leaking, removed condensor and replaced with full size aftermarket unit, sublet vehicle for regas, tested operation, all ok.			\$0.00 \$262.50 \$0.00
Hot air blowing through vents even when on cold setting, removed heater tap and replaced with genuine heater tap, bled cooling system, road tested vehicle all ok.			\$0.00 \$0.00 \$175.00
Total			\$4,147.50

Parts:

<i>Part Number</i>	<i>Description</i>	<i>Qty</i>	<i>Per Unit</i>	<i>Subtotal</i>
LR042752	Turbocharger, 2.2 Defender Puma	1	\$1,891.00	\$1,891.00
LR025985	CONDENSER	1	\$600.00	\$600.00
STC3185	BEARING	2	\$31.90	\$63.80
FRC6968	THRUST WASHER, G/BOX TRANSFER DIFF.	4	\$2.73	\$10.92
FRC5564	BEARING, MAINSHAFT, LT230T T/BOX.	2	\$44.00	\$88.00
IED500060	INTERMEDIATE SHAFT, LT230	1	\$89.55	\$89.55
FRC8292	O RING	1	\$1.82	\$1.82
FRC7439	OIL SEAL, O RING	1	\$1.82	\$1.82

Monday, 27 November 2023

Page 1 of 2



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

UYH500020	INTERMEDIATE SHAFT STAKE NUT LT230	1	\$6.55	\$6.55
IYH000030	LT230 CENTRE DIFF STAKE NUT	1	\$18.22	\$18.22
ICV100000	SEAL, TRANSFER MAINSHAFT, LT230T	1	\$15.45	\$15.45
STC1130	BEARING, FRONT/REAR OUTPUT(CENTRE DIFF)	2	\$17.27	\$34.54
FTC4939	SEAL,OIL, TRANSFER BOX	2	\$15.45	\$30.90
606474	LT95 Rear centre diff bearing	1	\$44.55	\$44.55
AAU2304	OIL SEAL HOUSING.	1	\$11.45	\$11.45
NZ606041L	NUT, NYLOC, PROPSHAFT.	16	\$1.61	\$25.76
KQB500550	MOUNT, TD5 GEARBOX -R/H	1	\$53.22	\$53.22
PHE500060	Air Filter, Defender '07>	1	\$24.09	\$24.09
LR030778	Filter, Oil, Duratorq 2.2, Def+FLNDR	1	\$13.55	\$13.55
1013938	PLUG, SUMP & WASHER Puma	1	\$5.80	\$5.80
232039	COPPER WASHER, BREATHER BANJO	2	\$1.70	\$3.40
509045P	PROPSHAFT BOLT 3/8"UNF (DIFF END)	2	\$0.98	\$1.96
599552	LT95/LT230 MAGNETIC DRAIN PLUG	1	\$4.55	\$4.55
LOFCK	Heavy Duty LOF Clutch Kit Puma	1	\$1,460.00	\$1,460.00
LT230-MACH	Machine and bush LT230 case intermediate shaft	1	\$385.00	\$385.00
JQD500080	HEATER WATER CONTROL VALVE, DEF '07>	1	\$281.60	\$281.60
A/C	Regas airconditioning system, inc fluoro dye	1	\$181.81	\$181.81
GL-4	GL-4 Pro Gear 75-90 Penrite	2.5	\$28.00	\$70.00
HPR5	Oil, Penrite HPR5, Semi-Synthetic	6.7	\$16.95	\$113.57
A12-0302	No. 12 3/16 x 1/8BSP Male Branch Tee	1	\$29.46	\$29.46
BP5-0302	PS 3/16 x 1/8BSP Nut & Tail	1	\$5.07	\$5.07
Total				\$5,567.41

Note:

Subtotal	\$9,714.91
GST	\$971.49
Invoice Total	\$10,686.40
Total Payments	
Amount Due	\$10,686.40

Why not pay by phone? We accept most major credit cards - Or - by Direct Deposit To KLR Automotive BSB 012 874 A/C 472434595