

ROLE CARD · QUALITY

Quality

Pages: Quality (NCR / CAR / FAI / Scrap codes) · SPC · Calibration · Traceability. You own the gates the floor runs into — keep them clean and the floor keeps moving.

DAILY LOOP

1	Triage NCRs — kiosk-filed out-of-tolerance NCRs arrive pre-filled (spec, actual, part/lot/serial) in IN PROCESS status.
2	Work the receiving inspection queue: accept or reject with method and notes.
3	Approve labor time entries daily — self-approval is refused. Late approvals erode the floor's trust in the clock.
4	Escalate an NCR to a CAR when the cause is systemic.

OWN THE VOCABULARY AND THE GATES

- Scrap reason codes live on Quality > Scrap tab. Retire codes by making them inactive — never delete. With no active codes the kiosk falls back to a legacy free-text grid.
- Calibration: every gauge must be ACTIVE with a next-calibration date, or every gauge-required step on the floor is refused (fail-closed). Alerts surface 30 days out.
- SPC fills itself from conforming wired measurements. A correction adds a NEW point — it is a time series, not a rewrite.
- FAI prefill-from-steps copies actuals and the measuring device where the characteristic description exactly matches the step label. It never sets conformance — you disposition every characteristic.

WATCH OUT

- TRAP** — Unqualified-operator warnings do NOT block clock-ins — the system records the exception on the audit trail instead of stopping the work. Review those warnings; nothing was prevented.
- TRAP** — You are the custodian of force-complete: the audited steps-gate bypass exists for legacy and paper-evidenced jobs only. Habitual use quietly erodes the AS9100D evidence posture.