AGE 310: Instrumentation and Measurements

Dr. Kadeghe Fue, Department of Agricultural Engineering, SUA

Morogoro, Tanzania

Abstract

This compendium serves as a detailed academic reference for AGE 310. Lecture 1 establishes the foundational definitions, static characteristics, error classification, and the universal structure of measurement systems necessary for modern agricultural engineering practice. The content is tailored to ensure students can translate theoretical knowledge into practical solutions on the *shamba* (farm).

Lecture 1: Foundational Concepts in Measurement

1.1 Definitions and Scope

1.1.1 Instrumentation and Measurement

In the context of Agricultural Engineering, instrumentation is the critical link between the physical world and data-driven decision-making.

Instrumentation: This is the science and technology dealing with the measurement and control of physical variables. It encompasses the design, construction, and operation of instruments used to quantify parameters such as soil moisture, tractor engine power, grain weight, and air temperature.

Measurement: The process of quantitatively comparing an unknown magnitude of a physical quantity (the *measurand*) with a predefined, standardized magnitude of the same quantity.

$$\text{Measurement} = N \times U$$

where N is the numerical value (magnitude) and U is the unit (standard). The unit provides the indispensable context for the numerical value. For example, 5 Litres (Volume of water) is physically meaningful, unlike 5 alone.

1.1.2 The Role in Agricultural Engineering

Measurement is the cornerstone of Precision Agriculture (PA). Our ability to optimize resource use relies entirely on accurate data.

- **Resource Management:** Measuring soil pH, Electrical Conductivity (EC), and nutrient levels to apply fertilizer (e.g., urea) only where required, thus optimizing inputs and reducing waste.
- **Process Control:** In food processing plants or automated greenhouses, continuous temperature or humidity measurement drives actuators (heaters, fans) via a feedback loop.
- **Testing and Evaluation:** Measuring the drawbar pull, fuel consumption, and slip of tractors during official performance tests. This ensures the equipment is appropriate for Tanzanian conditions.

1.2 The Generalized Measurement System (GMS)

Every measurement instrument, regardless of complexity (from a simple ruler to a modern automated weather station), can be broken down into three functional elements operating sequentially.

1. **Primary Sensing/Detection Stage**
2. **Signal Conditioning/Manipulation Stage**
3. **Data Presentation/Termination Stage**

1.2.1 Stage 1: The Primary Sensing Element (Detector)

This element is in direct contact with the measurand. It absorbs energy from the measurand and converts it into an energy form usable by the next stage (often mechanical or electrical).

- **Example:** The glass bulb and mercury column of a thermometer (thermal energy converted to volume expansion).
- **Example:** The diaphragm of a pressure gauge (force converted to displacement).

The **Transducer** function is often combined here, converting the sensed energy into an electrical signal (e.g., a thermistor converting temperature change into resistance change).

1.2.2 Stage 2: Signal Conditioning

The raw signal from the sensing element is often weak (e.g., microvolts from a thermocouple) or unsuitable (e.g., resistance) for direct use. This stage modifies, amplifies, or converts the signal.

- **Amplification:** Increasing the signal amplitude (e.g., using an Op-Amp to boost a strain gauge signal from mV to V).
- **Filtering:** Removing unwanted noise (e.g., a low-pass filter removing high-frequency electrical interference).
- **Conversion:** Changing the signal type (e.g., an Analog-to-Digital Converter (ADC) translating continuous voltage into discrete binary code for a microcontroller).

1.2.3 Stage 3: Data Presentation/Termination

The final element where the measured variable is communicated to the human operator or fed into a control system.

- **Indicators:** Analog (pointer on a dial) or Digital (LCD screen).
- **Recorders/Loggers:** Hard drives, SD cards, or computer databases storing the time-stamped data.
- **Control Elements:** Sending the signal to an actuator (e.g., a solenoid valve) to implement a change based on the measurement.

1.3 Static Performance Characteristics

These describe the instrument's performance when the input is unchanging (static). They are crucial for assessing the quality of a measurement.

1.3.1 Accuracy and Precision

Accuracy: The closeness of the measured value to the true value. High accuracy implies a low systematic error. **Precision (Repeatability):** The closeness of agreement among independent measurements obtained under the same conditions. High precision implies low random error.

An instrument can be highly precise (all readings clustered tightly) but inaccurate (clustered far from the true value).

[Image of Target Diagram illustrating Accuracy vs Precision]

Static Error (e): The difference between the measured value (V_m) and the true value (V_t).

$$e = V_m - V_t$$

Relative Error (e_r): Often expressed as a percentage.

$$e_r = \frac{V_m - V_t}{V_t} \times 100\%$$

1.3.2 Sensitivity

Sensitivity (S) is the ratio of the change in output signal (ΔO) to the change in the measured quantity (ΔI). It defines how much the output moves for a given change in input.

$$S = \frac{\Delta O}{\Delta I} = \frac{\text{Output units}}{\text{Input units}}$$

A high sensitivity instrument can detect smaller changes in the measurand. For example, a flow meter with a sensitivity of 5 mV/LPM (Litres per Minute) is more sensitive than one with 1 mV/LPM.

Calculation Example 1: Sensitivity

A thermistor measures temperature in a grain silo. At $20°$C, its resistance is 10 kΩ. At $30°$C, its resistance is 5 kΩ. Calculate its average sensitivity over this range.

Solution:

- Change in Output (ΔO): 5 k$\Omega - 10$ k$\Omega = -5$ kΩ
- Change in Input (ΔI): $30°$C $- 20°$C $= 10°$C
- Sensitivity (S):

$$S = \frac{\Delta O}{\Delta I} = \frac{-5 \text{ k}\Omega}{10°\text{C}} = -0.5 \text{ k}\Omega/°\text{C}$$

The negative sign indicates a Negative Temperature Coefficient (NTC).

1.3.3 Resolution and Threshold

Resolution: The smallest change in the input quantity that can be detected reliably by the instrument. A digital thermometer displaying tenths of a degree (0.1°C) has a resolution of 0.1°C.

Threshold: The minimum value of the input necessary to cause a detectable change from zero output. If a low-cost pH meter does not register any reading until the solution reaches pH3.5, the threshold is pH3.5.

1.3.4 Drift, Hysteresis, and Linearity

Drift: A gradual change in the instrument's reading over time, independent of the measurand, typically caused by aging, temperature variation, or power supply fluctuations.

Hysteresis: The difference in output for a given input when the input is approached from two different directions (increasing vs. decreasing). For instance, a pressure gauge might read 100 kPa when pressure is rising, but 98 kPa when pressure is falling, at the true value of 99 kPa.

Linearity: The degree to which the calibration curve (Output vs. Input) deviates from a perfect straight line. High linearity is desired because it simplifies the signal conditioning stage.

Calculation Example 2: Hysteresis

A force sensor (Load Cell) is calibrated for a maximum range of 0 to 500 N. During testing, the output voltage is 2.0 V when the load increases to 250 N, but 1.95 V when the load decreases back to 250 N. The full scale output (FSO) is 5.0 V.

Calculate the Hysteresis as a percentage of the Full Scale Output (FSO).

Solution:

- Hysteresis Value (Hyst): $\text{Reading}_{\text{rising}} - \text{Reading}_{\text{falling}} = 2.0 \text{ V} - 1.95 \text{ V} = 0.05 \text{ V}$
- Hysteresis (% of FSO):

$$H\% = \frac{\text{Hysteresis Value}}{\text{FSO}} \times 100\% = \frac{0.05 \text{ V}}{5.0 \text{ V}} \times 100\% = 1.0\%$$

A 1.0% hysteresis is significant and indicates potential internal mechanical friction within the load cell mechanism.

1.4 Errors in Measurement

Understanding errors is vital because no measurement is perfect. Errors determine the final uncertainty of the data we collect.

1.4.1 Classification of Errors

A. Gross Errors (Human Mistakes) These are mainly due to human carelessness or lack of training.

- **Example:** Misreading the scale of an analog voltmeter (e.g., reading 22 V instead of 2.2 V).
- **Example:** Improper equipment handling or calculation mistakes (e.g., using $\pi = 3.14$ when greater precision is needed).
- **Mitigation:** Proper training, using checklists, and taking multiple independent readings (e.g., two students reading the same manometer).

B. Systematic Errors (Bias) These errors are consistent and repeatable. They introduce a fixed bias and are caused by known factors.

1. **Instrumental Errors:** Faults inherent in the device itself.
    - *Zero Error/Bias:* The instrument does not read zero when the measurand is zero.
    - *Defective Parts:* Frayed wires introducing unexpected resistance.
    - *Loading Effect:* Connecting a low-impedance measuring device changes the quantity being measured (e.g., a voltmeter drawing current from a circuit).
2. **Environmental Errors:** External conditions affect the instrument.
    - *Temperature:* Sensor resistance changes due to ambient heat, not the measurand.
    - *Humidity:* Moisture absorption affects dielectric sensors.
    - *Vibration:* Mechanical interference affecting sensitive balances.
3. **Observational Errors:** Systematic human faults (e.g., Parallax error when viewing a pointer from an angle).
4. **Mitigation: Calibration** is the primary method to reduce systematic error.

C. Random Errors These are unpredictable variations that remain after all systematic and gross errors have been accounted for. They are usually caused by microscopic fluctuations in environmental conditions or noise in the electrical components.

- **Mitigation:** Statistical methods, such as taking a large number of readings and averaging the result, are used to minimize the effect of random errors.

1.5 Calibration and Standards

Calibration is the process that ensures our measurements are meaningful and traceable back to an accepted standard. This is the ultimate tool for mitigating systematic errors.

1.5.1 The Calibration Process

Calibration involves comparing an instrument's output against a reference standard of known accuracy across the instrument's entire operating range.

1. The instrument is subjected to a known input (x).
2. The output (y) is recorded.
3. The output (y) is plotted against the input (x).
4. A straight line (or curve) of best fit is determined.
5. Any deviation from the ideal straight line reveals the instrument's error curve.

1.5.2 Traceability and Standards Hierarchy (Tanzania Context)

All standards must be traceable back to the International System of Units (SI).

1. **International Standards:** Maintained by organizations like the BIPM.
2. **Primary Standards:** Maintained by the TBS (Tanzania Bureau of Standards). These are highly accurate, laboratory-grade standards used only to check Secondary Standards.
3. **Secondary Standards:** Used by calibration laboratories and specialized institutions (like the SUA Metrology Lab) to calibrate Working Standards.
4. **Working Standards:** The standards used routinely in the workshop or field for day-to-day checking of instruments.

Traceability means that a chain of accurate comparisons links the measurement made on your *shamba* to the SI unit definitions.

Calculation Example 3: Calibration and Correction

A pressure gauge is used to measure the pressure in a sprayer tank. The calibration reference (Primary Standard) shows the true pressure is 200 kPa. The reading from the sprayer gauge is 205 kPa.

1. Calculate the absolute systematic error.
2. Determine the required correction factor.

Solution:

1. Absolute Systematic Error (e):

$$e = V_m - V_t = 205 \text{ kPa} - 200 \text{ kPa} = +5 \text{ kPa}$$

The gauge reads 5 kPa too high (Positive bias).

2. Correction Factor (C): This must be added to the measured value to get the true value.

$$C = -e = -5 \text{ kPa}$$

If the operator applies this correction, a measured reading of 210 kPa would be corrected to 210 kPa $- 5$ kPa $= 205$ kPa.

1.6 Summary of Key Terms (Swahili/Context)

- **Measurand:** Kitu kinachopimwa (The quantity being measured).
- **Calibration:** Kurekebisha kifaa (Adjusting the instrument to match a known standard).
- **Precision:** Usahihi wa marudio (How close repeated readings are to each other).
- **Accuracy:** Karibu na thamani halisi (Closeness to the true value).
- **Hysteresis:** Tofauti ya usomaji kutokana na mwelekeo (The path dependency of a reading).
- **TBS:** Shirika la Viwango Tanzania (Tanzania Bureau of Standards - national metrology institute).

Lecture 1: Review Questions

SECTION A: Basic Concepts (5 Questions)

1. Define Instrumentation and explain its primary goal within the context of SUA's agricultural research projects.
2. List and briefly explain the three main functional elements of the Generalized Measurement System (GMS).
3. Differentiate clearly between Accuracy and Precision, providing a practical example relevant to weighing sacks of maize on a farm scale.
4. Define the terms *Resolution* and *Threshold* as they apply to a digital soil pH meter.
5. Provide two examples of *Gross Errors* that can occur when an agricultural engineer uses an analog flow meter to measure irrigation water.

SECTION B: Advanced Analysis and Calculations (10 Questions)

6. **Sensitivity Calculation:** A temperature sensor changes its output voltage from 150 mV to 250 mV when the temperature in a chicken incubator increases from 30°C to 35°C. Calculate the average sensitivity of the sensor in mV$/^{\circ}$C and explain if this sensor is suitable for measuring temperature with a required resolution of 0.05°C.
7. **Hysteresis Analysis:** A pressure transducer with a Full Scale Output (FSO) of 10 V exhibits a 0.08 V difference in output when measured at 50% of its capacity during increasing and decreasing cycles. Calculate the Hysteresis as a percentage of the FSO. Explain the physical cause of this error in mechanical sensors.
8. **Systematic Error and Correction:** The TBS calibrated an instrument and found the true value of moisture content was 18.5%. The instrument consistently read 19.2%.
   - Calculate the absolute systematic error.
   - What is the correction factor that must be applied to all future readings?
   - Calculate the relative error in percentage.
9. **Systemic Error Classification:** An engineer notices that an electronic weighing scale reads consistently 2 kg too high when the ambient temperature is above 35°C, but reads correctly below 30°C. Classify the type of error and suggest a primary method (other than calibration) to mitigate this issue.
10. **Traceability and Standards:** Explain the necessity of the standards hierarchy in the Tanzanian context. If a farmer's scale is certified by TBS, to which international body is the measurement ultimately traceable?
11. **GMS Block Function:** In a modern automated poultry house, identify the component in the GMS that performs the following functions:
    - Senses the ammonia level in the air.
    - Boosts the weak electrical signal from the sensor.
    - Turns on the exhaust fan.

12. **Unit Conversion and Error:** A student measures a distance of 1.5 km but mistakenly uses a measuring wheel that is 2% oversized. Calculate the actual distance measured and the absolute error in meters.

13. **Signal-to-Noise Ratio (SNR) Concept:** Briefly explain why a low SNR makes measurement difficult. Which stage of the GMS is primarily responsible for improving the SNR?

14. **Drift vs. Systematic Error:** Differentiate between *Drift* and a *Systematic Error*. If a sensor's output gradually decreases over a month, what is the most likely cause, and how would you verify it?

15. **Zero Order Idealization:** Explain why a simple potentiometer is considered a Zero Order instrument. What factors are ignored in this idealization that would cause it to display minor lag in a real-world high-speed application?