

Click for Information on International Mail Service


Kits and Parts dot Com

Supplying Toroids, Electronic Parts and Kits to Engineers, Schools and Hobbyists

Home
Create Quote
Place Order
Customer Portal
Trimmer Capacitors
NPO Disc Capacitors
Polystyrene Capacitors
Silvered Mica Capacitors
Crystals - Matched
W3NQN Filters
WA2EBY Toroid Kit
Variable Inductors
Magnet Wire
Diodes
Integrated Circuits
Jacks Plugs
Transistors - Fets
Misc Parts
RFtoolkits
Organic 5Watter Kits
Transceivers for 17,20,30,40 Meters
Toroids
Retired Kits
SMT Parts
Contact
FAQ


Build this Universal SWR bridge V1.5
Note that there are many FAKE versions on Ebay.



[PDF Instructions in Spanish submitted of Jon, EA2SN](#)



T1,2 = FT-50-43_10T:1T

QRP SWR Bridge for 1.8-30 MHz		
Kits And Parts Dot Com		
by W8DIZ	Rev 1.4	29 Oct 2018





Building Instructions:

1. Inventory all Parts

2. Install all Resistors.

___ R1,2: 51 (1/2 Watt) Green-Brown-Black-Gold

Note: R3,4 controls the output of the SWR bridge.

___ R3,4: 50K ohm pot

3. Install all capacitors.

___ C1,2,3,4: SMT or 100n brown labeled 104 or green 104

We highly recommend installing the SMT caps vs the thru hole types

The SMT caps provide better RF shunting to ground

4. Install the detector Diodes.

___ D1,2: 1N5711 - install flush against PCB per parts markings

Do not overheat when soldering.

5. Wind and install the RF coupling transformers.

___ T1 & T2: Wind 10/12 turns of 26 ga red or green wire on both FT50-43 ferrite toroids.

For 3.5 - 30 MHz, use 10 turns (more sensitive at low power)

For 1.8 - 30 MHz, use 12 turns (less sensitive at low power)

Cut the 20 inches of red magnet wire in half.

Wind the wires (10" each) on the toroids **clockwise**.

Trim the wires of T1 & T2 to a half inch.

Strip the insulation off the wires using a very hot solder pencil and solder.

Install the wound toroids on the PCB and trim leads from the PCB.



Cut the 2 inches of #20 green magnet wire in half.
Earlier versions of the SWR kit use surplus resistor leads.
Strip the insulation off of 0.25 inches (6.3 mm) on all 4 ends of the wires
Bend the wires in a "U" shape using a standard size pencil.
Install the leads thru T1 & T2 with the wire going thru the center of the toroid
Solder the leads on the bottom of the PCB.

6. Connections.

Connect the bridge to a 5W RF source(in) and a 50 ohm dummy load(out).
Connect two mechanical meters to J1 or one meter with a SPDT switch.
Suggest using 50 uA, up to 2 mA mechanical meters.
Note: Meters are NOT supplied in the kit.
Adjust both R3 & R4 to mid-range.
Apply 5 Watts and adjust R4 for a full scale reading.
Reverse the RF connections so that the dummy load is at the input.
Apply 5 Watts and adjust R3 for a full scale reading.
The SWR Meter is now ready to use (5 watts full scale).
Designed for a maximum of 100 Watts (intermittent).