

3D Panel Installation Manual

KESTREL WELDED MESH 3D fencing system — assembly instructions

DOCUMENT NO. KM-IG-001	CREW 2 persons · standard tools	EST. SPEED 25–40 m/day
---------------------------	------------------------------------	---------------------------

1. Tools Required

String line · spirit level · post driver or auger Ø120 mm · torque wrench (13 mm socket) · rubber mallet · concrete mixer · tape measure.

2. Site Layout

- 1 Establish fence line with string; mark post centers at **2,030 mm ± 10 mm** (single panel module).
- 2 Verify underground utilities before any excavation.
- 3 Set corner and gate posts first; run string between them at top and 200 mm above ground.

3. Post Installation

- 4 Drill / drive posts plumb. Foundation: see KM-CAD-002 Post Foundation Details for depth by height and wind zone.
- 5 Concrete (C20/25) tamped in layers; slope top of concrete away from post for water run-off.
- 6 Cure minimum 24 h (48 h below 5 °C) before hanging panels.

4. Panel Fixing

- 7 Hook panel onto post bracket rail — security clips face **outward** (attack side).
- 8 Fix with anti-vandal Torx M8 security bolts: washer face down, torque to **25–30 N·m**. Never power-drive to full torque.
- 9 Maintain ground clearance 30–50 mm; panels must overlap post bracket fully.

5. Gates & Completion

Hang gates after panel lines are complete; adjust hinges for 5 mm drop clearance. Final check: every 10th bolt torque-verified, line straightness ≤ 10 mm over 10 m.

Safety: wear gloves and eye protection when handling cut wire ends. Panels > 2.4 m must be lifted by two persons.