

Report Details

Report ID	FR-2026-001
Location	Mission - 2847 Mission St
Machine	CBM-003 Siemens EQ.9 Plus Connect
Serial No	SIE-EQ9-20191110-003
Date	2026-07-18
Reported by	Sara M. (Location Manager)

Brew Pressure - Last 5 Readings



Fault Description

Fault code E-07 (Pressure Sensor Fault) has triggered three times in 18 days. Events on 2026-07-01, 2026-07-10, and 2026-07-18. The first two were resolved by TECH-01 but the fault recurred each time. The machine is still operational but pulling shots at 7.5-8.2 bar versus the normal 9.0 bar. Roughly 20% of espresso shots were rejected during fault windows. Customer complaints were logged on 12 Jul and 17 Jul.

Requested Action / Technician Notes

- Urgent inspection required - fault is escalating, not stabilising.
- Likely root cause: worn pump assembly or cracked pressure line.
- Parts anticipated: pump assembly (SIE-EQ9-PUMP-003), pressure line kit (SIE-EQ9-PL-KIT).
- Previous pressure transducer replacements (2 Jul, 11 Jul) did NOT resolve the fault.
- Contact: sara.m@sunnybayroastery.com | +1-415-555-0103