

Report Details

Report ID	FR-2026-005 (Supplement to FR-2026-001)
Location	Mission - 2847 Mission St
Machine	CBM-003 Siemens EQ.9 Plus Connect
Serial No	SIE-EQ9-20191110-003
Fault Code	E-07 (Pressure Sensor Fault)
Date	2026-07-19
Reported by	TECH-01 (Field Technician)

Pressure Readings - 30 Day Log



Technician Assessment

Fault code E-07 (Pressure Sensor Fault) remains unresolved. The pressure transducer was replaced twice (2 Jul, 11 Jul) and the fault persists. The pattern indicates a worn pump or a cracked pressure line upstream of the transducer, not the sensor itself.

Parts to Order / Escalation

- Pump assembly: SIE-EQ9-PUMP-003
- Pressure line kit: SIE-EQ9-PL-KIT
- Estimated repair time: 2 hours on-site.
- Escalate to senior technician - this is now the top-priority machine in the fleet.