

Sunny Bay Roastery - Fault Report

Report Details

Report ID:	FR-2026-001
Location:	Mission District - 2847 Mission St
Machine:	CBM-003 Siemens EQ.9 Plus Connect
Serial No:	SIE-EQ9-20191110-003
Date:	2026-07-18
Reported by:	Sara M. (Location Manager)
Priority:	HIGH - Urgent

Fault Description

Fault code E-07 (Pressure Sensor Fault) has triggered three times in 18 days. Events on 2026-07-01, 2026-07-10, and 2026-07-18. First two resolved by TECH-01 but fault recurred each time. Machine still operational but pulling shots at 7.5-8.2 bar vs normal 9.0 bar. ~20% of espresso shots rejected during fault windows. Customer complaints logged on 12 Jul and 17 Jul.

Requested Action / Technician Notes

Urgent inspection required. Likely root causes: worn pump assembly or cracked pressure line. Parts anticipated: pump assembly (SIE-EQ9-PUMP-003), pressure line kit (SIE-EQ9-PL-KIT). Previous pressure transducer replacements (2 Jul, 11 Jul) did not resolve the fault.

Contact: sara.m@sunnybayroastery.com | +1-415-555-0103