

Sunny Bay Roastery - Fault Report

Report Details

Report ID:	FR-2026-005 (Supplement to FR-2026-001)
Location:	Mission District - 2847 Mission St
Machine:	CBM-003
Serial No:	SIE-EQ9-20191110-003
Date:	2026-07-19
Reported by:	TECH-01 (Field Technician)
Priority:	HIGH - Escalation

Fault Description

Pressure readings log (last 30 days):

- 2026-06-19: 9.0 bar - normal
- 2026-06-25: 8.8 bar - slightly low
- 2026-07-01: 7.9 bar - E-07 triggered
- 2026-07-08: 9.1 bar - post-repair
- 2026-07-10: 7.8 bar - E-07 triggered
- 2026-07-15: 8.9 bar - post-repair
- 2026-07-18: 7.5 bar - E-07 triggered (unresolved)

Requested Action / Technician Notes

Pressure transducer replaced twice (2 Jul, 11 Jul) - fault persists. Pattern indicates worn pump or cracked pressure line upstream of transducer.

- Parts to order:
- Pump assembly: SIE-EQ9-PUMP-003
 - Pressure line kit: SIE-EQ9-PL-KIT

Estimated repair time: 2 hours on-site. Escalate to senior technician.