

## Check the sensor and replace, if it's not working

### Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

Loose connection in AN1 to AN13 will cause this warning.

Check F38 (Pin 1 and 2) in AN1 to AN13 panel (X01 Pin 1 and 2) connector for supply cable continuity. Check continuity between F40 (pin 17) in AN1 to X01 pin No 17 at AN13 panel

The defect sensor or damaged cable will trigger this warning. Check and replace the sensor.

Relevant spare parts	
Description	Item No.
PROXI SWITCH I1808PPOS1531 18	<a href="#">60009270</a>