SERVICE BULLETIN

NUMBER: 07-003-13

GROUP: Cooling

DATE: September 04, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:
Accessory Drive Belt Noise

OVERVIEW:
This bulletin involves the installation of a revised serpentine drive belt that is able to compensate for slight pulley misalignment.

MODELS:

2009 - 2013	(DS)	Ram 1500
2009	(DH)	Ram 2500
2010 - 2013	(DJ)	Ram 2500
2009	(D1)	Ram 3500
2013	(D2)	Ram 3500
2009	(DC)	Ram 3500 Cab Chassis
2010 - 2013	(DD)	Ram 3500 Cab Chassis

NOTE: This bulletin applies to vehicles equipped with a 5.7L engine (sales code EZH, EZC, EZD, EZE or EZC) built on or before November 20, 2012 (MDH 1120XX).

SYMPTOM/CONDITION:
The customer may experience a belt chirp type noise from the engine compartment.

DIAGNOSIS:
If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68204819AA	Belt, Serpentine Drive

REPAIR PROCEDURE:
1. Remove the serpentine belt. Refer to the detailed removal procedure available in DealerConnect> TechConnect under : Service Info> Cooling> Accessory Drive> Belt, Serpentine> Removal. Operate the engine with the belt removed for a period of no more than 15 seconds. Was the noise eliminated?

a. Yes >>> Continue to Step 2.
b. No >>> This bulletin does not apply, further diagnosis is required.

2. Visually inspect all accessory drive pulleys to ensure there is no damage, corrosion or debris present. If any of these conditions are found, repair as necessary before proceeding.
3. Install revised serpentine belt p/n 68204819AA. Refer to the detailed installation procedure available in DealerConnect> TechConnect under: Service Info> Cooling> Accessory Drive> Belt, Serpentine> Installation.
4. Operate engine and verify the noise is no longer present. Was the noise eliminated?
   a. Yes >>> Repair is complete.
   b. No >>> Further diagnosis is required.

POLICY:
Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
07-20-17-90	Belt, Serpentine Drive - Replace (0 - Introduction)	1- Engine Repair	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action