

Northstar Knitwear & Apparels Pvt. Ltd.

Quality Inspection Report

Reporting Period: August 2026

Document No.: NSK/QC/QIR/2026-08

Prepared by: Quality Assurance Reviewed by: Quality Manager

Control	Details
Inspection Period	August 2026
Lots Inspected	186
Final Inspection Pass	96.4%
Major Defect Rate	1.1%
Recurring Defects	Skipped stitch, open seam, shade variation
Status	Amber

1. Buyer / Article Quality Summary

Buyer	Article	Checked	Passed	Rejected	Reject %	Main Defect
Arvind	ARV-HENLEY-26	2,400	2,324	76	3.2%	Skipped stitch
LPP	LPP-SWEAT-26	1,800	1,746	54	3.0%	Open seam
Decathlon	DEC-JOG-26	2,200	2,168	32	1.5%	Measurement
M&S	MNS-POLO-26	2,100	2,072	28	1.3%	Shade
Reliance	RT-TEE-26	2,600	2,568	32	1.2%	Print placement
Monte Carlo	MC-HOOD-26	1,500	1,476	24	1.6%	Puckering

2. Defect Pareto

Defect	Occurrences	Share	Department	Trend	Action
Skipped stitch	184	24%	Stitching	Increasing	Needle/thread checks
Open seam	146	19%	Stitching	Stable	SPI/seam audit
Shade variation	108	14%	Fabric/Finishing	Increasing	Lot segregation
Measurement out	96	13%	Finishing	Stable	Hourly measurement
Print placement	74	10%	Printing	Improving	Template control
Oil/soil mark	58	8%	Stitching	Stable	Machine cleaning
Puckering	51	7%	Stitching	Stable	Tension setting

3. Inline Inspection

Line	Article	Checked	Major	Minor	First Pass	Remarks
L1	Basic Tee	1,200	8	42	95.8%	Needle break marks
L2	Polo	1,150	5	31	96.9%	Good
L3	Jogger	1,100	7	28	96.8%	Waistband tension
L4	Hoodie	980	14	57	92.8%	Open seam/puckering
L5	Ladies Top	1,250	4	22	97.9%	Best line
L6	Kidswear	1,020	9	35	95.7%	Measurement drift

4. Final Inspection Exceptions

Report	Buyer	Article	Defect	Disposition	Owner
FI-260812	Arvind	Henley	Skipped stitch at armhole	100% recheck + repair	Line 1
FI-260821	LPP	Sweatshirt	Open seam at cuff	Rework 54 pcs	Line 4
FI-260826	M&S	Polo	Shade mismatch by panel	Segregate + approval	Finishing
FI-260829	Reliance	Tee	Print 4 mm off-center	Reprint 32 pcs	Printing

5. Corrective Action Reports

CAR	Issue	Root Cause	Corrective Action	Due	Status
CAR-0826-04	Skipped stitch	Needle condition/speed	Needle change frequency + speed limit	03-Sep	Open
CAR-0826-05	Open seam	Low seam allowance	Operation bulletin + SPI check	02-Sep	Open
CAR-0826-06	Shade variation	Mixed dye lots	Lot-wise cutting/bundle segregation	01-Sep	Open
CAR-0826-07	Puckering	Tension setting	Machine setting sheet	05-Sep	Open

6. Audit Checks

Check	Target	Actual	Finding	Action
Measurement system	100% calibrated	100%	No issue	Continue
Needle policy	100% record	96%	4 records missing	Supervisor sign-off
Shade segregation	100% lots	92%	Mixed lot in L4	Retrain
AQL final audit	Buyer standard	Compliant	No major breach	Continue
Metal detection	100% applicable	100%	Pass	Continue

7. Management Observation

Defects are concentrated in sewing operations rather than spread across the factory. Line 4 requires joint Quality and IE intervention. Increasing final inspection alone will not address the capacity loss created by rework.

8. Action Plan

- Start-of-shift first-piece approval for every active style.
- Hourly checks on armhole, cuff and waistband critical operations.
- Prohibit dye-lot mixing unless QA and Merchandising approve.
- Track repair hours separately from production hours.
- Review recurring defects at the daily production meeting.

9. Sign-off / Follow-up

Function	Responsible Role	Status
Quality	Quality Manager	Reviewed
Production	Production Head	Actions accepted
Merchandising	Merchandising Manager	Buyer communication ongoing
IE	IE Manager	Line 4 study scheduled
Factory	Factory Manager	Weekly monitoring