

WORK ORDER CLOSEOUT FORM

Work Order No: WO-2025-0631

Asset Tag EQ-101 (Feed Pump A)	Date Opened / Closed 15-May-2025 / 18-May-2025
Failure Code MECH-SEAL-FAIL	Technician Suresh Yadav

Failure Description

Mechanical seal failure, preceded by rising vibration and bearing housing temperature over approximately 30 days. Pattern consistent with thermal cycling wear mode described in OEM manual FP-MAN-EQ1XX-SEAL.

Parts Used

Part Number FSL-2240A	Note Superseded part -- current spec is FSL-2240B per FP-SB-2025-04 (issued 15-Jan-2025)
---------------------------------	--

Operational Verification Performed (technician attestation)

Ran equipment for 30 minutes at design load following reassembly. No abnormal noise, temperature excursion, or vibration observed during test run. Return to service approved.

Root Cause

Thermal cycling wear on mechanical seal faces, consistent with the failure mode addressed by the superseded seal specification.

Sign-Off

Technician Suresh Yadav (signed 18-May-2025)	Reviewed By Ananya Iyer, Reliability Engineer
--	---