

FISCHER PUMPS LTD. - SERVICE BULLETIN

Document FP-SB-2026-22 | Issued 20-Aug-2026 | Supplementary to FP-SB-2025-04

Bulletin reference:	FP-SB-2026-22
Issue date:	20-Aug-2026
Applies to:	EQ-103
Equipment class:	Centrifugal Feed Pump
Component:	FSL-2240B
Classification:	Advisory - recommended practice
Supersedes:	None. Supplements FP-SB-2025-04, which remains in force.

1. PURPOSE

This bulletin issues supplementary maintenance guidance for EQ-103. It does not revise any part number, material or rating published in FP-SB-2025-04, which remains the controlling document.

2. RECOMMENDED COUPLING ALIGNMENT TOLERANCE

For EQ-103, Fischer Pumps Ltd. recommends a coupling alignment tolerance of 0.05 mm parallel offset. Angular misalignment is not to exceed 0.03 mm per 100 mm of coupling diameter.

3. COLD ALIGNMENT CHECK INTERVAL

Cold alignment check interval for EQ-103 is specified as 12 months. Values beyond 18 months are outside the qualified range and are the most common installation defect reported to service centres.

4. ACTION REQUIRED

Site reliability engineering to align planned maintenance for EQ-103 with Section 2 at the next scheduling review. No immediate shutdown action is required.