

MERIDIAN HEAT TRANSFER SYSTEMS - SERVICE BULLETIN

Document MHT-PB-2026-23 | Issued 20-Aug-2026 | Supplementary to MHT-PB-2026-11

Bulletin reference:	MHT-PB-2026-23
Issue date:	20-Aug-2026
Applies to:	HE-301
Equipment class:	Shell and Tube Heat Exchanger
Component:	HE-3xx series
Classification:	Advisory - recommended practice
Supersedes:	None. Supplements MHT-PB-2026-11, which remains in force.

1. PURPOSE

This bulletin issues supplementary maintenance guidance for HE-301. It does not revise any part number, material or rating published in MHT-PB-2026-11, which remains the controlling document.

2. RECOMMENDED TUBE BUNDLE CLEANING INTERVAL

For HE-301, Meridian Heat Transfer Systems recommends a tube bundle cleaning interval of 18 months. Interval shortens to 12 months where fouling factor exceeds 0.0004 m²K/W.

3. CHANNEL COVER BOLT TORQUE

Channel cover bolt torque for HE-301 is specified as 210 N-m. Values beyond 240 N-m are outside the qualified range and are the most common installation defect reported to service centres.

4. ACTION REQUIRED

Site reliability engineering to align planned maintenance for HE-301 with Section 2 at the next scheduling review. No immediate shutdown action is required.