

MERIDIAN HEAT TRANSFER SYSTEMS - SERVICE BULLETIN

Document MHT-PB-2026-24 | Issued 20-Aug-2026 | Supplementary to MHT-PB-2026-11

Bulletin reference:	MHT-PB-2026-24
Issue date:	20-Aug-2026
Applies to:	HE-302
Equipment class:	Shell and Tube Heat Exchanger
Component:	HE-3xx series
Classification:	Advisory - recommended practice
Supersedes:	None. Supplements MHT-PB-2026-11, which remains in force.

1. PURPOSE

This bulletin issues supplementary maintenance guidance for HE-302. It does not revise any part number, material or rating published in MHT-PB-2026-11, which remains the controlling document.

2. RECOMMENDED SHELL-SIDE GASKET REPLACEMENT INTERVAL

For HE-302, Meridian Heat Transfer Systems recommends a shell-side gasket replacement interval of every second opening. Spiral wound gaskets are single use and are not to be re-seated once compressed.

3. GASKET SEATING STRESS

Gasket seating stress for HE-302 is specified as 55 MPa. Values beyond 70 MPa are outside the qualified range and are the most common installation defect reported to service centres.

4. ACTION REQUIRED

Site reliability engineering to align planned maintenance for HE-302 with Section 2 at the next scheduling review. No immediate shutdown action is required.