

期間 Date 2019/1/22

出張者 Name Mr Siva

添付資料 Attachment 有 Yes 無 No

同行者 Colleuge Mr Izumo

MM-IN-RD-9100-P06-04 Rev.2

出張先 Customer	Samsung Philipines (SEMPHIL)	相手先 面談者 Attendance	Ms Sunshine – Purchaing Engineer Mr Byunghun Kim – Engineer Mr Ichiro Tanaka – Snr Manager Mr Jong-in Kim – Purchasing Manager
出張目的 Visit Purpose	☒ RN104PA – Dimension Issue ☒ RN102P – Crack ☐	会議フォローアップ項目 Meeting Follow-Up	☒ As attach in below table ☐ ☐

報告内容 Report

Meeting begin at 9:00AM

Topic #1 : RN104PA

Explained about the differences in MM and SEMPHIL masters. The summary of this differences is the control of master in SEMPHIL. need tobe improved. (Please refer to the attach report for details)

Currently SEMPHIL is doing 100% check for dimension before input in printing process.

Topic #2 : RN102P – Crack

Explained on Maruwa action items

- Reduce slit height
- Eliminate back slit dummy
- Color ratio – improve detection in MM

SEMPHIL is currently carry out 100% crack check with MARKER before input in printing process.

It is observed that the product handling is very weak and explained that the crack occurrence also from SEMPHIL as well MM Action

=> Show MM method of handlig product

=> Audit SEMPHIL process & IQC for mthod of handling

Topic #3 : ON- HOLD disposition with Purchasing

RN104PA –Semphil will rerank and input to their process. (Improve on the Master control in SEMPHIL)

RN102P – Crack

- MM will accept the return of 2000pcs (crack sorting Ng in semphil)
- Samsung need to improve the handling method and will monitor the crack sorting result.
- Current crack soting result is 3% and estimated MM retrun qty is ~ 13kpcs (RM20K)

SEMPHIL FOLLOW UP ACTIVITY

10/7/2019

No	Product	Activity	MM Date	PIC	SEMPHIL Date	PIC
1		To rerun additional 3 ranks to confirm the data and submit to SEMPHIL	15-Jul	Mr Izumo	-	
2	RN104PA - Dimension NG	If result accepted, rerun the ranking for all return goods in MM RANK 85 RANK 96 RANK 74 RANK 86 RANK 95 This product need to ship to SEMPHIL. Total Qty : 8800	19-Jul	Mr Izumo	-	
3	R102P - CRACK	Design control #1 Reduction of slit height - reference to ALT10-4TE Slit height WD reduce 140um => 110u Design Control #2 Eliminate back slit dummy & reduce slit height Handling of product - explain MM control method (VIDEO presentation on product ahndling) Color condition-Increase color density from 50gm => 150/500gm SEMPHIL will do evaluation to confirm which is acceptable QTY : 150gm - 300pcs 500gm - 300pcs	DONE DONE DONE 19-Jul	Mr Izumo Mr Izumo Mr Siva Mr Siva	31-Jul 31-Jul - -	Mr Kim Mr Kim - Mr Kim
4	Purchasing	Wrapping method - Simplified method for easier removal of product 1. Requested to cancel all PO balance MM reply : Cannot cancel because product have produced and need to ship bease from the PO 2. Request to return RN102P - 435kpcs? MM reply - No return accted because the occurence of crack need to be confirm whether it was SEMPHIL or MM 3. Request to return after sorting NG to be return (qty : 2000pcs) MM reply : The 2000pcs accepted to be return but MM will confirm wther need to return or scrap at SEMPHIL. MM also requested to prepare the masterlist of SEMPHIL inventory and indicate clearly the NG qty in detail by carton. Without the data => return is not accepted	Next shipment	Ms Kavitha Mr Siva / Mr Izumo Mr Siva / Mr Izumo Mr Rosli	- - - 16-Jul	Ms Sunshine Ms Sunshine Ms Sunshine
5	AUDIT - RANKING	a. Master reading inconsistent - After master check, value is inconsistent when cross check with other master b. SEMPHIL ranking machine - not consistent on the measurement value c. No product master for confirmation after calibration d. Master prepared with measure scope (measured from top) and ranking machine is camera type (measuring shadow) and thid will definetly have measurement difference	- - - -	Mr Siva / Mr Izumo Mr Siva / Mr Izumo Mr Siva / Mr Izumo Mr Siva / Mr Izumo	- - - -	Mr Byunghun Kim Mr Byunghun Kim Mr Byunghun Kim Mr Byunghun Kim
6	AUDIT IQC	a. Bundle holding => request 100pcs to 50pcs b. Inspection table => No cushion and directly working on stainless steel table MM => shown the method in MM c. Unwrapping => very rough by IQC & printing process d. IQC => product collection from warehouse with big container which can accumulate of 3 layers of product MM => request to change the container which can only accommodate 1 layer of product only e. Bundle colouring method - inspection method	- - - - -	Mr Siva / Mr Izumo Mr Siva / Mr Izumo Mr Siva / Mr Izumo Mr Siva / Mr Izumo Mr Siva / Mr Izumo	- - - - -	Mr Byunghun Kim Mr Byunghun Kim Mr Byunghun Kim Mr Byunghun Kim Mr Byunghun Kim

意見・Opinion

RN 104 – SEMPHIL need to improve the MASTER control

RN102 – SEMPHIL have very weak control for product handling from warehouse to printing process.

SEMPHIL FOLLOW UP ACTIVITY

10/7/2019

No	Product	Activity	MM		SEMPHIL	
			Date	PIC	Date	PIC
1		To rerun additional 3 ranks to confirm the data and submit to SEMPHIL	15-Jul	Mr Izumo	-	
2	RN104PA - Dimension NG	If result accepted, rerun the ranking for all return goods in MM RANK 85 RANK 96 RANK 74 RANK 86 RANK 95 This product need to ship to SEMPHIL Total Qty : 8800	19-Jul	Mr Izumo	-	
3	R102P - CRACK	Design control #1 Reduction of slit height - reference to ALT10-4TE Slit height WD reduce 140um => 110u	DONE	Mr Izumo	31-Jul	Mr Kim
		Design Control #2 Eliminate back slit dummy & reduce slit height	DONE	Mr Izumo	31-Jul	Mr Kim
		Handling of product - explain MM control method (VIDEO presentation on product ahndling)	DONE	Mr Siva	-	-
		Color condition-Increase color density from 50gm => 150/500gm SEMPHIL will do evaluation to confirm which is acceptable QTY : 150gm - 300pcs 500gm - 300pcs	19-Jul	Mr Siva		Mr Kim
		Wrapping method - Simplified method for easier removal of product	Next shipment	Ms Kavitha		
4	Purchasing	1. Requested to cancel all PO balance MM reply : Cannot cancel because product have produced and need to ship bease from the PO		Mr Siva / Mr	-	Ms Sunshine
		2. Request to return RN102P - 435kpcs? MM reply - No return acceted because the occurence of crack need to be confirm whether it was SEMPHIL or MM		Mr Siva / Mr	-	Ms Sunshine
		3. Request to return after sorting NG to be return (qty : 2000pcs) MM reply : The 2000pcs accepted to be return but MM will confirm wther need to return or scrap at SEMPHIL. MM also requested to prepare the masterlist of SEMPHIL inventory and indicate clearly the NG qty in detail by carton. Without the data => return is not accepted		Mr Rosli	16-Jul	Ms Sunshine
5	AUDIT - RANKING	a. Master reading inconsistent - After master check, value is inconsistent when cross check with other master	-	Mr Siva / Mr		Mr Byunghu n Kim
		b. SEMPHIL ranking machine - not consistent on the measurement value	-	Mr Siva / Mr		Mr Byunghu n Kim
		c. No product master for confirmation after calibration	-	Mr Siva / Mr		Mr Byunghu n Kim
		d. Master preparaed with measure scope (measured from top) and ranking machine is camera type (measureing shadow) and thid will definetly have measurement difference	-	Mr Siva / Mr		Mr Byunghu n Kim
6	AUDIT IQC	a. Bundle holding => request 100pcs to 50pcs		Mr Siva / Mr		Mr Byunghu n Kim
		b. Inspection table => No cushion and directly working on stainless steel table MM => shown the method In MM		Mr Siva / Mr		Mr Byunghu n Kim
		c. Unwrapping => very rough by IQC & printing process		Mr Siva / Mr		Mr Byunghu n Kim
		d. IQC => product collection from warehouse with big container which can accumlate of 3 layers of product MM => request to change the container which can only accomodate 1 layer of product only		Mr Siva / Mr Izumo		Mr Byunghu n Kim
		e. Bundle colouring method - Inspection method		Mr Siva / Mr		Mr Byunghu n Kim