

Risk Analysis					
Product	migo	Record ID:	TF-Migo-RA		
Form code:	-	Revision	1.2	Date	01.02.2025
Analysis prepared by	Srdjan Djordjević			Signature	
Approved by:	Michael Lange			Signature	

Revision history table:

Revision	Issue Date	Description	Author
1.0	01.06.2024.	First revision of the form	Srdjan Djordjević
1.1	07.10.2024	Added new components introduced in the version 1.3 of the software, reevaluted risks of all influenced compoents. Added SW-HTM-0071 to SW-HTM-0078	Allan Krogh Jensen
1.2	01.02.2025	Updated members of RM team	Dragan Jovic
1.3	26.06.2025	Updated risk analysis after adding new deployemend methods (multiproduct and multitenant) and fixing bugs in 1.4v version of the software.	Srdjan Djordjević
1.4	26.11.2025	Updated risk analysis after sw change v1.5 (adding camera grouping, improving performance, situp/laydown detection)	Srdjan Djordjević
1.5	15.03.2026	Updated risk analysis after sw change v1.6 (new risks: SW-HTM-0079, SW-HTM-0080, USE-HTM-0042) (updated risks: SW-HTM 0005, SW-HTM-0006)	Srdjan Djordjević
1.6	20.04.2026	Updated risk analysis after sw change v1.6.1 Removed Prometheus, Alart manager and CAdvisor from SOUP sheet (removed risks SO-HTM-0021, SO-HTM-0022, SO-HTM-0023, SO-HTM-0024, SO-HTM-0042, SO-HTM-0043 and SO-HTM-0044)	Srdjan Djordjević

CEO		Michael Lange	Approval of Risk Management Plan (RMP) Approval of Risk Management File (RMF)
RISK MANAGEMENT TEAM			
No	Team Function	Name and surname	Responsibilities
1	CTO	Toni Elias Aoun	Leads the RM Team Establish and maintain risk management activities in compliance with EN ISO 14971:2019. Manages project, keep team members aligned Assuring that all risks are identified, documented and mitigated to an acceptable level Obtaining Management approval for risk management activities Maintaining the Risk Management File (RMF) Tasks and results in department, and preparing input to management review meetings in compliance with SOPs. SME for topics related to the application of the medical device Conduct phase reviews to allow for review of risk management activities Collection of relevant production and post-production information (new or revised standards, regulations or norms, market surveillance, vigilance) and ensuring these are integrated into the risk management file
2	Application expert/SW Engineering	Andreas Duedam Heino Mortensen	SME for product design and development Identification of hazards Evaluation of product-related risks and proposal of risk control options Initiate, maintain and document the hardware risk assessment (Design FMEA) throughout the entire product life cycle Implementation and verification of product risk control measures SME for topics related to the application of the medical device
3	Regulatory consultants	Dragan Jović Srdjan Djordjević	Act as SME for the risk management process (risk analysis methodology and tools) Establishing risk management documentation Identifying the data required for effective review of the (Risk Management File) RMF, collecting summary reports and data from the responsible functions, regulatory body, and customers related to safety segments of medical product. Assuring that all risks are identified, documented and mitigated to an acceptable level
4	Clinical Expert/ External specialist	Cherry Malonzo Marty	Handling clinical studies and clinical evaluation Input into risk analyses (e.g. severity levels, hazard list) Provides scientific specific input Supports device control documentation as required Definition of severities for each identified harm Evaluation of overall residual risk acceptability Risk-benefit analysis Collection of relevant production and post-production information (new scientific publications, new clinical data) and ensuring these are integrated into the risk management file

ISO/TR 24971:2020 - Annex A - Identification of hazards and characteristics related to safety		Input to Risk Analysis? (yes/no)	Performance related hazards	Usability hazards		Information hazards			
				Function	Use error	Labelling	IFU	Warnings	Service and maintenance specification
A2.1 - What is the intended use and how is the medical device to be used? Factors that should be considered include: — what is the medical device's role relative to — diagnosis, prevention, monitoring, treatment or alleviation of disease, — diagnosis, monitoring, treatment or alleviation of or compensation for injury or handicap, — investigation, replacement, modification or support of anatomy or a physiological process, or — control of conception? — what are the indications for use (e.g. patient population, user profile, use environment)? — what are the contra-indications? — does the medical device sustain or support life? — is special intervention necessary in the case of failure of the medical device? — can essential performance be impacted in the event of a security breach (performance degradation or loss of availability)? — can unauthorized access, unauthorized activities, or loss of data affect the medical device safety?	Intended use: "The migo solution is intended to monitor patients admitted to the intensive care unit (ICU)". The migo solution is not intended to be used on minors. The migo solution is not intended to be used outside of the ICU.	Yes			*		*		
A2.2 - Is the medical device intended to be implanted? Factors that should be considered include the location of implantation, the characteristics of the patient population, age, weight, physical activity, the effect of ageing on implant performance, the expected lifetime of the implant, the reversibility of the implantation, whether the implant can be modified or configured while implanted and the access connection to perform this modification or configuration (e.g. physical access point or wireless connection to the implanted medical device).	No, device is software	No							
A2.3 - Is the medical device intended to be in contact with the patient or other persons? Factors that should be considered include the nature of the intended contact, i.e. surface contact, invasive contact, or implantation and, for each, the period and frequency of contact.	No, device is software	No							
A2.4 - What materials or components are utilized in the medical device or are used with, or are in contact with, the medical device? Factors that should be considered include: — compatibility with relevant substances; — compatibility with tissues or body fluids; — whether characteristics relevant to safety are known; — is the medical device manufactured utilizing materials of animal origin?	No, device is software	No							
A2.5 - Is energy delivered to or extracted from the patient? Factors that should be considered include: — the type of energy transferred; — its control, quality, quantity, intensity and duration; — whether energy levels are higher than those currently used for similar medical devices.	No, device is software	No							
A2.6 - Are substances delivered to or extracted from the patient? Factors that should be considered include: — whether the substance is delivered or extracted; — whether it is a single substance or range of substances; — the maximum and minimum transfer rates and control thereof.	No, device is software	No							
A2.7 - Are biological materials processed by the medical device for subsequent re-use, transfusion or transplantation? Factors that should be considered include the type of process and substance(s) processed (e.g. auto-transfusion, dialysis, blood component or cell therapy processing).	No, device is software	No							
A2.8 - Is the medical device supplied sterile or intended to be sterilized by the user, or are other microbiological controls applicable? Factors that should be considered include: — whether the medical device is intended for single use or re-use packaging; — shelf-life issues; — limitation on the number of re-use cycles; — method of product sterilization; — the impact of other sterilization methods not intended by the manufacturer.	No, device is software	No							

A2.9 - Is the medical device intended to be routinely cleaned and disinfected by the user? Factors that should be considered include the types of cleaning or disinfecting agents to be used and any limitations on the number of cleaning cycles. The design of the medical device can influence the effectiveness of routine cleaning and disinfection. In addition, consideration should be given to the effect of cleaning and disinfecting agents on the safety or performance of the medical device.	No, device is software	No							
A2.10 - Does the medical device modify the patient environment? Factors that should be considered include: — temperature; — humidity; — atmospheric gas composition; — pressure; — light.	No, device is software	No							
A2.11 - Are measurements taken? Factors that should be considered include the variables measured and the accuracy and the precision of the measurement results, as well as whether the measurement apparatus or data can be compromised. In addition, the need for calibration and maintenance should be considered (see also A.2.18).	No	No							
A2.12 - Is the medical device interpretative? Factors that should be considered include whether conclusions are presented by the medical device from input or acquired data, the algorithms used, and confidence limits. Special attention should be given to unintended applications of the data or algorithm, as well as unauthorized manipulation or changes to algorithms and data.	Video and alarm from beds are presented via the smartphone.	Yes	*		*				
A2.13 - Is the medical device intended for use in conjunction with other medical devices, medicines or other medical technologies? Factors that should be considered include - identifying any other medical devices, medicines or other medical technologies that can be involved - the potential problems associated with such interactions (such as the medical device impacting the performance of other medical devices) and - whether the patient follows the instructions for the therapy.	Video and alarm from beds are presented via the smartphone. Server application is running on server hardware. Cameras are used for video signal acquisition.	Yes	*		*		*	*	*
A2.14 - Are there unwanted outputs of energy or substances? - Energy-related factors that should be considered include noise and vibration, heat, radiation (including ionizing, non-ionizing, and ultraviolet/visible/infrared radiation), contact temperatures, leakage currents, and electric or magnetic fields. - Substance-related factors that should be considered include substances used in manufacturing, cleaning or testing having unwanted physiological effects if they remain in the product. - Other substance-related factors that should be considered include discharge of chemicals, waste products, and body fluids.	No, device is software	No							
A2.15 - Is the medical device susceptible to environmental influences? Factors that should be considered include the operational, transport and storage environments. These include light, temperature, humidity, vibrations, spillage, susceptibility to variations in power and cooling supplies, and electromagnetic interference.	No, device is software	No							
A2.16 - Does the medical device influence the environment? Factors that should be considered include: — the effects on power and cooling supplies; — emission of toxic materials; — the generation of electromagnetic disturbance.	No, device is software	No							
A2.17 - Does the medical device need consumables or accessories? Factors that should be considered include specifications for such consumables or accessories and any restrictions placed upon users in their selection of these.	No, device is software	No							
A2.18 - Is maintenance or calibration necessary? Factors that should be considered include: — whether maintenance or calibration are to be carried out by the user or by a specialist; — whether special substances or equipment are needed for proper maintenance or calibration; — traceability of the calibrator values to a higher order reference; — how to determine when maintenance or recalibration is needed; — how to verify that calibration is (still) acceptable.	No	No							
A2.19 - Does the medical device contain software? Factors that should be considered include whether software is intended to be installed, verified, modified or exchanged by the user or by a specialist, and the authenticity of a software update.	Yes, software is installed by informed personnel.	Yes	*	*	*		*	*	*

A2.20 - Does the medical device allow access to information? Factors that should be considered include Ethernet ports, USB ports, serial ports and removable hard drives.	No, patent data are not stored, neither in the server nor in the smartphone.	No							
A2.21 - Does the medical device store data critical to patient care? Factors that should be considered include the possibility of the data being modified or corrupted unauthorized access to the data, and the consequences for the patients	No, patent data are not stored, neither in the server nor in the smartphone.	No							
A2.22 - Does the medical device have a restricted shelf-life? Factors that should be considered include whether the medical device can deteriorate over time, the impact of storage conditions and primary packaging, the communication of the expiry date [by labelling or an indicator], possibility of use after the expiry date, and the disposal of expired medical devices.	No, device is software	No							
A2.23 - Are there any delayed or long-term use effects? Factors that should be considered include ergonomic and cumulative effects. Examples could include pumps for saline that corrode over time, mechanical fatigue, loosening of straps and attachments, vibration effects, labels that wear or fall off, long-term material degradation.	No, device is software	No							
A2.24 - To what mechanical forces will the medical device be subjected? Factors that should be considered include whether the forces to which the medical device will be subjected are under the control of the user or controlled by interaction with other persons.	No, device is software	No							
A2.25 - What determines the lifetime of the medical device? Factors that should be considered include battery depletion, deterioration of materials and failure of components due to ageing, wear, fatigue or repeated use. The availability of spare parts should be considered as well	No, device is software	No							
A2.26 - Is the medical device intended for single use? Factors that should be considered include: - whether the medical device self-destructs after use; - whether it is obvious to the user that the medical device has been used	No, device is software	No							
A2.27 - Is safe decommissioning or disposal of the medical device necessary? Factors that should be considered include the waste products that are generated during the disposal of the medical device itself, and the proper sanitization (removal) of all sensitive data on the medical device. For example, does it contain hazardous material (e.g. toxic chemical or biological agent), or is the material recyclable? If the medical device stores data, proper handling and security of the stored data should be considered, including data removal and retention.	No, patent data are not stored, neither in the server nor in the smartphone.	No							
A2.28 - Does installation or use of the medical device require special training or special skills? Factors that should be considered include the complexity and novelty of the medical device and the knowledge, skills and ability of the persons installing, maintaining or using the medical device. This can include training education, competence assessment, certification or qualification	Users shall be informed, no traing needed	No							
A2.29 - How will information for safety be provided? Factors that should be considered include: — whether information will be provided directly to the end user by the manufacturer or will it involve the participation of third parties such as installers, care providers, health care professionals, laboratory directors or pharmacists and whether this will have implications for training; — commissioning and transferring to the end user and whether it is likely/possible that installation can be carried out by people without the necessary skills; — based on the type and expected life time of the medical device, whether re-training or re-certification of users or service personnel would be indicated.	IFU	Yes					*		
A2.30 - Are new manufacturing processes established or introduced? Factors that should be considered include the application of new or innovative technology and changes in the scale of production. This can also involve changes in contract manufacturing, suppliers and vendors.	No	No							
A2.31 Is successful application of the medical device dependent on the usability of the user interface?	Yes, users shall be informed and able to understand software interface.	Yes			*		*	*	
A.2.31.1 Can the user interface design features contribute to use error? Factors that should be considered include: control and indicators, symbols used, ergonomic features, physical design and layout, hierarchy of operation, menus for software-driven medical devices, visibility of warnings, audibility of alarms, standardisation of colour coding. See IEC 62366-1 for additional information on usability and IEC 60601-1-8 for alarms.	Yes, not understanging software interface can cause user errors.	Yes			*		*	*	

A2.31.2 - Is the medical device used in an environment where distractions can cause use error? Factors that should be considered include: — the consequence of use error, — whether the distractions are commonplace; — whether the user can be disturbed by an infrequent distraction; — whether repetitive stress can reduce the user's awareness or attention	No	No							
A2.31.3 -Does the medical device have connecting parts or accessories? Factors that should be considered include the possibility of wrong connections, similarity to other products' connections, connection force, feedback on connection integrity, and over- and under-tightening.	No, but mobile application is running on mobile phone which must be compatible.	Yes	*	*				*	*
A2.31.4 -Does the medical device have a control interface? Factors that should be considered include spacing, coding, grouping, mapping, modes of feedback, blunders, slips, control differentiation, visibility, direction of activation or change, whether the controls are continuous or discrete, and the reversibility of settings or actions.	Interface via the smartphone, the medical app.	Yes			*		*		
A2.31.5 - Does the medical device display information? Factors that should be considered include visibility in various environments, orientation, the visual capabilities of the user, populations and perspectives, clarity of the presented information, units, colour coding, and the accessibility of critical information.	Yes, information about patient movements is shown in mobile app.	Yes	*	*			*		
A2.31.6 Is the medical device controlled by a menu? Factors that should be considered include complexity and number of layers, awareness of state, location of settings, navigation method, number of steps per action, sequence clarity and memorization problems, and importance of control function relative to its accessibility and the impact of deviating from specified operating procedures.	Yes, admin menu can be used to select types of movement, add patient beds to be monitored, assign nurses, etc...	Yes	*		*		*		
A2.31.7 – Is the successful use of the medical device dependent on a user's knowledge, skills and abilities? Factors that should be considered include: — the (intended)user, their mental and physical abilities, skill and training; — the use environment, ergonomic aspects, installation requirements; — the capability of intended users to control or influence the use of the medical device, and — the personal characteristics of intended users that can affect their ability to successfully interact with the medical device. See IEC/TR 62366-2 .	Yes, users shall be informed how to understand and use software interface. User type is defined in intended use document.	Yes			*		*		
A2.31.8 -Will the medical device be used by persons with specific needs? Factors that should be considered include: — users with special characteristics, such as disabled persons, the elderly and children, who might need assistance by another person to enable the use of a medical device; — users having wide-ranging skill levels and differing cultural backgrounds and expectations that could lead to differences in what is considered appropriate application of the medical device.	No, software is not intended to be used by persons with specific needs	No							
A.2.31.9 Can the user interface be used to initiate unauthorised actions? Factors that should be considered include whether the user interface allows the user to enter an operation mode with restricted access [e.g. for maintenance or special use], which increases the possibility of use error and thereby the associated risks, and whether the user becomes aware of having entered such operation mode.	Yes	Yes		*	*				
A2.32 -Does the medical device use an alarm system? Factors that should be considered are the risk of false alarms, missing alarms, disconnected alarm systems, unreliable remote alarm systems, and the user's ability of understanding how the alarm system works. Guidance for alarm systems is given in IEC 60601-1-8.	Yes, software shows alarms/alerts to nurses if patients are moving in bed.	Yes			*		*		
A2.33 - In what ways might the medical device be misused (deliberately or not)? Factors that should be considered are incorrect use of connectors, disabling safety features or alarms, neglect of manufacturer's recommended maintenance, unauthorized access to the medical device or to medical device functions.	Yes, use outside defined intended use.	Yes			*		*	*	
A2.34 - Is the medical device intended to be mobile or portable? Factors that should be considered are the need for grips, handles, wheels or brakes, and for mechanical stability and durability.	NA - device is software	No							
A2.35 -Does the use of the medical device depend on essential performance? Factors that should be considered are, for example, the characteristics of the output of life supporting medical devices or the operation of an alarm. See IEC 60601-1 for a discussion of essential performance of medical electrical equipment and medical electrical systems.	No	No							

A.2.36 Does the medical device have a degree of autonomy? Factors that should be considered include: — awareness of the user when the medical device with a degree of autonomy generates an error, alarm or failure; — awareness of the user when intervention in an autonomously performed action is required; — the ability of the user to intervene in or to abort an action that is performed autonomously; and — the ability of the user to select and perform proper corrective actions. See IEC TR 60601-4-11 for further guidance on medical devices with a degree of autonomy.	Yes, device uses automatic software detection algorithm to detect patient movement.	Yes	*	*					
A.2.37 Does the medical device produce an output that is used as an input in determining clinical action? Factors that should be considered include whether incorrect or delayed outputs can result in direct or indirect risks to patients, e.g. an incorrect diagnosis resulting in delayed or omitted therapy for a patient. See Annex H for guidance on in vitro diagnostic medical devices.	Yes	Yes	*	*	*		*	*	

Severity \ Probability	Negligible (1)	Minor (2)	Serious (3)	Critical (4)	Catastrophic (5)
Frequent 5	R2	R2	R3	R3	R3
Probable 4	R1	R2	R2	R3	R3
Occasional 3	R1	R2	R2	R2	R3
Remote 2	R1	R1	R2	R2	R2
Improbable 1	R1	R1	R1	R1	R2

Additional risk control measures shall be implemented to reduce the risk to R1 level. If no measures are practicable or if the risk value remains within the R2 level, a risk-benefit analysis must be performed and documented in the risk management report.

Risk Class	Risk level	Range	Acceptance Criteria
R1	Low Risk Level	1-4	Acceptable
R2	Medium Risk Level	5-12	Risk reduction actions required and must be made to bring the risk to an acceptable(Low) level (investigate further reduction)
R3	High Risk Level	13-25	Not acceptable Risk

SEVERITY	Definition	Value
Catastrophic	Results in death or life-threatening injury or illness	5
Critical	Injury or illness that results in non-trivial permanent impairment of a body function or permanent damage to a body structure, or necessitates medical or surgical intervention to prevent non-trivial permanent impairment of a body function or permanent damage to a body structure	4
Serious	Injury or illness that results in trivial permanent impairment or temporary/reversible bodily impairment or damage requiring professional medical or surgical intervention Damage to the environment.	3
Minor	Results in temporary injury or impairment not requiring medical or surgical intervention	2
Negligible	No injury to the patient or user. Results in inconvenience or temporary discomfort.	1

Probability	Definition	Value
Frequent	Above 1 in 10 (10%) (Harm is expected to occur in at least 1 case per 10 products sold). It is almost certain that a large amount of harms will occur	5
Probable	1 in 100 < F ≤ 1 in 10 (1% to 10%)	4
Occasional	1 in 1,000 < F ≤ 1 in 100	3
Remote	1 in 10,000 ≤ F ≤ 1 in 1,000	2
Improbable	F ≤ 1 in 10,000 (Harm is expected to occur in equal or less than 1 case per 10.000 products sold). It is unlikely that the harm will occur	1

Hazards related to System															Evaluation of Overall Residual Risk Acceptability		
Risk ID	Hazard (source)	Forseeable sequence of events (cause)	Hazardous situation	Harm	Probability of Occurrence	Severity	risk estimation	Risk Level Review	Risk Mitigation measure	Probability of Occurrence	Severity	mitigated risk estimation	Residual Risk Review	Related verification Document	Residual Hazard (Yes/ No) - Rationale	Benefit/ Risk Analysis	Does risk control parameters don't cause new hazards or risks
SYS-HTM-0001	Notification (incorrect information) - IT-env	Server down. Server turned off	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0002	Notification (incorrect information) - IT-env	Network down. No movement detected - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0003	Notification (incorrect information) - Ext env.	Camera loses power/restarts. No movement detected - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system displays the stack status. SRE0137	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0004	Notification (incorrect information) - IT-env	Certificate expires. No communication - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0005	Notification (incorrect information) - IT-env	Certificates in camera or MediaMTX expired. No communication - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system displays the stack status. SRE0137	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0006	Notification (incorrect information) - Hardware	Speaker does not work on mobile device. No audio notification.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system uses a tactile signal to indicate a new notification. SRE0068	2	2	4	LOW RISK	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0007	Notification (incorrect information) - Hardware	Hardware error on mobile device. App crashes - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system redirects RED notifications to the group after 120 seconds if not acknowledged. SRE0061 2. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 4. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 5. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0008	Notification (incorrect information) - Hardware	Hardware error on server.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149 2. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 3. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0009	Notification (incorrect information) - Hardware	Hardware error on camera. No video feed - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system displays the stack status. SRE0137	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0010	Notification (incorrect information) - IT-env	Server out-of-disk space - warnings not stored and escalation does not work - False negative	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149 2. The system shall run on a server with the following specifications: - Linux Distro ubuntu 24.04 - CPU 32c 64t - RAM 256GB - GPU NVIDIA 24GB - SSD 1TB usable (fx 2x1TB RAID1/Mirror) SRE0118 3. The system sends prometheus alerts to an alert client. SRE0089 4. The system sends metrics to a remote write server. SRE0094 5. The system sends log messages to a syslog server. SRE0095	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SYS-HTM-0011	Notification (incorrect information) - IT-env	Android out-CPU resources. App crashes or freezes and warnings are not raised on the mobile device - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system redirects RED notifications to the group after 120 seconds if not acknowledged. SRE0061 2. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 4. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 5. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0012	Notification (incorrect information) - IT-env	Android out-of-memory. App crashes or freezes and warnings are not raised on the mobile device - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system redirects RED notifications to the group after 120 seconds if not acknowledged. SRE0061 2. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 4. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 5. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0013	Notification (incorrect information) - IT-env	Server out-of-memory. Server inoperational and warnings are not propagated to the mobile devices App crashes or freezes and warnings are not raised on the mobile device - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149 2. The system shall run on a server with the following specifications: - Linux Distro ubuntu 24.04 - CPU 32c 64t - RAM 256GB - GPU NVIDIA 24GB - SSD 1TB usable (fx 2x1TB RAID1/Mirror) SRE0118 3. The system sends prometheus alerts to an alert client. SRE0089 4. The system sends metrics to a remote write server. SRE0094 5. The system sends log messages to a syslog server. SRE0095	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0014	Notification (incorrect information) - IT-env	Server out-of- CPU resources. Server processes slowed down and warnings are delayed to the mobile devices.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 2. The system shall run on a server with the following specifications: - Linux Distro ubuntu 24.04 - CPU 32c 64t - RAM 256GB - GPU NVIDIA 24GB - SSD 1TB usable (fx 2x1TB RAID1/Mirror) SRE0118	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0015	Notification (incorrect information) - IT-env	Network performance drops. Warnings are not propagated to the mobile devices and/or video feed not available - False negative.	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0016	Intentional Misuse	Unauthorized access to admin panel.	Unauthorized configuration change (deleting/adding nurses, beds, changing of parameters).	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system creates the first user with configuration permission during installation. SRE0155	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SYS-HTM-0017	Usability	Hospital runs multiple instances of migo for multiple departments (with different configurations)	Update and maintenance of the system takes too much time	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. M2Call's process: Service Technician follows the installation guidance 2. Multitenant functionality SRE0400 3. Multiproduct functionality SRE0401	2	2	4	LOW RISK	Installation Manual-migo System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

Hazards related to software issues															Evaluation of Overall Residual Risk Acceptability			
Risk ID	Item	Hazard (source)	Forseeable sequence of events (cause)	Hazardous situation	Harm	Probability of Occurrence	Severity	risk estimation	Risk Level Review	Risk Mitigation measure	Probability of Occurrence	Severity	mitigated risk estimation	Residual Risk Review	Related verification Document	Residual Hazard (Yes/ No) - Rationale	Benefit/ Risk Analysis	Does risk control parameters don't cause new hazards or risks
SW-HTM-0001	Admin Web	Notification (incorrect information)	Admin Web Terminates	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0002	Admin Web	Notification (incorrect information)	Admin Web Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149 2. The system raises a warning if the time on a mobile device differs from the time on the server by more than 1 seconds. SRE0123 3. The system raises a warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0003	Admin Web	Notification (incorrect information)	Logic error in Admin Web (False positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0004	Admin Web	Notification (incorrect information)	Logic error in Admin Web (False negative)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0005	Any Movement Detector	Notification (incorrect information)	AI fails to detect body poses wich causes any movement detector crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system starts detectors if they are not running. SRE0138 3. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0006	Any Movement Detector	Notification (incorrect information)	AI fails to detect body poses wich causes any movement detector to freeze.	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0007	Any Movement Detector	Notification (incorrect information)	Logic Error in Any Movement Detector (False positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0008	Any Movement Detector	Notification (incorrect information)	Logic Error in Any Movement Detector (False negative)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0009	Arm Movement Detector	Notification (incorrect information)	Arm Movement Detector Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects arm movement. SRE0040 2. The system starts detectors if they are not running. SRE0138 3. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0010	Arm Movement Detector	Notification (incorrect information)	Arm Movement Detector Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects arm movement. SRE0040 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0011	Arm Movement Detector	Notification (incorrect information)	Logic Error in Arm Movement Detector (False positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects arm movement. SRE0040	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

[illegible]

SW-HTM-0029	Eye Movement Detector	Notification (incorrect information)	Eye Movement Detector Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects eye movement. SRE0041 2. The system starts detectors if they are not running. SRE0138 3. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0030	Eye Movement Detector	Notification (incorrect information)	Eye Movement Detector Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects eye movement. SRE0041 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0031	Eye Movement Detector	Notification (incorrect information)	Logic Error in Eye Movement Detector (false positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects eye movement. SRE0041	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0032	Eye Movement Detector	Notification (incorrect information)	Logic Error in Eye Movement Detector (false negative)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects eye movement. SRE0041	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0033	Heartbeat Service (HS)	Notification (incorrect information)	Heartbeat Service (HS) crashes. A warning about a slow server is shown	HCP receives wrong system alert about technical problem on the server	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0034	Heartbeat Service (HS)	Notification (incorrect information)	Heartbeat Service (HS) freezes. A warning about a slow server is shown	HCP receives wrong system alert about technical problem on the server	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0035	Heartbeat Service (HS)	Notification (incorrect information)	Logic Error in Heartbeat Service (HS) - false positive	HCP receives wrong system alert about technical problem on the server	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0036	migo app	Notification (incorrect information)	migo app Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0037	migo app	Notification (incorrect information)	migo app Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0038	migo app	Notification (incorrect information)	Logic Error in migo app (false negative)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system displays a warning if the volume is off. SRE0134 16. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 17. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 18. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 19. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SW-HTM-0039	migo app	Notification (incorrect information)	Logic Error in migo app (false positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system displays a warning if the volume is off. SRE0134 16. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 17. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 18. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 19. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0040	Mouth Movement Detector	Notification (incorrect information)	Mouth Movement Detector Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects mouth movement. SRE0045 2. The system starts detectors if they are not running. SRE0138 3. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 4. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0041	Mouth Movement Detector	Notification (incorrect information)	Mouth Movement Detector Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects mouth movement. SRE0045 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152, 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 4. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0042	Mouth Movement Detector	Notification (incorrect information)	Logic Error in Mouth Movement Detector (false positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects mouth movement. SRE0045	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0043	Mouth Movement Detector	Notification (incorrect information)	Logic Error in Mouth Movement Detector (false negative)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects mouth movement. SRE0045	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0044	Notification Interferer (NI)	Notification (incorrect information)	Notification Interferer (NI) Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0045	Notification Interferer (NI)	Notification (incorrect information)	Notification Interferer (NI) Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SW-HTM-0046	Notification Interferer (NI)	Notification (incorrect information)	Logic Error in Notification Interferer (NI) - False positive	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0047	Notification Interferer (NI)	Notification (incorrect information)	Logic Error in Notification Interferer (NI) - false negative	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0048	Pixel Threshold Engine (PTE)	Notification (incorrect information)	Pixel Threshold Engine (PTE) Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 16. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 17. The system starts detectors if they are not running. SRE0138	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0049	Pixel Threshold Engine (PTE)	Notification (incorrect information)	Pixel Threshold Engine (PTE) Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 16. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0050	Pixel Threshold Engine (PTE)	Notification (incorrect information)	Logic Error in Pixel Threshold Engine (PTE)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SW-HTM-0051	Pose Estimation (PE)	Notification (incorrect information)	Pose Estimation (PE) Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 18. The system starts detectors if they are not running. SRE0138	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0052	Pose Estimation (PE)	Notification (incorrect information)	Pose Estimation (PE) Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0053	Pose Estimation (PE)	Notification (incorrect information)	Logic Error in Pose Estimation (PE) - False positive	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0054	Pose Estimation (PE)	Notification (incorrect information)	Logic Error in Pose Estimation (PE) - False negative	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SW-HTM-0055	Post Pose Processor (PPP)	Notification (incorrect information)	Post Pose Processor (PPP) Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 18. The system starts detectors if they are not running. SRE0138	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0056	Post Pose Processor (PPP)	Notification (incorrect information)	Post Pose Processor (PPP) Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0057	Post Pose Processor (PPP)	Notification (incorrect information)	Logic Error in Post Pose Processor (PPP)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405	3	1	3	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0058	Pre-Processor (PP)	Notification (incorrect information)	Pre-Processor (PP) Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 18. The system starts detectors if they are not running. SRE0138	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SW-HTM-0059	Pre-Processor (PP)	Notification (incorrect information)	Pre-Processor (PP) Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0060	Pre-Processor (PP)	Notification (incorrect information)	Logic Error in Pre-Processor (PP)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0061	Stack Manager	Notification (incorrect information)	Stack Manager Crashes and changes to docker compose files not detected. Cropping area not enforced and detections don't work	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system crops the camera view area according to camera specific settings. SRE0120	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0062	Stack Manager	Notification (incorrect information)	Stack Manager Freezes and changes to docker compose files not detected. Cropping area not enforced and detections don't work	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system crops the camera view area according to camera specific settings. SRE0120	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0063	Stack Manager	Notification (incorrect information)	Logic Error in Stack Manager	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system crops the camera view area according to camera specific settings. SRE0120	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0064	Streaming engine	Notification (incorrect information)	Streaming engine Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132 18. The system starts detectors if they are not running. SRE0138	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SW-HTM-0065	Streaming engine	Notification (incorrect information)	Streaming engine Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 17. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0066	Streaming engine	Notification (incorrect information)	Logic Error in Streaming engine	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0067	Installer	Notification (incorrect information)	Crashes. Incomplete installation.	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0068	Installer	Notification (incorrect information)	Crashes. Incomplete installation.	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0069	Installer	Notification (incorrect information)	Freezes. Incomplete installation.	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0070	Installer	Notification (incorrect information)	Logic error. Inconsistent installation.	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0071	Leaving cropped Detector	Notification (incorrect information)	Leaving cropped area Detector Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0316 2. The system starts detectors if they are not running. SRE0138 3. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0072	Leaving cropped area Detector	Notification (incorrect information)	Leaving cropped area Detector Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0316 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0073	Leaving cropped Detector	Notification (incorrect information)	Logic Error in Leaving cropped area Detector (False positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0316	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0074	Leaving cropped Detector	Notification (incorrect information)	Logic Error in Leaving cropped area Detector (False negative)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0316	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0075	Activity Tracker	Notification (incorrect information)	Activity Detector Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0326 2. The system starts detectors if they are not running. SRE0138 3. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0076	Activity Tracker	Notification (incorrect information)	Activity Detector Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0326 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0077	Activity Tracker	Notification (incorrect information)	Logic Error in Activity Detector (False positive)	HCP receives wrong notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0326	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM-0078	Activity Tracker	Notification (incorrect information)	Logic Error in Activity Detector (False negative)	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0326	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

DISTR- HTM- 0001	/	Notification (incorrect information) - Software	Installation media corrupt. Inconsistent system installed.	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM RISK	1.The system requires signed software upgrades. 2. The system upgrades the server software from an installation media. SRE0145	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM- 0079	/	Notification (incorrect information) - Software	During startup, monitoring may not yet be fully active, which can trigger temporary false invisibility warnings.	System sends numerous false positive notifications	HCP frustration	4	2	8	MEDIUM RISK	1. Graceful startup - System shall suppress notifications for a startup window (during camera startup/initialization) after camera/region enable or stream restart to avoid false startup alerts. SRE0409	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SW-HTM- 0080	/	Notification (incorrect information) - Software	The patient body part gets outside the camera view (covered by blanked, or outside the cropping area), the system continuously sends non-visible notifications to HCP	System sends numerous notifications for the same event	HCP frustration	4	2	8	MEDIUM RISK	1. Body parts invisible notifications behavior SRE0314	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

Hazards related to SOUP issues																Evaluation of Overall Residual Risk Acceptability		
Risk ID	Item	Hazard (source)	Forseeable sequence of events (cause)	Hazardous situation	Harm	Probability of Occurrence	Severity	risk estimation	Risk Level Review	Risk Mitigation measure	Probability of Occurrence	Severity	mitigated risk estimation	Residual Risk Review	Related verification Document	Residual Hazard (Yes/ No) - Rationale	Benefit/ Risk Analysis	Does risk control parameters don't cause new hazards or risks
SO-HTM-0001	Heartbeat Service (HS)	Software	Logic Error in Heartbeat Service (HS) - false negative	HCP receives no system alert about technical problem on the server	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	Use of 62304 standard for software development, configuration, maintainance and problem resolution.	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304)	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0002	Android	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0003	Android	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0004	Android	Notification (incorrect information)	Terminates migo app	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0005	Android	Notification (incorrect information)	Loses network connection	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0006	Browser	SOUP Software	Freezes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304)	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0007	Browser	SOUP Software	Crashes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304)	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0008	Camera software	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0009	Camera software	Notification (incorrect information)		HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0010	Linux	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0011	Linux	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0012	Docker	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0013	Docker	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149 2. The system uses heartbeats between movement detection components to detect frozen applications. SRE0152 , 3. The system raises warning if warnings from the server are delayed by more than 6 seconds. SRE0132	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0014	NGINX	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0015	NGINX	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0016	MediaMTX	SOUP Software	Crashes	HCP cannot see live video	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304)	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0017	MediaMTX	Notification (incorrect information)	Freezes. The user receives a notifications but sees a frozen image and believes the patient position is fine	HCP has the wrong perception of the patient position	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system displays low resolution live video streams on mobile devices upon request SRE0044	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0018	MediaMTX	Notification (incorrect information)	Logic error in MediaMTX. The wrong video feed is sent to the wrong mobile device	HCP has the wrong perception of the patient position	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system displays low resolution live video streams on mobile devices upon request SRE0044	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SO-HTM-0019	Postgres Database Server	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0020	Postgres Database Server	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0025	Syslog-ng	SOUP Software	Crashes	IT technician does not receive diagnostic data	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0026	Syslog-ng	SOUP Software	Freezes	IT technician does not receive diagnostic data	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0027	djangopap allauth	Notification (incorrect information)	Crashes, user cannot authenticate	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0028	djangopap allauth	Notification (incorrect information)	Freezes, authentication not possible	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0029	djangopap allauth	Notification (incorrect information)	Logic error, false negative. Authorized user cannot login.	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system shall authenticate a user upon request. SRE0028 2. The system shall require configurator permissions to: - Configure beds - Configure cameras - Configure users - Configure devices - Configure teams - Import configuration - Export configuration - Download a new mobile device software from the server for deployment in the MDM system. SRE0007	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0030	djangopap auditlog	SOUP Software	Crashes	Audit log created available	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0031	djangopap auditlog	SOUP Software	Freezes	Audit log created available	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0032	djangopap auditlog	SOUP Software	Logic error	In-correct audit log	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	Use of 62304 standard for software development, configuration, maintenance and problem resolution.	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0033	djangopap bootstrap_modals_forms	SOUP Software	Crashes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0034	djangopap bootstrap_modals_forms	SOUP Software	Freezes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0035	djangopap bootstrap_modals_forms	SOUP Software	Logic error	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	Use of 62304 standard for software development, configuration, maintenance and problem resolution.	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0036	djangopap bootstrap5	SOUP Software	Crashes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0037	djangopap bootstrap5	SOUP Software	Freezes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0038	djangopap bootstrap5	SOUP Software	Logic error	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	Use of 62304 standard for software development, configuration, maintenance and problem resolution.	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0039	djangopap conshaders	SOUP Software	Crashes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0040	djangopap conshaders	SOUP Software	Freezes	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0041	djangopap conshaders	SOUP Software	Logic error	Configurator cannot configure migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	Use of 62304 standard for software development, configuration, maintenance and problem resolution.	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0045	djangopap fontawesomefontawesome	Notification (incorrect information)	Crashes	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0046	djangopap fontawesomefontawesome	Notification (incorrect information)	Freezes	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SO-HTM-0047	djangoapp_fontawesomefont	Notification (incorrect information)	Logic error	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0048	djangoapp_jquery	Notification (incorrect information)	Crashes	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0049	djangoapp_jquery	Notification (incorrect information)	Freezes	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0050	djangoapp_jquery	Notification (incorrect information)	Logic error	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0051	djangoapp_ninja	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0052	djangoapp_ninja	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0053	djangoapp_ninja	Notification (incorrect information)	Logic error and a REST request is not handled	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0054	djangoapp_oauth2_provider	Notification (incorrect information)	Crashes, user cannot authenticate	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0055	djangoapp_oauth2_provider	Notification (incorrect information)	Freezes, authentication not possible	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0056	djangoapp_oauth2_provider	Notification (incorrect information)	Logic error, false positive. Unauthorized access	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0057	djangoapp_oauth2_provider	Notification (incorrect information)	Logic error, false negative. Authorized user cannot login.	HCP cannot use migo	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system shall authenticate a user upon request. SRE0028 2. The system shall require configurator permissions to: - Configure beds - Configure cameras - Configure users - Configure devices - Configure teams - Import configuration - Export configuration Download a new mobile device software from the server for deployment in the MDM system. SRE0007	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SO-HTM-0058	djangoapp rest_framework	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218 "	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0059	djangoapp rest_framework	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218 "	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0060	djangoapp rest_framework	Notification (incorrect information)	Logic error	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0061	django	Notification (incorrect information)	Crashes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218 "	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0062	django	Notification (incorrect information)	Freezes	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0063	uwsgi	Notification (incorrect information)	Crashes.	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system raises a warning if the connection to the server is lost. SRE0149 2. The IFU shall instruct the HCP to contact Configurator if system freezes/crashes. SRE0218	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

SO-HTM-0064	all soups	SOUN Software	Use of obsolete SOUNs and SOUNs with no bugs or vulnerabilities.	Incompatibility with software system. Errors in functionality.	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	Use of 62304 standard for software development, configuration, maintenance and problem resolution.	2	2	4	LOW RISK	SOPs according to 62304 and records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No
SO-HTM-0065	Python/RUST	SOUN Software	Logical error	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	5	2	10	MEDIUM RISK	1. The system detects movements. SRE0039 2. The system detects arm movement. SRE0040 3. The system detects eye movement. SRE0041 4. The system detects a hand near the face. SRE0042 5. The system detects if hands are near each other. SRE0043 6. The system detects mouth movement. SRE0045 7. The system detects rapid movement. SRE0046 8. The system separates detection of left and right arm SRE0047 9. The system separates detection of left and right hand SRE0048 10. The system detects if a person leaves cropped area SRE0316 11. The system detects if person is resting or active SRE0326 12. The system does not detect movements caused by shadows SRE0318 13. The system does not detect movements during a significant light change SRE0339 14. The system detects when a patient sits up or lies back down. SRE0405 15. The system works with low light (5 lux) level in the patient room. SRE0109 16. Use of 62304 standard for software development, configuration, maintenance and problem resolution.	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report SOP SW Development SOP SW Configuration SOP SW Maintenance SOP SW Problem resolution + records created during development (according to 62304).	No, residual risk is rated as acceptable	N/A	No

Cybersecurity hazards															Evaluation of Overall Residual Risk		
HAZARD	Hazard (source)	Forseeable sequence of events (cause)	Hazardous situation	Harm	Probability of Occurrence	Severity	risk estimation	Risk Level Review	Risk Mitigation measure	Probability of Occurrence	Severity	mitigated risk estimation	Residual Risk Review	Related verification Document	Residual Hazard (Yes/ No) - Rationale	Benefit/ Risk Analysis	Does risk control parameters don't cause new hazards or risks
HTM-CBR-0001	Server	Availability Contributing factors: - Server stolen - Server missing - Availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0002	Server	Availability Contributing factors: - Bruteforce of Server - Server turned off - Availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0003	Server	Availability Contributing factors: - DoS of server - Server overloaded - Availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0004	Server, Phone, Camera & Infrastructure	Availability Contributing factors: - Backdoor access through hardware component - Hardware turned off - Availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0005	Server	Availability Contributing factors: - Authorized access with bad intentions - Server turned off or decommissioned - Availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0006	Network infrastructure	Availability Contributing factors: - Network infrastructure stolen - Network infrastructure availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0007	Network infrastructure	Availability Contributing factors: - Bruteforce of infrastructure - Network infrastructure availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0008	Network infrastructure	Availability Contributing factors: - DoS of infrastructure - Network infrastructure availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0009	Network infrastructure	Availability Contributing factors: - Authorized access with bad intentions - Network infrastructure availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use Instructions for use shall contain all information as required by applicable standards and regulations SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

HTM-CBR-0010	Network infrastructure	Availability Contributing factors: - Backdoor access through infrastructure component - Network infrastructure availability lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. Instructions for use instructions for use shall contain all information as required by applicable standards and regulations. SRE0217 3. The system raises a warning if the connection to the server is lost. SRE0149	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0011	Phone	Integrity Contributing factors: - Phone lost - Configuration comprimized - System log incorrect - Integrity lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. The system redirects RED notifications to the group after 120 seconds if not acknowledged. SRE0061 3. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 5. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 6. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0012	Server	Integrity Contributing factors: - Unauthorized access to server - Configuration comprimized - System log incorrect - Integrity lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	2	2	4	LOW	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses"	1	2	2	LOW	IFU	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0013	Server	Integrity Contributing factors: - Authorized access to server - Bad intentions to change alarm settings - Configuration comprimized - System log incorrect - Integrity lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224	2	2	4	LOW	IFU	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0014	App	Integrity Contributing factors: - Authorized access to app - Bad intentions to change alarm settings - Configuration comprimized - System log incorrect - Integrity lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224	2	2	4	LOW	IFU	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0015	Camera	Integrity Contributing factors: - Intentionally obstruct view of camera to patient - Configuration comprimized. - System log incorrect - Integrity lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224	2	2	4	LOW	IFU	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0016	Server	Integrity Contributing factors: - Bruteforce of server and infrastructure - System overload to handle all activities - Integrity lost	HCP does not receive alerts about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. IFU - "Mobil. 4031 6389 E-mail: support@siemenshealthineers.com" IFU - "• Do not use the migo solution if there is software on your device that has been hacked or infected by viruses" SRE0224 2. The system raises a warning if warnings from the server are delayed by more than 6 seconds. SRE0132	1	2	2	LOW	IFU System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0017	Server/Firewall	Cyber attack using open ports on firewall.	Non operational system.	Delayed intervention in patient positioning	3	2	6	MEDIUM	1. The system closes all unused ports in the firewall. SRE0140 2. The system runs on a Linux server with a firewall. SRE0142	2	2	4	LOW	System/Software Verification plan System/Software Verification Protocol System/Software Verification report Installation protocol	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0018	Network infrastructure	Cyber attack - network sniffing	Attacker get access to video stream	Data leak	3	2	6	MEDIUM	1. The system encrypts communication between camera, server and mobile devices. SRE0141	2	2	4	LOW	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
HTM-CBR-0019	Compromised software release	M2Call Employee with poor knowledge of cybersecurity policies and threats fails to social engineering	Adversarial actor gains access to the system and perform a logic change in software	Patient and operator frustration / data leak	2	3	6	MEDIUM	1. Cybersecurity policy 2. Regular Cybersecurity training for all employees. 3. Software developed and tested before deployment according to 62304	1	3	3	LOW	Cybersecurity policy System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

Evaluation of Overall Residual Risk Acceptability																		
Risk-ID	Usability Task	Hazard (source)	Foreseeable sequence of events (cause)	Hazardous situation	Harm to patient / user	Probability of Occurrence	Severity	Risk estimation	Risk Level Review	Risk Mitigation measure	Probability of Occurrence	Severity	Risk estimation	Residual Risk Review	Related verification Document	Residual Hazard (Yes/ No) - Rationale	Benefit/ Risk Analysis	Does risk control parameters don't cause new hazards or risks
USE-HTM-0001	TAM-0001 FUS-0018	Notification (incorrect information) - TA001	migo solution cannot monitor and evaluate patient Contributing factors: - Moving of bed outside camera range - HCP/other people i/sr standing in front of the camera - Blanket covering the patient	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall raise a 'No Patient' BLUE notification. SRE0073 2. The system shall raise a 'Right arm to face not visible' BLUE notification. SRE0131. 3. The system shall raise a 'Left arm movement not visible' BLUE notification. SRE0125. 4. The system shall raise a 'Left arm to face not visible' BLUE notification. SRE0126. 5. The system shall raise a 'Right arm movement not visible' BLUE notification. SRE0130. 6. The system shall raise an 'Overlapping hands not visible' BLUE notification. SRE0129	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0002	TAM-0006	Use error- Notification (incorrect information)	Notifications reach the mobile device but not the HCP Contributing factors: - Too noisy - Sound too low - Silent and in the pocket - Using other apps - User turns off android notifications	HCP does not receive android notifications about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM RISK	1. The system displays a warning if the volume is off. SRE0134. 2. The system redirects RED notifications to the group after 120 seconds if not acknowledged. SRE0061 3. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 5. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 6. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0003	TAM-0019	Use error- Notification (incorrect information)	User is not aware of which movements notifications are turned on when logging in to the system Contributing factors: - Forgetfulness	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall display a warning if relevant notifications have not been configured for a shift in a session. SRE0129	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0004	TAM-0024 TAM-0025	Use error- Notification (incorrect information)	User moves patient to other bed and forget to change bed in migo Contributing factors: - Forgetfulness	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a 'Empty bed' notification. SRE0073	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0005		Use error- Notification (incorrect information)	User go to the bathroom or on a break without adding a new primary nurse Contributing factors: - Forgetfulness	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0006	TAM-0001	Use error- Notification (incorrect information)	Device runs out of battery Contributing factors: - User forgets to recharge	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	2	2	4	LOW RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	1	2	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0007		Use error- Notification (incorrect information)	User cannot see enough details on the video feed due to a dirty camera lens Contributing factors: - Uncleaned camera	HCP does not receive video feed about patient movement	Delayed intervention in patient positioning	2	2	4	LOW RISK	1. The system displays a warning if the camera cropping area has not been configured for a shift in a session. SRE0121	1	2	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0008	TAM-0018	Use error- Notification (incorrect information)	User forgets/ to turn on detections after a notification pause Contributing factors: - Forgetfulness	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system allows specification of the period where notifications are suppressed. The default is 3 minutes. SRE0066. 2. The system provides an overview of beds with suppressed notifications upon request. SRE0154	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0009	TAM-0024 TAM-0025	Use error- Notification (incorrect information)	User chooses wrong beds for monitoring Contributing factors: - Miscalc	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	2	2	4	LOW RISK	1. The system displays the list of primary and secondary nurses for a bed. SRE0030	1	2	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0010	TAM-0024 TAM-0025	Use error- Notification (incorrect information)	User turns off wi-fi on mobile device Contributing factors: - Miscalc	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	2	2	4	LOW RISK	1. The system raises a warning if the connection to the server is lost. SRE0149	1	2	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0011	TAM-0016	Use error- Notification (incorrect information)	User turns off notifications settings without notifying other primary or secondary nurses Contributing factors: - Miscalc	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0012	TAM-0001 FUS-0018	Use error- Notification (incorrect information)	User forgets password Contributing factors: - Forgetfulness	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM RISK	1. System admins have the possibility to authorise mobile phones with Migo App by using unique client key. Users can not just install the app and use username and password. SRE0206	2	2	4	LOW RISK	IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0013	TAM-0009 TAM-0008 TAM-0009 TAM-0001	Use error- Notification (incorrect information)	User gets many notifications from different beds at the same time and do not react accordingly to the notifications Contributing factors: - HCP cannot understand where the "turn camera off" button is or its function - Patient to HCP ratio is high, e.g. during night time so all notifications are not attended immediately - HCP cannot understand which are the high priority notifications - HCP is not available	HCP receives too many notifications about patient movement	Delayed intervention in patient positioning	4	2	8	MEDIUM RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0080 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No

USE-HTM-0014		Use error- Notification (incorrect information)	User swaps mobile device with colleague without logging in again Contributing factors: - All the phones are lookalike	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0300 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148 5. The system redirects RED notifications to the group after 120 seconds if not acknowledged. SRE0061.	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0015	TAM-0020 TAM-0023	Use error- Notification (incorrect information)	User has turned off camera and forgets to turn it on again Contributing factors: - Missclick	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system displays if a camera is activated or de-activated. SRE0054	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0016		Use error- Notification (incorrect information)	User looks at "wrong" patient Contributing factors: - Missclick	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system contains the following user groups: migo configurator: Can configure the system migo nurse: Can use the app on the mobile device. migo auditor: Can access the audit log. SRE0077	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0017	TAM-0004	Use error- Notification (incorrect information)	User does not choose the cropping area in which the patient is placed and therefore the user do not get notifications Contributing factors: - Forgetfulness	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall display a warning if the camera cropping area has not been configured for a shift in a session. SRE0121	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0018	TAM-0003 TAM-0003 TAM-0010 TAM-0010 FUS-0039	Use error- Notification (incorrect information)	User accidentally logs out Contributing factors: - Missclick when choosing shift end time - User cannot understand time format - Cannot find the option of changing/extend shift - Chooses the wrong time for the shift to end	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	2	2	4	LOW RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0300 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148 5. The system redirects RED notifications to the group after 120 seconds if not acknowledged. SRE0061	1	2	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0019		Use error- Notification (incorrect information)	User has mobile device in a pocket and an accidental touch confirms the notification without the user knowing it. Contributing factors: - Accident	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0300 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0020	TAM-0006 TAM-0008	Use error- Notification (incorrect information)	User accidentally confirms a notification instead of rejecting it Contributing factors: - Missclick	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system shall redirect YELLOW warnings to the secondary HCP after a maximum of 120 seconds if not acknowledged. SRE0079 2. The system shall redirect RED warnings to the team after a maximum of 120 seconds if not acknowledged. SRE0147 3. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if not acknowledged by the secondary HCP. SRE0300 4. The system shall redirect YELLOW warnings to the team after a maximum of 120 seconds if no secondary HCP has been configured. SRE0148	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0021		Use error- Notification (incorrect information)	Camera captures too large an area and detections don't work Contributing factors: - Bed is moved too far away	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	2	2	4	LOW RISK	1. The system raises a "Empty bed" notification. SRE0073 2. The system shall display a warning if the camera cropping area has not been configured for a shift in a session. SRE0121	1	2	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0022		Use error- Notification (incorrect information)	Camera captures too small an area image doesn't work Contributing factors: - Patient is elevated too much in the bed	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. The system raises a "Empty bed" notification. SRE0073 2. The system shall display a warning if the camera cropping area has not been configured for a shift in a session. SRE0121	2	2	4	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0023		Misuse	System used outside of ICU.	Use of system outside intended use	No injury, possible patient frustration	3	1	3	LOW RISK	IFU clearly states intended use and contraindications.	2	1	2	LOW RISK	IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0024		Misuse	System used by minors or persons with bad vision, color blindness, hearing impairment or limited manual dexterity or cognitive abilities.	Use of system outside intended use	Possible delayed intervention in patient positioning, operator frustration	3	2	6	MEDIUM RISK	IFU clearly states intended use and contraindications.	2	2	4	LOW RISK	IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0025		Misuse	System used by minors or persons with bad vision, color blindness, hearing impairment or limited manual dexterity or cognitive abilities.	Use of system outside intended use	Possible delayed intervention in patient positioning, operator frustration	3	2	6	MEDIUM RISK	IFU clearly states intended use and contraindications.	2	2	4	LOW RISK	IFU	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0026		User error / complicated user interface	User interface too complicated for intended users	Failure to understand interface and operate system as intended.	Possible delayed intervention in patient positioning, operator frustration	3	2	6	MEDIUM RISK	Usability testing of the system	2	2	4	LOW RISK	IFU, Usability documentation.	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0027		IFU	IFU too complicated for intended users	Failure to understand and/or follow IFU instructions	Possible delayed intervention in patient positioning, operator frustration	3	2	6	MEDIUM RISK	Usability testing of the system including IFU	2	2	4	LOW RISK	IFU Usability Evaluation Report	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0028		IFU	IFU not available to intended users	Failure to understand and/or follow IFU instructions	Possible delayed intervention in patient positioning, operator frustration	3	2	6	MEDIUM RISK	IFU available to users, Additional copies available online and/or upon request.	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0029		IFU	IFU poorly translated to language of intended user.	Failure to understand and/or follow IFU instructions	Possible delayed intervention in patient positioning, operator frustration	3	2	6	MEDIUM RISK	M2Call shall use certified translation companies. Usability testing of the system including IFU.	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0030	TAM-0014	Notification (incorrect information)	Cannot change the language Contributing factors: - Cannot understand where the language settings are. User cannot understand the job.	HCP does not receive android notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	The IFU will describe how to change language.	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0031	TAM-0015	Notification (incorrect information)	User does not press pause Contributing factors: - User cannot understand where the pause button is, user is in function.	HCP does not receive android notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	migo app displays an overview of beds with notification on pause The IFU will describe how to pause and what to pause.	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0032	TAM-0016	Notification (incorrect information)	Notifications paused by accident Contributing factors: - User chooses the wrong amount of pause time - Accidentally pause when not supposed to	HCP does not receive android notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	migo app displays an overview of beds with notification on pause If "pause" is chosen migo app pauses it for 3 min by default	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No

USE-HTM-0033	TAM-0023	Notification (incorrect information)	User turns camera off Contributing factors: - User cannot understand where the "turn camera off" button is or to function	HCP does not receive android notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	The migo app will display whether the camera is activated or de-activated	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0034	TAM-0043	Notification (incorrect information)	Copy and run file - migo is not working properly due to installation media corrupt, inconsistent system installation	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	Signed software upgrade	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0035	TAM-0034 FUS-0023 FUS-0024	Notification (incorrect information)	Unable to configure cameras for the migo app - when creating/adding/editing camera, do not monitor correct patient	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	Live video stream	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0036	TAM-0040 FUS-0029 FUS-0030	Notification (incorrect information)	Unable to configure of beds for the migo app - when adding/editing bed, the correct camera and teams are not aligned with the beds	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	Live video stream	2	2	4	LOW RISK	IFU IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0037	TAM-0044	Notification (incorrect information)	Unable to integrate with hospital's maintenance systems - Cannot understand how to integrate	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	M2Call's process: Service Technician follows the installation guidance	2	2	4	LOW RISK	IFU Installation Manual-migo IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0038	TAM-0045	Notification (incorrect information)	Unable to installation/upgrade software of migo - Cannot understand how to upgrade software	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	M2Call's process: Service Technician follows the installation guidance	2	2	4	LOW RISK	IFU Installation Manual-migo IFU verification record	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0039	TAM-0047	Notification (incorrect information)	Unable to troubleshoot migo problems - Cannot understand how to troubleshoot migo	HCP does not receive notifications about patient movement	Delayed intervention in patient positioning	2	2	6	MEDIUM RISK	M2Call's process: Service Technician follows the installation guidance	2	2	4	LOW RISK	IFU Installation Manual-migo IFU verification report	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0040	/	Performance	Light changes and shadows confuse the migo system.	System raises false positive alarms.	No injury, possible HCP frustration	3	1	3	LOW RISK	1. The system shall not detect movements caused by shadows in the input image. SRE0318 2. The system shall not detect movements during a significant light change. SRE0339	2	1	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0041	/	Performance	Multiple cameras monitoring same patient	HCP finds it troublesome to navigate through multiple cameras in the hospital to monitor one patient.	No injury, possible HCP frustration	3	1	3	LOW RISK	1. The system shall allow grouping of cameras in same room (monitoring same patient) SRE0402 2. The system shall include "room group" functionality so configurator (hospital administrator) can group multiple cameras in one room (group) via Admin Web SRE0403	2	1	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No
USE-HTM-0042	/	Performance	patient sits up	migo system untested for "patient sitting up" posture, migo system sends false notifications or does not detect movements	Delayed intervention in patient positioning	3	2	6	MEDIUM RISK	1. migo system tested for "patient sitting up" posture (Release 1.5/1.6) 2. The system shall detect when a patient sits up or lies back down. SRE0405	1	2	2	LOW RISK	System/Software Verification plan System/Software Verification Protocol System/Software Verification report	No, residual risk is rated as acceptable	N/A	No

Risk ID	Requirement ID	Risk ID	Requirement ID	Risk ID	Requirement ID	Risk ID	Requirement ID	Risk ID	Requirement ID
System		Software		SOUP		Cybersecurity		Usability	
SYS-HTM-0001	SRE0149	SW-HTM-0001	SRE0149	SO-HTM-0001	N/A	HTM-CBR-0001	SRE0224, SRE0217 SRE0149	USE-HTM-0001	SRE0073, SRE0131 SRE0125, SRE0126 SRE0130, SRE0128
SYS-HTM-0002	SRE0149	SW-HTM-0002	SRE0149, SRE0123 SRE0132	SO-HTM-0002	SRE0218	HTM-CBR-0002	SRE0224, SRE0217 SRE0149	USE-HTM-0002	SRE0134, SRE0061 SRE0079, SRE0080 SRE0147, SRE0148
SYS-HTM-0003	SRE0137	SW-HTM-0003	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405	SO-HTM-0003	SRE0218	HTM-CBR-0003	SRE0224, SRE0217 SRE0149	USE-HTM-0003	SRE0129
SYS-HTM-0004	SRE0149	SW-HTM-0004	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405	SO-HTM-0004	SRE0218	HTM-CBR-0004	SRE0224, SRE0217 SRE0149	USE-HTM-0004	SRE0073
SYS-HTM-0005	SRE0137	SW-HTM-0005	SRE0039, SRE0138 SRE0152	SO-HTM-0006	SRE0218	HTM-CBR-0005	SRE0224, SRE0217 SRE0149	USE-HTM-0005	SRE0079, SRE0147 SRE0080, SRE0148
SYS-HTM-0006	SRE0068	SW-HTM-0006	SRE0039, SRE0152 SRE0132	SO-HTM-0005	SRE0149	HTM-CBR-0006	SRE0224, SRE0217 SRE0149	USE-HTM-0006	SRE0079, SRE0147 SRE0080, SRE0148
SYS-HTM-0007	SRE0061, SRE0079 SRE0080, SRE0147 SRE0148	SW-HTM-0007	SRE0039	SO-HTM-0007	SRE0218	HTM-CBR-0007	SRE0224 SRE0217 SRE0149	USE-HTM-0007	SRE0121
SYS-HTM-0008	SRE0149 SRE0132 SRE0152	SW-HTM-0008	SRE0039	SO-HTM-0008	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405	HTM-CBR-0008	SRE0224 SRE0217 SRE0149	USE-HTM-0008	SRE0066 SRE0154
SYS-HTM-0009	SRE0137	SW-HTM-0009	SRE0040 SRE0138 SRE0152	SO-HTM-0009	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405	HTM-CBR-0009	SRE0224 SRE0217 SRE0149	USE-HTM-0009	SRE0030
SYS-HTM-0010	SRE0149, SRE0118 SRE0089, SRE0094 SRE0095	SW-HTM-0010	SRE0040, SRE0152 SRE0132	SO-HTM-0010	SRE0149	HTM-CBR-0010	SRE0224, SRE0217 SRE0149	USE-HTM-0010	SRE0149
SYS-HTM-0011	SRE0061, SRE0079 SRE0080, SRE0147 SRE0148	SW-HTM-0011	SRE0040	SO-HTM-0011	SRE0149	HTM-CBR-0011	SRE0224, SRE0061 SRE0079, SRE0080 SRE0147, SRE0148	USE-HTM-0011	SRE0079, SRE0147 SRE0080 SRE0148
SYS-HTM-0012	SRE0061, SRE0079 SRE0080, SRE0147 SRE0148	SW-HTM-0012	SRE0040	SO-HTM-0012	SRE0149, SRE0152 SRE0132	HTM-CBR-0012	N/A	USE-HTM-0012	SRE0206
SYS-HTM-0013	SRE0149, SRE0118 SRE0089, SRE0094 SRE0095	SW-HTM-0013	SRE0042, SRE0138 SRE0152	SO-HTM-0013	SRE0149, SRE0152 SRE0132	HTM-CBR-0013	SRE0224	USE-HTM-0013	SRE0079, SRE0147 SRE0080, SRE0148
SYS-HTM-0014	SRE0132 SRE0118	SW-HTM-0014	SRE0042, SRE0152 SRE0132	SO-HTM-0014	SRE0149	HTM-CBR-0014	SRE0224	USE-HTM-0014	SRE0079, SRE0147 SRE0080, SRE0148 SRE0061
SYS-HTM-0015	SRE0149	SW-HTM-0015	SRE0042	SO-HTM-0015	SRE0218	HTM-CBR-0015	SRE0224	USE-HTM-0015	SRE0054
SYS-HTM-0016	SRE0155	SW-HTM-0016	SRE0042	SO-HTM-0016	SRE0218	HTM-CBR-0016	SRE0224, SRE0132	USE-HTM-0016	SRE0027
SYS-HTM-0017	SRE0400 SRE0401	SW-HTM-0017	SRE0043, SRE0138 SRE0152	SO-HTM-0017	SRE0044	HTM-CBR-0017	SRE0140 SRE0142	USE-HTM-0017	SRE0121

SW-HTM-0018	SRE0043, SRE0152 SRE0132	SO-HTM-0018	SRE0044	HTM-CBR-0018	SRE0141	USE-HTM-0018	SRE0079, SRE0147 SRE0080, SRE0148 SRE0061
SW-HTM-0019	SRE0043	SO-HTM-0019	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109	HTM-CBR-0019	N/A	USE-HTM-0019	SRE0079 SRE0147 SRE0080 SRE0148
SW-HTM-0020	SRE0043	SO-HTM-0020	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109			USE-HTM-0020	SRE0079 SRE0147 SRE0080 SRE0148
SW-HTM-0021	SRE0046, SRE0138 SRE0152	SO-HTM-0025	SRE0218			USE-HTM-0021	SRE0073, SRE0121
SW-HTM-0022	SRE0046, SRE0152 SRE0132	SO-HTM-0026	SRE0218			USE-HTM-0022	SRE0073 SRE0121
SW-HTM-0023	SRE0046	SO-HTM-0027	SRE0218			USE-HTM-0023	N/A
SW-HTM-0024	SRE0046	SO-HTM-0028	SRE0218			USE-HTM-0024	N/A
SW-HTM-0025	SRE0073, SRE0138 SRE0152	SO-HTM-0029	SRE0028 SRE0007			USE-HTM-0025	N/A
SW-HTM-0026	SRE0073, SRE0152 SRE0132	SO-HTM-0030	SRE0218			USE-HTM-0026	N/A
SW-HTM-0027	SRE0073	SO-HTM-0031	SRE0218			USE-HTM-0027	N/A
SW-HTM-0028	SRE0073	SO-HTM-0032	N/A			USE-HTM-0028	N/A
SW-HTM-0029	SRE0041, SRE0138 SRE0152	SO-HTM-0033	SRE0218			USE-HTM-0029	N/A
SW-HTM-0030	SRE0041, SRE0152 SRE0132	SO-HTM-0034	SRE0218			USE-HTM-0030	N/A
SW-HTM-0031	SRE0041	SO-HTM-0035	N/A			USE-HTM-0031	N/A
SW-HTM-0032	SRE0041	SO-HTM-0036	SRE0218			USE-HTM-0032	N/A
SW-HTM-0033	SRE0152	SO-HTM-0037	SRE0218			USE-HTM-0033	N/A
SW-HTM-0034	SRE0152	SO-HTM-0038	N/A			USE-HTM-0034	N/A
SW-HTM-0035	SRE0152	SO-HTM-0039	SRE0218			USE-HTM-0035	N/A
SW-HTM-0036	SRE0218	SO-HTM-0040	SRE0218			USE-HTM-0036	N/A
SW-HTM-0037	SRE0218	SO-HTM-0041	N/A			USE-HTM-0037	N/A
SW-HTM-0038	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0134, SRE0079 SRE0147, SRE0080 SRE0148	SO-HTM-0045	SRE0218			USE-HTM-0038	N/A
SW-HTM-0039	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0134, SRE0079 SRE0147, SRE0080 SRE0148	SO-HTM-0046	SRE0218			USE-HTM-0039	N/A
SW-HTM-0040	SRE0045, SRE0138 SRE0152, SRE0218	SO-HTM-0047	SRE0218			USE-HTM-0040	SRE0318 SRE0339
SW-HTM-0041	SRE0045, SRE0152, SRE0132, SRE0218	SO-HTM-0048	SRE0218			USE-HTM-0041	SRE0402 SRE0403

SW-HTM-0042	SRE0045	SO-HTM-0049	SRE0218
SW-HTM-0043	SRE0045	SO-HTM-0050	SRE0218
SW-HTM-0044	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0218	SO-HTM-0051	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0218
SW-HTM-0045	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0218	SO-HTM-0052	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0218
SW-HTM-0046	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0218	SO-HTM-0053	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109
SW-HTM-0047	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405	SO-HTM-0054	SRE0039 SRE0218
SW-HTM-0048	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0152, SRE0132 SRE0138	SO-HTM-0055	SRE0039 SRE0218
SW-HTM-0049	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0152, SRE0132	SO-HTM-0056	SRE0218
SW-HTM-0050	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109	SO-HTM-0057	SRE0028 SRE0007

USE-HTM-0042	SRE0405
--------------	---------

SW-HTM-0051	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132, SRE0138	SO-HTM-0058	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0218
SW-HTM-0052	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132	SO-HTM-0059	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109
SW-HTM-0053	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405	SO-HTM-0060	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109
SW-HTM-0054	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109	SO-HTM-0061	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0218
SW-HTM-0055	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132, SRE0138	SO-HTM-0062	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0218
SW-HTM-0056	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132	SO-HTM-0063	SRE0149 SRE0218
SW-HTM-0057	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405	SO-HTM-0064	/

SW-HTM-0058	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132, SRE0138	SO-HTM-0065	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109
SW-HTM-0059	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132		
SW-HTM-0060	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109		
SW-HTM-0061	SRE0120		
SW-HTM-0062	SRE0120		
SW-HTM-0063	SRE0120		
SW-HTM-0064	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132, SRE0138		
SW-HTM-0065	SRE0039, SRE0040 SRE0041, SRE0042 SRE0043, SRE0045 SRE0046, SRE0047 SRE0048, SRE0316 SRE0326, SRE0318 SRE0339, SRE0405 SRE0109, SRE0152 SRE0132		
SW-HTM-0066	SRE0039		
SW-HTM-0067	SRE0039, SRE0218		
SW-HTM-0068	SRE0039, SRE0218		
SW-HTM-0069	SRE0039, SRE0218		
SW-HTM-0070	SRE0039, SRE0218		
SW-HTM-0071	SRE0316, SRE0138 SRE0152		
SW-HTM-0072	SRE0316, SRE0152 SRE0132		
SW-HTM-0073	SRE0316		
SW-HTM-0074	SRE0316		
SW-HTM-0075	SRE0326, SRE0138 SRE0152		
SW-HTM-0076	SRE0326, SRE0152 SRE0132		
SW-HTM-0077	SRE0326		
SW-HTM-0078	SRE0326		
DISTR-HTM-0001	SRE0145		
SW-HTM-0079	SRE0409		

SW-HTM-0080	SREQ314
-------------	---------