Diagnostic Signatures of Internal ECU Hardware Failures in 1990–2010 Petrol Engines: A Forensic OBD PID and Exhaust Analysis

During the 1990–2010 automotive manufacturing era, Engine Control Units (ECUs) transitioned to digital architectures featuring solid-state power switches, integrated analog-to-digital converters (ADCs), and non-volatile memory cells.[1] Operating in harsh under-hood environments—characterized by severe thermal cycles, high-frequency vibrations, and electrical transients—frequently induces physical degradation of these internal solid-state circuits.[1] When internal ECU components decay, they alter closed-loop control algorithms and produce driveability issues that closely mimic sensor or mechanical failures.[1]

Isolating these issues relies on identifying a distinct divergence between the data reported by the ECU over On-Board Diagnostics (OBD) and the physical exhaust gas composition measured using a 5-gas exhaust analyzer.[1] Under normal closed-loop conditions with engine coolant temperatures above $75\ ^\circ\mathrm{C}$, the ECU targets a stoichiometric air-fuel ratio, where the physical lambda (λ) is 1.000.[1] However, internal ECU component failures corrupt this feedback loop.[1]

To characterize these failures, the diagnostic framework analyzes the interaction of key parameters, including the J1979 Calculated Load Value ($LOAD_PCT$).[7] This PID represents the percentage of peak available torque being utilized and is calculated using the standard formula:

$$\text{LOAD_PCT} = \frac{\dot{m}_{\text{actual}}}{\dot{m}_{\text{max_WOT}}\,(RPM) \cdot \frac{BARO}{29.92} \cdot \sqrt{\frac{298}{AAT+273}}} \times 100\%$$

[7]

Where $\dot{m}_{\text{actual}}$ is the actual mass airflow, $\dot{m}_{\text{max_WOT}}\,(RPM)$ is the peak mass airflow at wide-open throttle (WOT) at standard temperature and pressure (STP) as a function of engine speed, $BARO$ is the barometric pressure, and AAT is the ambient air temperature in degrees Celsius.[7] When internal hardware failures occur, the variables in this equation or the sensor inputs themselves become highly distorted, creating distinct PID signatures at both low idle ($700–800\ \text{RPM}$) and stress idle ($3500–4500\ \text{RPM}$).[1]

Technical Analysis of the Five Core Hardware Failures

1. Liquid Electrolyte Capacitor Leakage and Board-Level Trace Corrosion

Radial and surface-mount liquid-electrolyte aluminum capacitors, widely utilized for electromagnetic interference filtering and voltage stabilization on internal $5\ \text{V}$ and $12\ \text{V}$ power rails, degrade over decades of thermal exposure.[1] The rubber seals degrade, leaking a corrosive and conductive electrolyte onto the printed circuit board (PCB).[1] This fluid dissolves the copper traces and through-hole vias, creating conductive high-impedance short-circuit paths and compromising rail stability.[1]

Low Idle (700–800 RPM)

At low idle, the alternator's charging output is lower, but the leaked electrolyte creates a high-impedance path that superimposes an alternating current (AC) voltage ripple onto the DC reference lines.[1] This ripple directly corrupts ratiometric sensor readings, causing the Manifold Absolute Pressure (MAP) and Mass Air Flow (MAF) signals to fluctuate rapidly.[1] Because the ECU struggles to stabilize its calculation of $\dot{m}_{\text{actual}}$, the $LOAD_PCT$ PID fluctuates erratically between 15% and 35%.[1] The primary oxygen sensor feedback loop reacts to this instability, forcing the Short-Term Fuel Trim (STFT) for both Bank 1 (B1) and Bank 2 (B2) into rhythmic, symmetric oscillations of $\pm 15\%$ as it chases the shifting sensor outputs.[1] Under a conventional zirconia O2 configuration, the upstream sensor voltage oscillates erratically between $0.15\ \text{V}$ and $0.85\ \text{V}$, while the downstream sensor mimics this oscillation, indicating that the catalyst is struggling to buffer the rapid mixture swings.[1] Physical emissions reveal slightly elevated carbon monoxide ($CO \approx 1.8\%$) and hydrocarbons ($HC \approx 450\ \text{ppm}$) due to local combustion instability, with a physical lambda oscillating around $\lambda \approx 1.025$.[1]

Stress Idle (3500–4500 RPM)

When the engine is revved to a stress idle within the $3500\text{–}4500\ \text{RPM}$ range, the alternator's rotational speed increases, driving up the charging system's output voltage and intensifying the AC ripple amplitude on the corrupted PCB.[1] This high-frequency electrical noise induces severe clock jitter within the ECU's microprocessor.[1] The serial data communication frequently corrupts, and the ECU's analog-to-digital converter (ADC) misinterprets the ratiometric reference values.[1] The ECU often defaults to an open-loop fault mode (OL_FAULT),

freezing STFT B1/B2 and LTFT B1/B2 at 0%.[1] The $LOAD_PCT$ PID drops to an artificially low value ($< 10\%$) or locks at a default fail-safe value.[1] The physical mixture drifts significantly rich because the ECU relies on base open-loop fueling maps that are heavily distorted by the corrupted sensor inputs.[1] The physical 5-gas emissions show a sharp rich shift: CO spikes to 3.5%, HC reaches $600\ \text{ppm}$, and physical lambda drops to $\lambda \approx 0.920$.[1] In a dual zirconia O2 setup, both the upstream and downstream O2 sensors peg high ($>$), confirming a highly rich exhaust gas environment that is completely unmetered by the corrupted OBD stream.[1]

2. Low-Side Fuel Injector Driver Failures

The low-side MOSFET switches or dedicated driver integrated circuits (ICs) inside the ECU are responsible for pulsing the ground circuit of each fuel injector.[1] These components are prone to thermal fatigue, resulting in micro-cracking of solder joints or physical degradation of the silicon channel.[3] This failure manifests in two distinct electrical modes: an open-circuit failure or a shorted-to-ground (stuck-active) failure.[1]

Mode A: Open-Circuited Fuel Injector Driver (Single Cylinder Dead on Bank 1)

At low idle, an open-circuited driver prevents the affected fuel injector from receiving a ground pulse, halting fuel delivery to that cylinder.[1] The non-functioning cylinder acts as an air pump, pushing pure atmospheric air (containing approximately 20.9% O_2) directly into the exhaust manifold of Bank 1.[1] Under a conventional zirconia O2 configuration, the Bank 1 upstream sensor detects this high oxygen level and pegs low ($<$), signaling an extreme lean condition, while Bank 2 upstream behaves normally.[1] Under a wideband upstream configuration, the Bank 1 wideband sensor reports an equivalent lambda of $\lambda > 1.2$.[1] The ECU responds by commanding a maximum positive fuel trim correction, pinning Bank 1 STFT (STFT B1) and Bank 1 LTFT (LTFT B1) at $+25\%$, while Bank 2 trims (STFT B2 / LTFT B2) remain near stoichiometry (0% to $+3\%$).[1] This maximum enrichment is applied globally to all cylinders on Bank 1, forcing the remaining functional cylinders on that bank to run extremely rich.[1]

The physical exhaust gas composition reflects this divergence: the 5-gas analyzer measures very high unburned oxygen ($O_2 \approx 4.5\%$) alongside high carbon monoxide ($CO \approx 1.5\%$) and elevated hydrocarbons ($HC \approx 400\ \text{ppm}$), resulting in a lean calculated lambda ($\lambda \approx 1.120$).[1] The downstream O2 sensor pegs low ($<$) because the unburned

oxygen flows through the catalytic converter.[1] The $LOAD_PCT$ PID remains relatively normal at $20–25\%$ as the MAP/MAF readings still match the low-idle throttle angle.[8] As engine speed transitions to the stress idle range of $3500–4500\ \mathrm{RPM}$, the engine's mechanical vibration worsens solder joint separation, solidifying the open circuit.[3] The physical air volume pumped by the dead cylinder increases significantly.[1] Bank 1 fuel trims remain pinned at $+25\%$.[1] The massive volume of raw unburned oxygen from the dead cylinder mixes with the extremely rich exhaust gas from the active cylinders on Bank 1 inside the catalytic converter, triggering an intense exothermic reaction.[1] This reaction converts the excess CO and HC, causing physical tailpipe CO to rise to 2.2% and HC to level off at $350\ \mathrm{ppm}$.[1] The physical lambda remains lean at $\lambda \approx 1.080$.[1] Under a wideband upstream configuration, the Bank 1 sensor reads a highly lean mixture, while the downstream zirconia O2 sensor continues to read $<$ due to the persistent oxygen bypass.[1] The $LOAD_PCT$ PID tracks normally with the high-RPM, low-load state ($\approx 12–15\%$).[10]

Mode B: Shorted-to-Ground Fuel Injector Driver MOSFET (Stuck-Active on Bank 1)

At low idle, a thermal short-circuit fuses the drain and source of the driver MOSFET, providing a continuous ground to the Bank 1 injector as soon as the key is in the ON position.[1] The injector sprays fuel constantly at full system rail pressure.[1] The affected cylinder is completely flooded with raw gasoline, preventing ignition and causing a severe rich misfire.[1] The Bank 1 upstream zirconia O2 sensor pegs high ($>$), and a wideband upstream sensor reads a highly rich equivalence ratio ($\lambda < 0.8$).[1] The ECU commands maximum negative fuel trims on the affected bank, pinning STFT B1 and LTFT B1 at -25%, while Bank 2 fuel trims remain balanced.[5] This starves the active cylinders on Bank 1 of fuel, causing them to run lean.[1] Physical tailpipe emissions show low CO_2 (8.0%), very high CO (7.5%), and extremely high raw hydrocarbons ($HC \approx 1600\ \mathrm{ppm}$) from the unburned gasoline, with a physical lambda of $\lambda \approx 0.780$.[1] Because the misfiring cylinder also pumps unburned oxygen, the tailpipe gas contains a deceptive O_2 reading of $\approx 1.8\%$.[1] The downstream zirconia O2 sensor pegs high ($>$).[14] The $LOAD_PCT$ PID is elevated to $30–35\%$ due to unstable, rough idle speed and high MAP (low vacuum).[10]

When the engine accelerates to a stress idle of $3500–4500\ \text{RPM}$, the constant fuel flow continues unabated.[1] The active cylinders on Bank 1, starved by the pinned -25% fuel trims, struggle to maintain combustion under the higher speed requirement, causing widespread multi-cylinder misfires on that bank.[1] The physical 5-gas emissions show a catastrophic rich condition: CO is measured at 6.8%, HC is at $1400\ \text{ppm}$, and the physical lambda is $\lambda \approx 0.810$.[1] The downstream zirconia O2 sensor remains locked at $> 0.8\ \text{V}$.[14] The catalytic converter is completely overwhelmed and fuel-flooded, presenting a severe risk of physical melting.[1] The $LOAD_PCT$ PID reads an artificially high value for a stationary vehicle ($\approx 25–30\%$) because the high volume of fuel vapor and misfires drastically reduces engine vacuum, raising the MAP sensor reading.[10]

3. High-Power Ignition Coil Driver Transistor Failures

During the 1990–2010 era, ECUs utilized high-power Darlington transistors or Insulated Gate Bipolar Transistors (IGBTs) to switch the ground circuit of the ignition coils.[1] These transistors switch currents up to $15\ \text{A}$ and generate significant heat.[1] High secondary-circuit resistance, often caused by worn spark plugs or deteriorated ignition wires, overstresses the transistor's collector-emitter junction.[1] This results in a thermal short-circuit, forcing a continuous 100% duty cycle ground on the ignition coil's primary winding.[1]

Low Idle (700–800 RPM)

The continuous ground current rapidly saturates the ignition coil's primary winding, generating extreme thermal energy that melts the internal insulation and causes an open-circuit failure within minutes.[1] Once the coil fails open, spark generation ceases permanently, resulting in a continuous single-cylinder ignition misfire on Bank 1.[1] The affected cylinder draws in a standard air-fuel mixture but cannot ignite it, pumping raw fuel and atmospheric oxygen directly into the exhaust manifold of Bank 1.[1] Because both unburned fuel and unburned air are expelled in stoichiometric proportions, the physical calculated lambda remains close to stoichiometry ($\lambda \approx 1.010$).[1] However, the physical 5-gas exhaust composition is highly abnormal: O_2 is measured at 5.2% and raw hydrocarbons are extremely high ($HC \approx 2200\ \text{ppm}$), while carbon monoxide is very low ($CO \approx 0.2\%$).[1]

The Bank 1 upstream O2 sensor detects the high raw oxygen content.[14] A conventional zirconia upstream sensor pegs low ($<$), while a wideband upstream sensor reads a deceptive lean mixture ($\lambda \approx 1.100$) due to its high sensitivity to free oxygen.[1] The ECU reacts by

driving STFT B1 and LTFT B1 to positive limits ($+15\%$ to $+20\%$), while Bank 2 trims remain normal.[5] This enrichment causes the functional cylinders on Bank 1 to run rich, raising the tailpipe CO to 1.2% . Under a dual zirconia O2 setup, the downstream O2 sensor drops to $<$ due to the massive oxygen throughput. The $LOAD_PCT$ PID registers normal idle values ($18–22\%$).[8]

Stress Idle (3500–4500 RPM)

At a stress idle of $3500–4500\ \mathrm{RPM}$, the high velocity of the exhaust gas carries the massive volume of raw hydrocarbons and unburned oxygen directly into the catalytic converter.[1] An intense exothermic reaction occurs on the precious metal washcoat, causing the catalyst substrate temperature to exceed $900\ ^\circ\mathrm{C}$ ($1650\ ^\circ\mathrm{F}$).[1] This extremely efficient catalytic combustion burns off a portion of the raw emissions before they reach the tailpipe, resulting in a measured tailpipe HC of $1800\ \mathrm{ppm}$ and a CO of 0.15% .[1]

The physical lambda remains balanced at $\lambda \approx 1.005$.[1] Because the catalyst consumes nearly all the available oxygen to burn the raw fuel, the downstream zirconia O2 sensor voltage may rise slightly to $0.45\ \mathrm{V}$ or exhibit rapid, erratic fluctuations as the catalyst reaches its oxygen storage capacity.[1] The Bank 1 upstream zirconia O2 sensor remains low ($<$) or oscillates erratically, while the wideband sensor continues to report a lean bias.[1] The Bank 1 fuel trims remain elevated at $+15\%$, while Bank 2 trims remain near stoichiometry.[5] The $LOAD_PCT$ PID tracks normally with the high RPM speed ($\approx 10–12\%$).[10]

4. Vaporized/Blown Internal Sensor Ground Trace (Reference Ground Open)

Internal sensor ground traces are thin, isolated copper pathways on the ECU PCB designed to provide a clean, noise-free $0\ \mathrm{V}$ reference ground for ratiometric engine sensors, including the Engine Coolant Temperature (ECT), Intake Air Temperature (IAT), Throttle Position Sensor (TPS), and MAP sensors.[1] If a high-current circuit, such as a shorted oxygen sensor heater power wire ($12\ \mathrm{V}$), accidentally contacts a sensor ground wire during service, the excessive current flows back through the delicate sensor ground trace, instantly vaporizing it.[1]

Low Idle (700–800 RPM)

When the internal ground trace vaporizes, the ground side of all connected sensors floats

upward, typically reaching a potential of $1.5\ \text{V}$ to $4.5\ \text{V}$ relative to the actual chassis ground.[1] Because the ECT and IAT sensors operate as thermistors, this high floating ground voltage is interpreted by the ECU as maximum electrical resistance, indicating an extreme cold condition (typically defaulting to $-40\ ^\circ\text{C}$ on the OBD datastream).[1] Simultaneously, the TPS signal pin floats to its maximum voltage, and the OBD datastream reports a wide-open throttle (WOT) condition (100% throttle position or $> 4.5\ \text{V}$), even though the physical throttle plate is closed.[1] This combination of a false $-40\ ^\circ\text{C}$ coolant temperature and a false 100% WOT position forces the ECU's fuel calculation algorithm into maximum cold-start and acceleration enrichment, injecting a massive volume of fuel.[1]

The engine runs extremely rough and is highly unstable.[1] The OBD fuel system status locks in Open-Loop cold-start or defaults to Open-Loop due to a system fault (OL_FAULT), freezing STFT B1/B2 and LTFT B1/B2 at 0%.[1] If the system attempts closed-loop, the fuel trims instantly peg at their maximum negative limits (-25%) in a futile attempt to lean out the mixture, but they are overridden by the cold-start enrichment maps.[5] The physical exhaust gas is opaque black.[1] The 5-gas analyzer measures extreme rich parameters: CO_2 is extremely low (6.5%), CO is exceptionally high (9.5%), and hydrocarbons are elevated ($HC \approx 1200\ \text{ppm}$), resulting in a physical lambda of $\lambda \approx 0.720$.[1] Under conventional and wideband configurations, the upstream O2 sensors peg high ($>$ or $\lambda <$), and the downstream O2 sensor locks at $>$.[1] The $LOAD_PCT$ PID spikes to a deceptive $80–90\%$ due to the high TPS and MAP readings.[10]

Stress Idle (3500–4500 RPM)

Attempting to rev the engine to a stress idle within the $3500–4500\ \text{RPM}$ range is extremely difficult; the engine bogs, backfires, and struggles to accelerate due to severe fuel flooding.[1] If a high engine speed is reached, the air volume increases, but the extreme over-fueling persists because the floating ground voltage remains constant.[1] The OBD ECT and IAT PIDs remain locked at $-40\ ^\circ\text{C}$, and the TPS remains locked at 100%.[1]

The $LOAD_PCT$ PID pegs at 100%, which is a highly anomalous reading for a stationary vehicle in neutral.[5] The physical 5-gas emissions show a persistent, heavy rich profile: CO is measured at 8.8%, HC is at $1400\ \text{ppm}$, and the physical lambda

remains at $\lambda \approx 0.740$.[1] The upstream and downstream O2 sensors remain locked at their maximum voltage limits ($>$), completely unresponsive to engine speed changes.[1]

5. Collapsed/Drifted Internal 5V Regulator Rail

The internal $5\ \text{V}$ voltage regulator steps down the vehicle's $12\ \text{V}$ battery/alternator voltage to a stable $5.0\ \text{V}$ reference rail (V_{REF}).[1] This rail is used internally by the ECU's microcontroller and analog-to-digital converters, and is routed externally to power ratiometric sensors (MAP, MAF, TPS, and pedal position sensors).[1] Thermal stress and internal silicon degradation can cause the regulator's output junction to drift downward, collapsing the reference rail to a low voltage, such as $4.1\ \text{V}$.[1]

Low Idle (700–800 RPM)

When the V_{REF} rail drops to $4.1\ \text{V}$, the maximum voltage output capability of all connected sensors is proportionally suppressed.[1] Because the ECU's microprocessor still calculates sensor values based on an expected $5.0\ \text{V}$ baseline, the low sensor signals are severely misinterpreted.[1] The MAP sensor reports an abnormally low voltage, which the ECU interprets as high manifold vacuum (extreme low load).[1] Simultaneously, the TPS voltage drops to near $0\ \text{V}$, indicating a closed throttle.[1] Based on these depressed inputs, the ECU calculates a minimal base fuel injection pulse width, starving the engine of fuel.[1]

The engine runs extremely lean, misfires, and is highly prone to stalling.[1] The primary O2 sensor detects this lean condition, with a conventional zirconia upstream sensor dropping to $<$ and a wideband upstream sensor reporting $\lambda > 1.3$.[1] The ECU responds by commanding a maximum positive fuel trim correction, pinning STFT B1/B2 and LTFT B1/B2 at $+25\%$.[1] However, because the base fueling calculation is severely limited by the corrupted MAP/MAF input, this trim correction is insufficient to restore stoichiometry.[1]

Physical tailpipe emissions show a severe lean misfire signature: CO_2 is low (8.5%), CO is nearly non-existent (0.1%), O_2 is high (6.5%), and unburned hydrocarbons are elevated ($HC \approx 850\ \text{ppm}$) due to lean misfires, resulting in a physical lambda of $\lambda \approx 1.350$.[1] The downstream zirconia O2 sensor pegs low ($<$).[14] The $LOAD_PCT$ PID displays an artificially low value of $5–8\%$.[8]

Stress Idle (3500–4500 RPM)

To maintain a high engine speed under these conditions within the $3500–4500\ \text{RPM}$ range, the physical throttle plate must be opened significantly to draw in enough air to match the minimal fuel delivery.[1] However, because the V_{REF} is collapsed, the TPS voltage remains suppressed, and the OBD TPS PID reads a maximum of only $15–20\%$.[22] The MAP PID remains low. The $LOAD_PCT$ PID remains abnormally low ($\approx 8–10\%$), failing to scale with the actual physical engine speed.[10] The fuel trims remain pinned at $+25\%$ across both banks.[1]

The ultra-lean mixture, combined with high engine speed, raises combustion chamber temperatures.[1] This causes a massive spike in nitrogen oxide emissions ($NO_x \approx 350\ \text{ppm}$), which is highly anomalous for an engine running in neutral.[1] The physical 5-gas emissions show extreme lean parameters: CO_2 drops to 7.0%, O_2 rises to 8.5%, and unburned hydrocarbons increase to $HC \approx 1100\ \text{ppm}$ from persistent lean misfires, with a physical lambda of $\lambda \approx 1.550$.[1] The upstream and downstream O2 sensors remain locked at their low voltage limits ($<$), indicating a complete breakdown of closed-loop fuel control.[1]

Comparative Diagnostic Framework

To systematically isolate these internal ECU hardware failures from common sensor or mechanical failures, the physical tailpipe emissions and OBD PID data must be compared directly. The following high-density tables outline the comparative signatures across the failures.

Table 1: Physical Tailpipe Emissions and Calculated Lambda Signatures

ECU Internal Hardware Failure	Operating State	CO2 (%)	O2 (%)	CO (%)	HC (ppm)	NOx (ppm)	Physical Lambda (λ)
1. Capacitor Leakag	Low Idle	11.5	2.5	1.8	450	40	1.025

e & Trace Corrosion [1]							
	Stress Idle ($3500–45$)	10.0	1.5	3.5	600	65	0.920
2A. Injector Driver failed Open (Bank 1) [1]	Low Idle	10.5	4.5	1.5	400	20	1.120
	Stress Idle ($3500–45$)	11.0	4.0	2.2	350	35	1.080
2B. Injector Driver Shorted (Bank 1) [1]	Low Idle	8.0	1.8	7.5	1600	5	0.780
	Stress Idle ($3500–45$)	8.5	1.2	6.8	1400	10	0.810
3. Coil Driver Transistor	Low Idle	11.0	5.2	0.2	2200	10	1.010

Shorted / Coil Melted [1]							
	Stress Idle (3500–45)	11.5	4.8	0.15	1800	25	1.005
4. Vaporized Sensor Ground Trace [1]	Low Idle	6.5	0.3	9.5	1200	10	0.720
	Stress Idle (3500–45)	7.2	0.2	8.8	1400	15	0.740
5. Collapsed 5V Regulator Rail [1]	Low Idle	8.5	6.5	0.1	850	110	1.350
	Stress Idle (3500–45)	7.0	8.5	0.05	1100	350	1.550

Table 2: Live OBD-II PID Signatures across Fuel Trim Banks and Sensor Inputs

ECU	Oper	LOA	STFT	STFT	LTFT	LTFT	MAP	TPS	ECT /

Internal Hardware Failure	ating State	D_PCT (%)	B1 (%)	B2 (%)	B1 (%)	B2 (%)	(kPa) / MAF (g/s)	(%)	IAT (◦C)
1. Capacitor Leakage [1]	Low Idle	$15–35$	±15	±15	±5	±5	Fluctuating	$15–18$	Normal ($>$)
	Stress Idle	$<$	0	0	0	0	Erratic Spikes	$25–30$	Normal ($>$)
2A. Injector Open [1]	Low Idle	$20–25$	$+25$	$0–3$	$+25$	$0–3$	Stable	$15–18$	Normal ($>$)
	Stress Idle	$12–15$	$+25$	$0–3$	$+25$	$0–3$	Scales with RPM	$25–30$	Normal ($>$)
2B. Injector Short [1]	Low Idle	$30–35$	-25	$0–3$	-25	$0–3$	Elevated	$18–22$	Normal ($>$)
	Stress Idle	$25–30$	-25	$0–3$	-25	$0–3$	Elevated	$30–35$	Normal ($>$)

3. Coil Driver Short [1]	Low Idle	18–22	+15–2	0–3	+15–2	0–3	Stable	15–18	Normal (>)
	Stress Idle	10–12	+15	0–3	+15	0–3	Scales with RPM	25–30	Normal (>)
4. Ground Trace Blown [1]	Low Idle	80–90	0	0	0	0	Pegged High	100	−40 (Locked)
	Stress Idle	100	0	0	0	0	Pegged High	100	−40 (Locked)
5. Collapsed 5V Rail [1]	Low Idle	5–8	+25	+25	+25	+25	Artificially Low	0	Normal (>)
	Stress Idle	8–10	+25	+25	+25	+25	Artificially Low	15–20	Normal (>)

Table 3: Oxygen Sensor Configuration Behavioral Chart

ECU Hardware	Configuration A: Upstream &	Configuration B: Wideband	Configuration C: Single Upstream

Failure	Downstream Conventional Zirconia	Upstream (UEGO) & Zirconia Downstream	Zirconia
1. Capacitor Leakage & Trace Corrosion [1]	Upstream and downstream exhibit highly erratic, in-phase oscillations ($0.15\ \text{V}–0.85\ \text{V}$) at low idle, shifting to a steady rich peg ($>$) at stress idle.[1]	Wideband reports a rapidly fluctuating lambda ($\lambda =$) at low idle, while downstream zirconia oscillates. At stress idle, wideband pegs rich ($\lambda <$).[1]	Single upstream zirconia exhibits high-amplitude, irregular voltage swings ($0.1\ \text{V}–0.9\ \text{V}$), with the ECU unable to establish a stable trim baseline.[1]
2A. Injector Driver failed Open [1]	Upstream B1 pegs lean ($<$); downstream pegs lean ($<$) due to high oxygen throughput.[1]	Wideband B1 reports a highly lean mixture ($\lambda >$). Downstream zirconia remains pegged lean ($<$).[1]	Upstream zirconia pegs lean ($<$), forcing the ECU to drive global STFT to $+25\%$.[1]
2B. Injector Driver Shorted (Stuck Active) [1]	Upstream B1 pegs rich ($>$); downstream pegs rich ($>$).[1]	Wideband B1 reports a highly rich mixture ($\lambda <$). Downstream zirconia remains pegged rich ($	> 0.85\text{ V}$).[1]
3. Coil Driver Transistor Shorted / Coil Melted [1]	Upstream B1 exhibits rapid, erratic lean spikes ($<$); downstream drops to $<$ due to high oxygen throughput.[1]	Wideband B1 reports a fluctuating lean-biased lambda ($\lambda \approx$). Downstream zirconia reads low ($<$).[1]	Upstream zirconia B1 oscillates erratically with a strong low-voltage (lean) bias, forcing positive fuel trims.[1]

4. Vaporized Sensor Ground Trace [1]	Upstream pegs high ($>$); downstream pegs high ($>$). Both are completely unresponsive to actual exhaust changes.[1]	Wideband reports a highly rich mixture ($\lambda <$). Downstream zirconia pegs high ($>$).[1]	Upstream zirconia pegs high ($>$), completely unresponsive. The fuel loop is locked in open-loop default.[1]
5. Collapsed 5V Regulator Rail [1]	Upstream pegs lean ($<$); downstream pegs lean ($<$).[1]	Wideband reports an ultra-lean lambda ($\lambda >$). Downstream zirconia remains pegged lean ($<$).[1]	Upstream zirconia pegs lean ($<$). The fuel loop runs at maximum positive trim in a futile correction attempt.[1]

Analytical Conclusions and Implications

Synthesizing this comparative matrix reveals critical physical relationships that distinguish true internal control module failures from external component failures.[1] First-order diagnostics often lead to incorrect replacements of sensors or actuators.[1] For example, when an internal $5\ \text{V}$ regulator rail collapses or drifts, a technician relying solely on fault codes might swap out the MAP or TPS sensors because their output voltages are permanently low.[1]

However, examining the physical tailpipe chemistry with a 5-gas analyzer reveals a massive, global lean condition with elevated O_2 and high NO_x .[1] Simultaneously, the OBD fuel trims are pinned at maximum positive enrichment ($+25\%$).[1] This combination of a severely lean tailpipe, pinned positive fuel trims, and a flat-line low voltage on all $5\ \text{V}$ ratiometric sensors indicates that the reference rail itself has collapsed, pointing directly to the ECU power supply stage.[1]

Symmetric versus asymmetric behavior across dual-bank engines is another key diagnostic factor.[1] A physical failure in an external sensor or single wiring harness connector is typically bank-specific (e.g., a Bank 1 oxygen sensor short).[14] In contrast, a vaporized reference ground trace inside the ECU affects the ground plane of all ratiometric sensors.[1]

This internal failure causes the ECT and IAT sensors to read a constant, locked temperature of $-40\ ^\circ\text{C}$ and forces the TPS to report 100% throttle.[1] This combination triggers extreme,

open-loop over-fueling across both banks.[1] Tailpipe carbon monoxide (CO) spikes to nearly 10%, and physical lambda falls to $\lambda \approx 0.720$.[1] This uniform, severe rich condition across both banks, accompanied by frozen fuel trims and locked, extreme sensor readings, confirms an internal reference ground failure.[1]

For low-side driver and coil driver failures, the physical lambda remains highly deceptive.[1] In a single-cylinder ignition misfire caused by a shorted coil driver transistor, raw fuel and unburned oxygen are pumped into the exhaust in stoichiometric proportions.[1] The 5-gas analyzer calculates a lambda of $\lambda \approx 1.010$, which appears normal.[1]

However, the raw hydrocarbon (HC) level spikes to $2200\ \text{ppm}$.[1] The upstream O2 sensor detects the high raw oxygen level and pegs low, prompting the ECU to apply positive fuel trims that enrich the active cylinders.[1] At stress idle speeds of $3500–4500\ \text{RPM}$, these high concentrations of unburned fuel and oxygen mix inside the catalytic converter, driving substrate temperatures past $900\ ^\circ\text{C}$.[1]

Similarly, an open-circuited injector driver creates a permanent single-cylinder dead spot, with the dead cylinder pumping pure air.[1] This causes a high unburned oxygen reading at the tailpipe ($O_2 \approx 4.5\%$) alongside high CO (1.5%) from the enriched active cylinders.[1]

By comparing the OBD PID datastream against physical 5-gas exhaust chemistry, diagnostic technicians can avoid unnecessary component swaps and isolate internal ECU hardware failures with precision.[1] This comprehensive approach allows for highly reliable board-level or control module repairs, preventing repeated component failures and restoring proper engine operation.[1]

Works cited

1. EcuGasSignature.md
2. P0101 Code Symptoms, Causes, Diagnosis & Repair Overview Guide - Flagship One Blog, accessed on June 6, 2026, https://www.fs1inc.com/blog/dtc-p0101-mass-volume-air-flow-sensor-circuit-range performance/
3. Why Is the ABS Warning Light On? Understanding Causes, Safety Risks, and Fixes, accessed on June 6, 2026, https://caradas.com/why-is-the-abs-warning-light-on/
4. P0107 Code Symptoms, Causes, Diagnostic Process, Cost & Safety - Flagship One Blog, accessed on June 6, 2026, https://www.fs1inc.com/blog/dtc-p0107-manifold-absolute-pressurebarometric-pressure-sensor-circuit-low/
5. Mazdaspeed Tuning Guide, accessed on June 6, 2026, https://cobbtuning.atlassian.net/wiki/display/PRS/MAZDASPEED+Tuning+Guide

6. BMW Fuel Trim Lambda and Lambda Control | PDF | Fuel Injection - Scribd, accessed on June 6, 2026, https://www.scribd.com/document/54288265/BMW-Fuel-Trim-Lambda-and-Lambda-Control
7. Re:Obd calculated load value - ScannerDanner Forum, accessed on June 6, 2026, https://scannerdanner.com/forum/post-your-repair-questions-here/7195-re-obd-calculated-load-value.html
8. OBD-II J1979 PID Listing - DashLogic, accessed on June 6, 2026, https://www.dashlogic.com/docs/technical/obdii_pids
9. MSC Mailout MSC #06-23 Guidelines for On-Board Diagnostic II (OBD II) Certification Data, accessed on June 6, 2026, http://ww2.arb.ca.gov/sites/default/files/classic/msprog/obdprog/msc0623.pdf
10. Driveability Corner | Calculated Load | MOTOR Magazine, accessed on June 6, 2026, https://www.motor.com/magazine-summary/driveability-corner-august2015/
11. February 2010 - Silicon Chip Online, accessed on June 6, 2026, https://www.siliconchip.com.au/Issue/2010/February
12. P0205 Code Symptoms, Causes, Diagnosis, Repair & Reprogramming Costs, accessed on June 6, 2026, https://www.fs1inc.com/blog/dtc-p0205-cylinder-5-injector-circuit/
13. OBD-II Code U0106: Lost Communication With Glow Plug Control Module | Go-Parts.com, accessed on June 6, 2026, https://www.go-parts.com/garage/obd-u0106
14. OBDII Codes - O2 Sensor Training Guide - Walker Products, accessed on June 6, 2026, https://www.walkerproducts.com/o2-sensor-training-guide/obdii-codes/
15. Understanding Fuel Trim in Engines | PDF - Scribd, accessed on June 6, 2026, https://www.scribd.com/document/449469450/What-is-fuel-trim
16. OBD-II Code P1262: Cylinder 2 Injector Circuit Fault | Go-Parts.com, accessed on June 6, 2026, https://www.go-parts.com/garage/obd-p1262
17. How to Read Live Data Like a Pro: Essential Parameters Every Mechanic Should Watch, accessed on June 6, 2026, https://www.cgsulitstore.com/blogs/car-diagnostic-news/how-to-read-live-data-like-a-pro-essential-parameters-every-mechanic-should-watch
18. 2011 MY OBD System Operation Summary for Gasoline Engines - CVPI Club, accessed on June 6, 2026, https://cvpi.club/library/2011%20OBD%20System%20Operation%20Summary%20v1.pdf
19. OBD-II Code P3515: Ignition Coil 'O' (Cylinder 15) Circuit Malfunction - Go-Parts, accessed on June 6, 2026, https://www.go-parts.com/garage/obd-p3515
20. Sensor ground/ chassis ground question | General Tuning Discussion - HP Academy, accessed on June 6, 2026, https://www.hpacademy.com/forum/general-tuning-discussion/show/sensor-ground-chassis-ground-question/
21. Failure Codes and Sensor Issues Guide | PDF | Throttle | Power Supply - Scribd, accessed on June 6, 2026,

https://www.scribd.com/document/955584814/FAILURE-CODE-TABLE-LINE-VX
22. P2139 — Throttle/Pedal Position Sensor/Switch D/F Voltage Correlation - Staff Communities, accessed on June 6, 2026, https://digital.staff-capital.com/en/dtc/p2139/
23. 2007 Dodge Caliber 2.0 CVT | P0123 Active - ECU Hardware Failure or Wiring? (Voltage Mismatch) : r/MechanicAdvice - Reddit, accessed on June 6, 2026, https://www.reddit.com/r/MechanicAdvice/comments/1rad8x6/2007_dodge_caliber_20_cvt_p0123_active_ecu/
24. Diagnostic Trouble Code (DTC) Charts and Descriptions, accessed on June 6, 2026, https://cim.mcgill.ca/~cprahacs/gtcs/DTC_Codes.pdf
25. Silicon Chip - Internet Archive, accessed on June 6, 2026, https://archive.org/download/silicon-chip/Silicon%20Chip/2010/silicon_chip-2010_01_text.pdf
26. OBD-II Code P0100: Mass Air Flow (MAF) Circuit Malfunction | Go-Parts.com, accessed on June 6, 2026, https://www.go-parts.com/garage/obd-p0100
27. P2126 — Throttle/Pedal Position Sensor/Switch E Circuit Range/Performance, accessed on June 6, 2026, https://digital.staff-capital.com/en/dtc/p2126/
28. Diagnostic Trouble Code (DTC) Index - Haltech Knowledge Base, accessed on June 6, 2026, https://support.haltech.com/portal/en/kb/articles/diagnostic-trouble-code-dtc-index
29. Making sense of your sensors: MAP sensor - Delphi Auto Parts, accessed on June 6, 2026, https://www.delphiautoparts.com/resource-center/article/making-sense-of-your-sensors-map-sensor