



Advanced Safety and User Experience

Error Code Document

RESIM - ERROR CODE DEFINITION

Version 2.9

April 12, 2021

Table of Contents

1 PURPOSE 3

1.1 Scope 3

1.2 References 3

1.3 Abbreviations and Acronyms 3

2 Resim exit codes 4

3 Resim console print messages 5

4 Notes 9

5 Revision Record 10

1 PURPOSE

This document gives the Error code of RESIM Application.

1.1 Scope

RESIM Error code implementation is done based on requirements.

1.2 References

The following online resources provide the foundation for this document.

Ref.	Title	Version
1		
2		
3		
4		
5		

1.3 Abbreviations and Acronyms

Acronym	Description

2 Resim exit codes

Following are the exit codes that are returned at the exit of resim application.

Sl. No	EXIT CODES	Condition for EXIT Code	Exit code number
1.	RESIM_SIL_INIT_FAILED	SIL initialization failed	-3
2.	RESIM_SIL_BINARY_FILE_LOAD_FAILED	When dll loading is failed	-2
3.	RESIM_EXIT_SUCCESS	When RESIM execution is successful	0
4.	RESIM_EXIT_FAILURE	When RESIM execution is not successful	1
5.	RESIM_INCORRECT_CMD_ARGUMENT	When the number of arguments or the arguments are not given properly	2
6.	RESIM_INVALID_CUSTOMER_IN_CONFIG_FILE	When customer name is not given correctly in the configuration file	3
7.	RESIM_CSV_FILE_READ_ERROR	Input CSV file read error.	4
8.	RESIM_LOG_LIST_READ_ERROR	Log list/json read error has encountered.	5
9.	RESIM_CONFIG_FILE_ERROR	Configuration xml file read/parsing failed.	6
10.	RESIM_JSON_FILE_ERROR	Json file parsing is failed.	7
11.	RESIM_CONTINUOUS_MODE_FILE_ERROR	Files are not in continuous mode	8
12.	RESIM_EXIT_WARNINGS	Resim exit with Warnings due to bad log/calibration data decoding failure/F360_GDSR failure/Scan Index jump/Bus spec ID missing in few logs.	9

3 Resim console print messages

The relevant console prints that are printed from resim framework are listed below with comments.

Sl. No	Console print messages	Remarks/comments
1.	[WARNING]: Received duplicate F360 internal data chunk with wrong data at scan index: NNNNNN for running count: NNN	Resim framework received duplicate of RECU F360 data chunk with wrong data at scan index NNNNNN at running count N.
2.	[WARNING]: Found F360 internal data chunk missing in the trace for running count: N	In the trace there is F360 internal data chunk is missed at running count N.
3.	[WARNING]: UDP Frame is missing	Found UDP frame missing
4.	[ERROR]: Number of file paths provided in the json file are not equal.	Json file has the number of file path counts are not equal.
5.	[ERROR]: Required Bus Spec ID not found in SRR_DEBUG trace file: <filename>!! Please provide trace file with Bus Spec ID 69632, 69633, 69634, 69635	Mandatory bus spec IDs from the mf4 file listed under key SRR_DEBUG in json are not present.
6.	[ERROR]: Required Bus Spec ID not found in BN_CALIFR Log: <filename>!! Please provide log with CAN FD data with Spec ID 526, 548 or 549 and 550.	Mandatory bus spec IDs from the mf4 file listed under key BN_CALIFR in json are not present.
7.	[ERROR]: Required Bus Spec ID not found in BN_FASETH Log: <filename>!! Please provide log with Spec ID (0xc600afd0) and (0xc610afd0).	Mandatory bus spec IDs from the mf4 file listed under key BN_FASETH in json are not present.
8.	[ERROR]: Error in Reading Log List... Exiting Resimulation...	Error in reading the input file list/json file.
9.	[WARNING]: CRC error found in the stream Z at scan index NNNN for sensor X	UDP packets of Z stream from sensor X has CRC mismatch at scan index NNNN.
10.	[WARNING]: Checksum error found in the stream Z at scan index NNNN for sensor X	Z stream from sensor X has checksum mismatch at scan index NNNN.
11.	[WARNING]: Found UDP data packets missing in the stream Z at scan index NNNN for sensor X	UDP Z stream from sensor X has missing data packets at scan index NNNN.
12.	[INFO]: Decoding Calibration data/F360 internals for Log <filename>	Resim framework is ready for decoding the calibration data and/ or F360/GDSR internals from the input UDP data recorded in the trace.
13.	[INFO]: Decoding Calibration data for the log <filename>	Resim framework is ready for decoding the calibration data for Sensors from the input UDP data recorded in the trace.
14.	[INFO]: Started F360 internal data decoding	Resim framework received RECU F360 data and started decoding F360 internals.
15.	[INFO]: Started F360 internal data decoding from next instance at scan index: NNNNNN	Resim framework received the next instance of RECU F360 data at scan index NNNNNN and restarted decoding F360 internals from this instance.

16.	[INFO]: EOF reached. F360 Internals decoding is incomplete	During the F360 decoding process, the EOF reached: not all the required number chunks of F360 are received from the trace hence F360 decoding is incomplete.
17.	[WARNING]: Calibration decoding is successful but GDSR internals failed for : SRR_RL	Calibration decoding is done successfully however the GDSR internal data decoding failed for this sensor.
18.	[WARNING]: Calibration decoding failed but GDSR internals obtained for: SRR_RL	Calibration decoding is failed however the GDSR internal data decoding is successful for this sensor.
19.	[WARNING]: Calibration and GDSR internals decoding failed for: SRR_RL	Calibration decoding and GDSR internal data decoding is successful for this sensor.
20.	[WARNING]: Calibration decoding failed for: SRR_RL	Calibration decoding is failed for this sensor.
21.	[WARNING]: Calibration decoding is successful but F360 internals failed for: RDR_ECU	Calibration decoding is successful however the F360 internal data decoding is failed for RADAR ECU.
22.	[WARNING]: Calibration decoding failed but F360 internals obtained for: RDR_ECU	Calibration decoding is failed however the F360 internal data decoding is successful for RADAR ECU.
23.	[WARNING]: Calibration and F360 internals decoding failed for: RDR_ECU	Calibration decoding and F360 internal data decoding failed for RADAR ECU.
24.	[WARNING]: UDP data is not found for the RECU in the file.	The current file is in short of RECU UDP data.
25.	[WARNING]: UDP data is not found for the sensor SRR_RL in the file.	The current file is in short of sensor SRR_RL UDP data.
26.	[WARNING]: Directory: /home/resimResult... doesn't have Read permission	The specified directory has no read permission.
27.	[WARNING]: Resim cannot proceed due to read/write permission error	Found read/write permission error for the specified folder/file path. Hence resim is stopping.
28.	[WARNING]: ECU SW stream ECU_CORE_0 has UDP packet loss in Scan Index: NNNN	RADAR ECU core 0 stream has UDP packet loss at the specified scan index.
29.	[WARNING]: ECU SW stream ECU_CORE_0 has checksum failed in Scan Index:	RADAR ECU core 0 stream has UDP packet has checksum data error at the specified scan index.
30.	[ERROR] : Unknown Program Tool Id is found in the log <FILENAME>	The md5 file has unknown program ID.
31.	[WARNING]: Unable to open file <FILENAME>. Max file path length allowed is 260 characters	The file FILENAME could not be opened due to the longer file path name. Maximum allowed path length is 260 characters.
32.	[ERROR]: Resim failed to open the md5 file	The provided MDF file open is failed.
33.	[ERROR]: Resim found no data in md5 file	The provided MDF file has either no data or is corrupted.
34.	[INFO]: F360 decoding failed for sensor RDR_ECU	F360 decoding is failed due to either packet loss/incomplete data/duplicate chunk ID with wrong data.
35.	[INFO]: F360 internal data decoding is successful.	Resim framework received all the required number of chunks for F360 data and F360 internal data decoding is successful.
36.	[INFO]: Calibration obtained for sensor X	Resim received and decoded calibration data from UDP trace from the sensor X successfully.

• APTIV •	Global SPICE-Compliant Process - Work Product Quality Criteria	RESIM_Error_Code
------------------	--	------------------

37.	[INFO]: Calibration and F360 data decoding is successful for the log <filename>	All the required calibration data and F360 data for RECU are decoded successfully from the trace.
38.	[INFO]: Calibration data decoding is successful for the log <filename>	All the required calibration data for Sensors are decoded successfully from the trace.
39.	[WARNING]: Calibration decoding failed for sensor SRR_RL	The calibration data decoding from the trace is failed for the sensor SRR_RL
40.	WARNING]: Calibration and GDSR decoding failed for sensor SRR_RL	The calibration data decoding and GDSR internal decoding failed for the sensor SRR_RL in the trace.
41.	[INFO]: Starting resimulation for the first log in the list...	Resim framework starting the resimulation operation from the first log in the given list of traces.
42.	[INFO]: Running Resim for Log <filename>	Resim framework currently running resim and processing the trace.
43.	[INFO]: Running Sequential mode Resim for Log <filename>	Resim framework currently running resim and processing the trace in sequential mode.
44.	[INFO]: Sequential mode resim is completed for the log <filename>	Resimulation in sequential is completed mode for the trace <filename>
45.	MODE:ALL Algorithms Current Scan Index- NNNN Radar- N	SIL is running in CDC mode. Current scan index processed is NNNN by the sensor N
46.	MODE: TRACKER ONLY Current Scan Index- NNNN Radar- N	SIL is running in tracker mode. Current scan index processed is NNNN by the sensor N
47.	Unsupported stream version : N for :XYZ stream	The UDP stream XYZ of version N has no support currently in this package of Resim.
48.	Unsupported stream size : NNN for : XYZ stream	The UDP stream XYZ has size mismatch.
49.	unsupported Stream Number: N is provided in the given logs for : XYZ stream	The UDP stream XYZ has no support currently in this package of Resim.
50.	[WARNING]: Resim encountered bad Log: <Filename>	The current processing file found to be a bad log.
51.	[WARNING]: BAD_LOG: RECU UDP data is missing in the file. OR [WARNING]: BAD_LOG: Sensor XX UDP data is missing in the file.	The Sensor/s and ECU UDP cycles a encountered synchronous radar cycles. This could be because one/more sensors have stopped logging the UDP data or one/more sensors UDP data are corrupted.
52.	[WARNING]: BAD_LOG: UDP stream loss for two continuous cycles : Sensor ID = N (XX), Scan Index = NNNN	Bad log encountered with UDP stream loss in two consecutive radar cycles.
53.	[WARNING]: BAD_LOG: Radar ECU is enabled but there is no ECU data in log file	Bad log, since the input log has no RECU UDP data to process.
54.	[WARNING]: BAD_LOG: Mismatch in number of cycle count in the file	Bad log encountered with mismatch in the total number of cycles count among the different sensors/RECU UDP data.

55.	[WARNING]: MISMATCH_SCAN Sensor ID = N (XX), Prev scan index = NNNN, Curr scan index = NNNN: Delta = XYZ	Bad log encountered with the scan index jump in radar cycles or reset in the sensor.
56.	[WARNING]: Rejecting the Log: <Filename>	The current log file is rejected by the resim due to unavailability of calibration or F360 data.
57.	Resim application failed to decode F360 internal data for all the traces in the list.	Resim application could not decode RECU F360 data from all the trace files given in the list. This could be due to bad F360 data logging/ missing F360 UDP packets.
58.	Resim application failed to decode calibration data for all the traces in the list.	Resim application could not decode Sensor calibration data from all the trace files given in the list. This could be due to bad calibration data logging/ missing calib UDP packets.
59.	Resim application failed to decode sensor calibration data for the traces in the list.	Resim application could not decode Sensor calibration data from some of the trace files given in the list. This could be due to bad calibration data logging/ missing calib UDP packets.
60.	Application has successfully recovered...	Resim application recovered from processing bad log and resuming now with next log.
61.	Resimulation Operation Completed...	Resim framework completed resimulation of all the files from the list successfully.
62.	Resimulation Operation Completed with warnings...	Resim framework completed resimulation of the files from the list, but encountered warnings such as UDP frame missing/continuous frame loss in two or more consecutive cycles/scan jump/mismatch in number of radar cycles.
63.	Resimulation Operation Completed with errors...	Resim operation failed due to errors such as file open failed/calibration decoding failed for all the traces in the list/stream version mismatch/stream size mismatch.
64.	[WARNING]: File doesn't have Read permission. (filename)	This file name has no read permission.

4 Notes

None.

5 Revision Record

Revision	Status	Description / Reason for Revision	Date	Author(s)
00	Draft	Initial Draft	27 December 2019	Girija B
1.0	Approved	Update on Error Code Definition	27 December 2019	Anju Satheesh
2.0	Approved	Updated resim console print messages	19 June 2020	Mrinal Das
2.1	Approved	Updated additional resim console print messages	22 June 2020	Kiran K R
2.2	Approved	Updated additional resim console print messages	28 June 2020	Kiran K R
2.3	Approved	Updated additional resim console print messages	30 June 2020	Kiran K R
2.4	Approved	Updated additional resim console print messages	10 July 2020	Kiran K R
2.5	Approved	Updated resim print messages on section 2 with serial numbers 1, 2, 3, 9, 10, 11, 31, 32, 33 and 34.	15 October 2020	Kiran K R
2.6	Approved	Updated resim print messages on section 2 with serial numbers 32 and 35. Newer print messages are added in section 2 with serial numbers 31, 33, 34 and 37.	27 October 2020	Kiran K R
2.7	Approved	Newer print messages are added in section 2 with serial numbers 16 till 30.	08 December 2020	Kiran K R
2.8	Approved	Additional console print is added in section 3 with serial number 63 and corrected the text Calib as Calibration.	04 January 2021	Kiran K R
2.9	Approved	Updated resim exit codes 8 and 9.	12 April 2021	Kiran K R