Ford Motor Company

Service Recall Bulletin

August 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: **DEMONSTRATION / DELIVERY HOLD - Safety Recall 00S18-S1:** Certain 2001 Model Year Escape Vehicles – Speed Control Cable and Servo Replacement

REASON FOR SUPPLEMENTAL INFORMATION – ADDITIONAL UNITS ADDED; BUILD DATE RANGE EXPANDED

An additional 393 units have been identified as being affected by Safety Recall 00S18 and the build date range has been expanded to include vehicles built from January 31, 2000. Note change to affected vehicles in the following section, AFFECTED VEHICLES.

AFFECTED VEHICLES

Certain 2001 model year Escape vehicles equipped with V-6 engine and speed control option, built at the Kansas City Assembly Plant from **January 31, 2000 through July 24, 2000**.

SAFETY CONCERN

Affected vehicles are equipped with a speed control cable that may have a cracked or missing speed control cable servo cap locating tab. The potential exists for the locating tab to enter the servo clutch cavity and interfere with the speed control function.

Additionally, it is possible for water to enter the servo on units that contain a cracked or missing servo cap locating tab. This water could eventually cause corrosion that could potentially interfere with speed control function.

Either condition may not allow the throttle to return to idle when the speed control is used. If either of the above conditions is present, a stuck throttle could result, which could potentially lead to a vehicle crash.

SERVICE ACTION

Dealers are to inspect and replace, if necessary, both the speed control cable and the servo to correct this condition.

Do not drive, demonstrate, deliver or perform pre-delivery inspection on any vehicles affected by this recall until this repair has been performed.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: 1-800-423-8851
Other (Dealer Only) Recall Questions: 1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

DEMONSTRATION / DELIVERY HOLD - Safety Recall 00S18-S1:
Certain 2001 Model Year Escape Vehicles – Speed Control Cable and Servo Replacement

OASIS

OASIS will be activated for this Safety recall. You must use OASIS to determine if a vehicle is eligible for this recall.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer VIN list which you will receive in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

RENTAL CARS

Rental vehicles are not authorized for Safety Recall 00S18.

DEMONSTRATION / DELIVERY HOLD - Safety Recall 00S18-S1:
Certain 2001 Model Year Escape Vehicles – Speed Control Cable and Servo Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspection	00S18A	0.2 Hours
Replace Speed Control Cable and Servo	00S18B	0.4 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through the Recall Hotline (1-800-325-5621). Parts will be shipped Priority Next Day delivery.

Part Number	Description	Quantity
YL8Z-9A825-AA	Cable, Speed Control	1
YL8Z-9C735-EA	Servo, Speed Control	1

NOTE: Removed parts must be mutilated and properly scrapped to prevent their use on another vehicle.

ORDER INFORMATION DOR/COR

DOR/COR number 50172 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621).

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

August 2000

00S18

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect that relates to motor vehicle safety exists in certain 2001 model year Escape vehicles equipped with the V-6 engine and speed control option.

We apologize for this situation and want to assure you that with your assistance we will correct this condition. Our commitment, together with Ford dealers, is to provide you with the highest level of service and support possible.

What the safety issue is…

Affected vehicles are equipped with a speed control cable that may have a cracked or missing speed control cable servo cap locating tab. The potential exists for the locating tab to enter the servo clutch cavity and interfere with the speed control function.

Additionally, it is possible for water to enter the servo on units that contain a cracked or missing servo cap locating tab. This water could eventually cause corrosion that could potentially interfere with speed control function.

Either condition may not allow the throttle to return to idle when the speed control is used. If either of the above conditions is present, a stuck throttle could result, which could potentially lead to a vehicle crash.

What Ford Motor Company and your dealer will do...

Your dealer will inspect and replace, if necessary, both the speed control cable and the servo. Owners who are affected by this recall are requested to return their vehicle to their dealer for this service.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do…

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 00S18.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8:00 am - 11:00 pm
Saturday: 9:00 am - 6:00 pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 1-202-366-0123).

Quality Care service is there for you all year round.

QualityCare at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs