ELECTRICAL—ELECTRIC VEHICLES (E.V.) RANGER/POSTAL VEHICLES—NEW VERSION 3.0 DIAGNOSTIC SOFTWARE IS AVAILABLE	Article No. 01-11-8

FORD: 1998-2001 RANGER

ISSUE

New Version 3.0 Diagnostic Software is available for the E.V. Ranger/Postal vehicles. The technician can perform this update to their previous Diagnostic version 2.0 New Generation Star Tester (NGS) card using Worldwide Diagnostic System (WDS).

ACTION

The previous NGS Diagnostic Card available to the field for the Ranger/Postal Electric Vehicle was version 2.0, as of the week of May 14 2001 a new version 3.0 is available. The Technician can update to the latest version once the dealership receives and updates their WDS with version (B13) release. This (B13) update to the WDS gives the Technician the ability to use the WDS to update the NGS card to version 3.0.

SERVICE PROCEDURE

Changes to the version 3.0 consist of the ability to monitor the Traction Inverter Module (TIM) temperature (TIMTEMP) and Transaxle (TRNTEMP) temperature separately, using the PIDS listed above. Refer to the Ranger EV 2001 Service Repair Manual for more details.

The following steps can be performed to update the Ranger/Postal Electric Vehicle (E.V.) Diagnostic NGS Card AFTER the WDS level (B13) is installed.

1. Select the systems tab in the upper left corner of the screen (icon that says WDS).
2. Select the systems utilities sub-tab at the lower left corner of the screen (icon looks like a Swiss army knife).
3. Select the menu with “NGS SOFTWARE UPDATE” near the bottom of the list, select the continue button in the lower right corner of the screen.
4. Install the old version 2.0 EV Ranger/Postal NGS Diagnostic Card in either slot on the right hand side of the WDS machine behind the black dust cover.

NOTE

WHEN THE CARD IS INSTALLED, THE WDS WILL BEEP, OR THE CURSOR WILL CHANGE TO AN HOUR GLASS THEN BACK TO THE ARROW TO INDICATE THE WDS HAS DETECTED THE NGS CARD. YOU MUST HEAR THE BEEP OR SEE THE HOUR GLASS CHANGE BEFORE PROCEEDING.

5. Select the appropriate slot being used to allow the WDS to program the card. Select: ELECTRIC VEHICLE DIAGNOSTIC VERSION 3.0, hit continue.
6. When completed the pop-up window indicate “Normal Completion”.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 203000, 401000, 503300, 504000, 507000, 509000, 510000, 597997, 601300, 602300, 603300, 607000, 607500, 607600, 698298

Copyright © 2001 Ford Motor Company